

September 30, 2026
Issue Number: 1075

Subject: Relocation of Strain Reliefs only for 3M™ 451 Series Socket Assembly

Effective immediately, 3M will be relocating manufacturing operations for Strain Reliefs only for 3M™ 451 Series Socket Assembly from China to Vietnam. This will allow us to streamline our operations to better serve our customers globally.

We do not anticipate this will cause any delays going forward.

Due to the change of COO we will have an updated sku, please see Appendix A for complete list.

Thank you for your support of 3M.

Brent Gossett
Portfolio Marketing Manager for Global Interconnect
bgossett@mmm.com

Updated skus in the list below.

Appendix A

Old Legacy SKU	Old SAP ID	Replacement Legacy Sku	Replacement SAP ID	3M part Number Description
XP700011990	7100287428	XP700011248	7100281652	3448-45126, 26P Strain Relief 451 SKT
XP700012006	7100287450	XP700011255	7100281658	3448-45140, 40P Strain Relief 451 SKT
XP700012014	7100287426	XP700011263	7100281245	3448-45150, 50P Strain Relief 451 SKT
XP700012022	7100288009	XP700011271	7100281249	3448-45114, 14P Strain Relief 451 SKT
XP700012030	7100287427	XP700011289	7100281659	3448-45116, 16P Strain Relief 451 SKT
XP700012048	7100287995	XP700011297	7100281246	3448-45120, 20P Strain Relief 451 SKT
XP700012055	7100288008	XP700011305	7100281655	3448-45130, 30P Strain Relief 451 SKT