
Product Change Notification

Date Issued :	March 12, 2026	**PCN Number :**	517949
Reason for Change :	Obsolete		
Description of Change :	This notification is to inform you about the obsolescence of parts referenced in this notice. Please review the below for details and connect with your Molex Sales Engineer for additional queries.		
Planned Implementation Date :	June 30, 2027		
Recommended replacement parts :	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts :	December 12, 2026		
Last Time Ship Date for Obsolete Parts :	March 12, 2027		

Before Picture



"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.
For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:517949
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 517949** " in the e-mail Subject line for faster response.

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com

PCN #	Customer #	Customer Name	Search Term	Molex Part #	Customer Material #
517949	103679	TTI, Inc.	TTI INC	0348300802	MLX34830-0802
517949	103679	TTI, Inc.	TTI INC	0477256040	MLX47725-6040
517949	103679	TTI, Inc.	TTI INC	0502128100	MLX50212-8100
517949	103989	TTI INCORPORATED	TTI INC	0348300802	MOL34830-0802
517949	103989	TTI INCORPORATED	TTI INC	0387600104	MOL38760-0104
517949	103989	TTI INCORPORATED	TTI INC	0477256040	MOL47725-6040
517949	CCC-10770	TTI	TTI	0348300802	
517949	CCC-10770	TTI	TTI	0387600104	
517949	CCC-10770	TTI	TTI	0477256040	
517949	CCC-10770	TTI	TTI	0502128100	
517949	CCC-10770	TTI	TTI	0508378000	

City	State	Country	Sales Engineer Name	Sales Engineer email
Maisach-Gernlinden	09	DE	Carlos ARINO	CARLOS.ARINOMORENO@MOLEX.COM
Maisach-Gernlinden	09	DE	Carlos ARINO	CARLOS.ARINOMORENO@MOLEX.COM
Maisach-Gernlinden	09	DE	Carlos ARINO	CARLOS.ARINOMORENO@MOLEX.COM
FORT WORTH	TX	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
FORT WORTH	TX	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
FORT WORTH	TX	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
Lisle	IL	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
Lisle	IL	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
Lisle	IL	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
Lisle	IL	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM
Lisle	IL	US	JOHN CRIMMINS	JOHN.CRIMMINS@MOLEX.COM

Opportunity #	Opportunity Item Lost Indicator

PCN No	Part List
517949	0003044052
517949	0050291509
517949	0190020003
517949	0348300802
517949	0348996010
517949	0387600104
517949	0477256040
517949	0502128100
517949	0508378000
517949	0528852073
517949	5024305040

Replacement parts list

Molex Part Number	Replacement part number:
508378000	503988000
3044052	39014050
50291509	39014052
190020003	190020002
348300802	348300801
387600104	389771004
477256040	477256010
502128100	502128000
528852073	528852074
348996010	348996080
5024305040	5024305030

Replacement type
CP2.5 terminal which has same 2.5pitch
Latch is different
Latch is different
Drop in replacement
Key change from B to A, Color change from Light Gray to Black
Drop in replacement
Color change from Stone Gray to Black
Drop in replacement
Packaging (Tray Vs Embossed tape Package)
Drop in replacement
Plating thickness.