

PRODUCT CHANGE NOTIFICATION

Product Category

CABLE ACCESSORIES

20260817-1

Product Group

CABLE ACCESSORIES

ISSUE DATE:

17-Aug-26

IMPACTED REGIONS:

☒ NA

☒ EMEA

☒ LATAM

☒ AP

REASON FOR CHANGE:

☐ DISCONTINUATION

☒ OTHER

DESCRIPTION OF CHANGE: (Required)

New product package design for select cable tie mounts. The new product packaging bag includes changes as follows: product description in three languages (English, Spanish and French-Canadian); product image; key product specification with icon illustrations; UL and other industry compliance standards; barcoded manufacturing information. There is no change to the actual product, only the package design printing.



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2025	9	15
Old product discontinuation date*			

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to: PCN@panduit.com

IMPACTED PART NUMBER(s)
TM3S10-C96A
TM3S8-C186
TM3S8-C76
TM2S8-C71
TM2S8-C76
TM2S8-C186
TM2S8-C79
TM2S8-C96A
TM3S10-C186
TM3S10-C76
TM3S8-C96A