Dear Valued Customer

Issue date: September 1, 2026

Yasushi Hamazawa
Director

LSI Production Headquarters
ROHM Co., Ltd.

Notification of Product Discontinuance

Doc. No.: 1026010

This letter intends as a formal notification of discontinuance of products which are currently supplied by ROHM Co., Ltd.

ROHM Co., Ltd. requires customers to provide acknowledgment of the receipt of this notification within 30 days from the date of this notice. Lack of acknowledgment of this notice within 30 days is considered as acceptance of the change.

After acknowledgement of the customer, lack of additional response within 90 day period constitutes acceptance of the change according to JEDEC Standard J-STD-046.

Your understanding and cooperation would be highly appreciated.

Issue Date:

Product category	Affected part number(s)	Suggested replacement product
LSI	Refer to the attached file	Refer to the attached file

Reason for discontinuance

Due to the significant increase in gold prices, products using gold bonding wire will be discontinued.

Product discontinuance date

Last time buy : September 30, 2027 / Last time shipment : March 31, 2029

Comments

We have prepared a replacement product with the same package and equivalent functionality. We would appreciate your consideration of transitioning to this replacement product.

Supplier contact

Please contact the local ROHM sales office or the authorized distributor.

[Regarding environmental data and other product related data for discontinued products]
Please be noted that we can only support data which is available at the time of the product discontinuance announcement.

Notes

Tracking No.	Rohm P/N	Sales Cust Code	Sales Cust	Sales Cust P/N	Recommended PN
1026010	BD450M2WEFJ-CE2	24580	I/TTI MARELLI	ROHBD450M2WEFJ-CE2	BD450S2WEFJ-CE2
1026010	BD450M2EFJ-CE2	24580	I/TTI MARELLI	ROHBD450M2EFJ-CE2	BD450S2EFJ-CE2