VISHAY
The DNA of tech.™

Product Information Notification

PIN

Product Group: OPT/Thursday October 22, 2026/PIN-OPT-1515-2026-REV-0

Change of laser marking font style of VSOP38xxx Parts

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

jim toal
2585 Junction Avenue
-
San Jose California United States 95134- 1923
Phone: +14085678358
Fax: +14082405687
jim.toal@vishay.com

Europe

boris lazic
Theresienstr.2
-
Heilbronn Germany 74072
Phone: +4971317498645
Fax: +497131673144
-

Asia

jason soon
25 Tampines Street 92
keppel building #02-00
singapore singapore Singapore 528877
Phone: +6567807879
Fax: +6567807897
jason.soon@vishay.com

Description of Change: Change of laser marking font style.

Reason for Change: The revised font style reduces the risk of marking escapees for VSOP33638 and VSOP33838 without requiring tighter visual inspection criteria, thereby minimizing the risk of false rejects and the associated impact on production efficiency.

Expected Influence on Quality/Reliability/Performance: None.

Part Numbers/Series/Families Affected: VSOP38336, VSOP38338,
Affected customers will be informed directly with a detailed part list.

Vishay Brand(S): Vishay Semiconductors

Time Schedule:
Start Shipment Date: Friday January 1, 2027

Sample Availability: No samples.

Product Identification: Via laser marking font style.

Qualification Data: No special qualification required.

Issued By: Rainer Hauschildt, rainer.hauschildt@vishay.com

© 2021 VISHAY INTERTECHNOLOGY, INC. ALL RIGHTS RESERVED.


THIS DOCUMENT IS SUBJECT TO CHANGE WITHOUT NOTICE. THE PRODUCTS DESCRIBED HEREIN AND THIS DOCUMENT ARE SUBJECT TO SPECIFIC DISCLAIMERS, SET FORTH AT www.vishay.com/doc?91000


OLD MARKING FONT (Chrset00.fnt)





NEW MARKING FONT (Chrset13.fnt)





Vishay Mat	Customer P	Location
VSOP3833[illegible]	VSOP3833[illegible]	Singapore