Change Notice

M2 Series

Changes to Production & Manufacture Location for M2 Series Pushbuttons



Type of Change:

☐ Engineering ☐ Part Number
☐ Product ☑ Appearance

I. There will be revisions to the production and manufacture location of M2 Series Pushbuttons. Previously, the lot code on the switch body had a dot mark above the first digit, but now the mark will be above the second digit. The shipping box for the switches had “CHINA FACTORY” on the side, but will be replaced with “PHILIPPINES FACTORY.” These changes will apply to all M2 Series Pushbuttons, including both standard and custom parts. Standard part numbers are on the table below.



Changes for M2 Series Pushbuttons

	Lot Number	Shipping Box
Before Changes	Dot Mark Above First Digit 69 Enlarged to Show Detail	“CHINA FACTORY” printed on side of box 
After Changes	Dot Mark Above Second Digit 69 Enlarged to Show Detail	“PHILIPPINES FACTORY” printed on side of box 

Notes
- There are no changes to the switches’ dimensions or specifications.
- The size and shape of the Shipping Box may vary depending on the part number.
- Contact information is below if more details are needed.

* EFFECTED STANDARD PART NUMBERS FOR CHANGES TO PRODUCTION (CHANGE 1)					
M2B15AA5W03	M2B15BA5A03	M2B25AA5G13	M2B15AA5W30	M2B15BA5A30	M2B25AA5G40
M2B15AA5G03	M2B25BA5W03	M2B25AA5A13	M2B15AA5G30	M2B25BA5W30	M2B25AA5A40
M2B15AA5A03	M2B25BA5G03	M2B15BA5W13	M2B15AA5A30	M2B25BA5G30	M2B15BA5W40
M2B25AA5W03	M2B25BA5A03	M2B15BA5G13	M2B25AA5W30	M2B25BA5A30	M2B15BA5G40
M2B25AA5G03	M2B15AA5W13	M2B15BA5A13	M2B25AA5G30	M2B15AA5W40	M2B15BA5A40
M2B25AA5A03	M2B15AA5G13	M2B25BA5W13	M2B25AA5A30	M2B15AA5G40	M2B25BA5W40
M2B15BA5W03	M2B15AA5A13	M2B25BA5G13	M2B15BA5W30	M2B15AA5A40	M2B25BA5G40
M2B15BA5G03	M2B25AA5W13	M2B25BA5A13	M2B15BA5G30	M2B25AA5W40	M2B25BA5A40

* Base part numbers

Effective Date

Changes for production and manufacture location for M2 Series Pushbuttons will be effective January 2027. However, the date may be subject to change depending on inventory of the products.

NKK SWITCHES
www.nkkswitches.com • 1.877.2BUYNKK (228.9655)
7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Change Notice

Changes to Production & Manufacture Location for M2 Series Pushbuttons

* EFFECTED STANDARD PART NUMBERS FOR CHANGES TO PRODUCTION (CHANGE 1 CONTINUED)					
M2B15AA5A13-HA	M2B15AA5G40-FA	M2B15AA5W30-HB	M2B15BA5G13-CG	M2B15BA5W03-BB	M2B25AA5G30-HA
M2B15AA5G03-FA	M2B15AA5G40-FC	M2B15AA5W30/UC	M2B15BA5G30-BC	M2B15BA5W03-CA	M2B25AA5G30-HB
M2B15AA5G03-FC	M2B15AA5G40-HA	M2B15AA5W40-FA	M2B15BA5G30-BF	M2B15BA5W03-CB	M2B25AA5G30-HC
M2B15AA5G03-HA	M2B15AA5G40-HC	M2B15BA5G03-BA	M2B15BA5G30-CA	M2B15BA5W13-BG	M2B25AA5G40-FA
M2B15AA5G03-HB	M2B15AA5W03-FA	M2B15BA5G03-BC	M2B15BA5G30-CC	M2B15BA5W13-CA	M2B25AA5G40-FC
M2B15AA5G03-HC	M2B15AA5W03-FC	M2B15BA5G03-BG	M2B15BA5G30-CF	M2B15BA5W13-CE	M2B25AA5W03-FA
M2B15AA5G13-FA	M2B15AA5W03-HA	M2B15BA5G03-CA	M2B15BA5G30-CG	M2B15BA5W13-CF	M2B25AA5W03-FB
M2B15AA5G13-FB	M2B15AA5W03-HC	M2B15BA5G03-CB	M2B15BA5G30-CH	M2B15BA5W13-CG	M2B25AA5W03-FC
M2B15AA5G13-FF	M2B15AA5W13-FA	M2B15BA5G03-CC	M2B15BA5G30/UC	M2B15BA5W30-BC	M2B25AA5W03-HA
M2B15AA5G13-HA	M2B15AA5W13-FB	M2B15BA5G03-CG	M2B15BA5G30/UC-BA	M2B15BA5W30-CA	M2B25AA5W13-HA
M2B15AA5G13-HB	M2B15AA5W13-FC	M2B15BA5G03-CH	M2B15BA5G30/UC-BC	M2B15BA5W30-CC	M2B25AA5W13-HC
M2B15AA5G13-HC	M2B15AA5W13-HA	M2B15BA5G13-BA	M2B15BA5G40-BA	M2B15BA5W40-CA	M2B25AA5W13/C
M2B15AA5G30-FA	M2B15AA5W13-HB	M2B15BA5G13-BB	M2B15BA5G40-BC	M2B25AA5G03-FA	M2B25AA5W30-FA
M2B15AA5G30-FB	M2B15AA5W13-HC	M2B15BA5G13-BC	M2B15BA5G40-BE	M2B25AA5G03-FB	M2B25AA5W30-FB
M2B15AA5G30-FC	M2B15AA5W30-FA	M2B15BA5G13-CA	M2B15BA5G40-BH	M2B25AA5G13/CUL	M2B25BA5W13-CA
M2B15AA5G30-HA	M2B15AA5W30-FB	M2B15BA5G13-CC	M2B15BA5G40-CA	M2B25AA5G13/CUL-HC	M2B25BA5W13-CG
M2B15AA5G30-HC	M2B15AA5W30-FC	M2B15BA5G13-CE	M2B15BA5G40-FA	M2B25AA5G30-FA	M2B15AA5G30-FA-D32
M2B15AA5G30/U	M2B15AA5W30-HA	M2B15BA5G13-CF	M2B15BA5W03-BA	M2B25AA5G30-FC	——

* Part numbers are based on NKK Switches of America's past eight years of inventory activity.

NKK SWITCHES
www.nkkswitches.com • 1.877.2BUYNKK (228.9655)
7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Change Notice

Change to UL Factory Code for M2 Series Pushbuttons

Type of Change:

- ☐ Engineering
- ☐ Part Number
- ☐ Product
- ☑ Appearance

2. M2 Series Pushbuttons with UL approval will have a change on the switch case that will include custom devices. Previously, the UL symbol appeared on the case with factory code 078. After the change, the code 080 will appear next to the UL symbol. The table below illustrates the difference, and effected standard part numbers follow.

UL Factory Code Change on Case of M2 Series Pushbuttons	
Before Change	**After Change**
® 078	® 080

Notes
- There are no changes to the switches' dimensions or specifications.
- The location of the UL code on the switch case may vary depending on the part number.
- Contact information is below if more details are needed.

* EFFECTED STANDARD PART NUMBERS FOR CHANGES TO UL FACTORY CODE (CHANGE 2)					
M2B15AA5W03/U	M2B25AA5G03/CUL	M2B15BA5A13/U	M2B15AA5W30/U	M2B25AA5G30/CUL	M2B15BA5A40/U
M2B15AA5G03/U	M2B25AA5A03/CUL	M2B25BA5W13/U	M2B15AA5G30/U	M2B25AA5A30/CUL	M2B25BA5W40/U
M2B15AA5A03/U	M2B15BA5W03/CUL	M2B25BA5G13/U	M2B15AA5A30/U	M2B15BA5W30/CUL	M2B25BA5G40/U
M2B25AA5W03/U	M2B15BA5G03/CUL	M2B25BA5A13/U	M2B25AA5W30/U	M2B15BA5G30/CUL	M2B25BA5A40/U
M2B25AA5G03/U	M2B15BA5A03/CUL	M2B15AA5W13/CUL	M2B25AA5G30/U	M2B15BA5A30/CUL	M2B15AA5W40/CUL
M2B25AA5A03/U	M2B25BA5W03/CUL	M2B15AA5G13/CUL	M2B25AA5A30/U	M2B25BA5W30/CUL	M2B15AA5G40/CUL
M2B15BA5W03/U	M2B25BA5G03/CUL	M2B15AA5A13/CUL	M2B15BA5W30/U	M2B25BA5G30/CUL	M2B15AA5A40/CUL
M2B15BA5G03/U	M2B25BA5A03/CUL	M2B25AA5W13/CUL	M2B15BA5G30/U	M2B25BA5A30/CUL	M2B25AA5W40/CUL
M2B15BA5A03/U	M2B15AA5W13/U	M2B25AA5G13/CUL	M2B15BA5A30/U	M2B15AA5W40/U	M2B25AA5G40/CUL
M2B25BA5W03/U	M2B15AA5G13/U	M2B25AA5A13/CUL	M2B25BA5W30/U	M2B15AA5G40/U	M2B25AA5A40/CUL
M2B25BA5G03/U	M2B15AA5A13/U	M2B15BA5W13/CUL	M2B25BA5G30/U	M2B15AA5A40/U	M2B15BA5W40/CUL
M2B25BA5A03/U	M2B25AA5W13/U	M2B15BA5G13/CUL	M2B25BA5A30/U	M2B25AA5W40/U	M2B15BA5G40/CUL
M2B15AA5W03/CUL	M2B25AA5G13/U	M2B15BA5A13/CUL	M2B15AA5W30/CUL	M2B25AA5G40/U	M2B15BA5A40/CUL
M2B15AA5G03/CUL	M2B25AA5A13/U	M2B25BA5W13/CUL	M2B15AA5G30/CUL	M2B25AA5A40/U	M2B25BA5W40/CUL
M2B15AA5A03/CUL	M2B15BA5W13/U	M2B25BA5G13/CUL	M2B15AA5A30/CUL	M2B15BA5W40/U	M2B25BA5G40/CUL
M2B25AA5W03/CUL	M2B15BA5G13/U	M2B25BA5A13/CUL	M2B25AA5W30/CUL	M2B15BA5G40/U	M2B25BA5A40/CUL

* Base part numbers

Effective Date

Changes for the UL factory code for M2 Series Pushbuttons will be effective January 2027. However, the date may be subject to change depending on inventory of the products.

NKK SWITCHES
www.nkkswitches.com • 1.877.2BUYNKK (228.9655)
7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435