Terminating Wires by CRIMPING

An **electrical crimp** is a type of solderless electrical connection used to terminate stranded wire.


Wire

Crimping Tool









Strip 3mm of insulation from the stranded wire.


Then, twist the end of the wire to group the strands together.



TITITITE T

Break off the terminal connector and place inner wings into appropriate slot of crimping tool.





Place wire in up to the insulation, and crimp inner wings around the wire strands.



Place outer wings into appropriate slot of crimping tool (size up if necessary) and crimp outer wings around insulation.

