



PRODUCT OBSOLESCENCE MEMO

MAGNETICS

Select Bourns® Transponders to Be Discontinued

Riverside, California – June 24, 2026 – In accordance with our ongoing product life cycle management procedure, effective immediately, Bourns will transfer select transponders to an End of Product Life (EOL) status. The obsolescence of supplier materials for these parts and the closure of our production site necessitate this action. A list of obsolete part numbers is included below.

Obsolete Part Numbers			
185029-000	186010-000	186037-000	186080-001
185041-000	186016-000	186038-000	186053-000
186006-000	186017-000	186039-001	186053-001
186007-000	186023-000	186042-000	
186008-000	186024-000	186080-000	

Regrettably, no replacement part numbers are available at this time. If there is a need in the future, we are ready to collaborate with you to develop a new design.

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC26098

185029-000
185041-000
186006-000
186007-000
186008-000
186010-000
186016-000
186017-000
186023-000
186024-000
186037-000
186038-000
186039-001
186042-000
186080-000
186080-001
186053-000
186053-001