



Product / Process Change Notification (PCN)

PCN ID#: 384

Title: Changing from Vendor Anixter, Manufacturer Atlas, Part # 1816P1015 to Vendor Anixter, Manufacturer Atlas, Part # 1816Q1015

Change: Permanent

Honeywell Contact

Name: Jennifer Hinojo

E-mail: Jennifer.hinojo@honeywell.com

Title: Sr. Quality Engineer

Product Information

Affected parts and revisions:

3070A, 3070A35, 3090A, 3090A35

Does the part number change? No

Type of Change:

Supplier – distributor

Change Description:

609420A wire (609420, 609421, 609422, 609423, 609424, 609425, 609426, 609427, 609428, 609429) changing from Vendor Anixter, Manufacturer Atlas, Part # 1816P1015 to Vendor Anixter, Manufacturer Atlas, Part # 1816Q1015

Reason for change:

1816P1015 obsolete

Justification for change: 1816P1015 obsolete Both alternate wires 1816Q1015 and 1816X1015 matched the obsolete wire 1816P1015 technical, performance, construction, material, and rating specifications very closely. They also matched indistinguishably in quality, appearance, and flexibility. There were not distinguishable differences during any aspect of the production/assembly processes. The sensor level production test data between all three matched very close and passed all acceptance criteria.

Product Identification to distinguish the change:

per DC 2865 13 Oct 2025

Samples (If required): N/A

Change Implementation Date: 10/13/2025

Honeywell is committed to providing you with a superior level of customer service. Please e-mail to contact listed above for additional information regarding this communication.