

Issue Date: April 8th, 2026

Dear Valued Customer,

This **C0627** notice is to inform you about the obsolescence of items that you have purchased from Littelfuse.

Description of the Change:

Littelfuse will obsolete and no longer support production or service of some part numbers (please refer to the attached affected and alternative PN list)

Reason for The Change:

- Declining market demand to continue support of tooling and production of some part numbers, leading to supply-chain and manufacturing challenges

Effective Date of the Change:

- Immediately

What You Need to Do:

- Remove for your system any of the parts made obsolete

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Associate Product Manager
Littelfuse Commercial Vehicle Products

Hi,

Please see attached file.

| LFPN | Alternative/Replacement PN |
|-------------|--|
| 90071-03 | 90071-02 The main difference is that the -02 uses fine silver vs. silver alloy rivets |
| 9611 | N/A |
| 9612 | N/A |
| 68369-02 | N/A |
| 90073-06 | 91811 Is only remotely similar, it is SPDT, but it is not sealed, does not have a rubber cap and has a different mounting hole. |
| 956-4107 | 956-4124 Has a bitted key rather than the Hencol key |
| 9243 | 90036-02 It only has two terminals rather than three, wiring will need to be spliced to use it. |
| 58312-G4 | L11D1DH1-AGZ00000 (Carling) |
| PL-523-AC | N/A |
| 95668-02 | N/A |
| 89690 | N/A |
| M-432 | N/A |
| 95061-50-BX | 95061-01 |
| 95061-100 | 95061-101 |

| | |
|-----------|----------|
| 95061 | 95061-01 |
| 880076 | 880075 |
| PL-523-RC | N/A |
| PL-523-BC | N/A |
| PL-523-CC | N/A |

Regards,



John Paolo A. Poblador

Sr. Customer Service Representative Team Lead- North America

Littelfuse, Inc.

NA Tel: (773) 628 0762, ext. 762

Mobile: +63 917 807 8882

Email: jpoblador@littelfuse.com