



Product Change Notification

Date Issued :	November 24, 2025	PCN Number :	517568
Reason for Change :	Obsolete		
Description of Change :	This notification is to inform you about the obsolescence of parts referenced in this notice. Please see below for more EOL details.		
Planned Implementation Date :	December 22, 2026		
Recommended replacement parts :	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts :	August 24, 2026		
Last Time Ship Date for Obsolete Parts :	November 24, 2026		

Before Picture

Overview

- As part of Molex's ongoing strategy to optimize our product structure, Molex is obsoleting this product.
- Product Impact
 - Obsolescence with Replacement
 - Please refer to above for LTB and LTS dates
- Part Number Impact
 - See attached impacted part list and possible replacement part
- Please review with your Molex Sales Engineer for final orders before LTB

"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.

For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquiries regarding this PCN by clicking on the below link

mailto:pcn_coordinator@molex.com?subject=PCN_Notification:517568

or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 517568** " in the e-mail Subject line for faster response.

Molex, LLC

2222 Wellington Court

Lisle, IL 60532

TEL (800) 786-6539

www.molex.com

PCN #	Customer #	Customer Name	Search Term	Molex Part #	Customer Material #
517568	103679	TTI, Inc.	TTI INC	2216320001	MLX221632-0001
517568	160957	TTI Electroncis Asia Pte Ltd.	TTI/HUATUN	2047355010	MOL204735-5010
517568	160957	TTI Electroncis Asia Pte Ltd.	TTI/HUATUN	2047355010	MOL204735-5010A
517568	160957	TTI Electroncis Asia Pte Ltd.	TTI/HUATUN	2047355410	MOL204735-5410
517568	160957	TTI Electroncis Asia Pte Ltd.	TTI/HUATUN	2047355410	MOL204735-5410A
517568	160957	TTI Electroncis Asia Pte Ltd.	TTI/HUATUN	2047365010	MOL204736-5010
517568	160957	TTI Electroncis Asia Pte Ltd.	TTI/HUATUN	2047365010	MOL204736-5010A
517568	165306	TTI Electroncis Asia Pte Ltd.	TTI	2068145022	
517568	165306	TTI Electroncis Asia Pte Ltd.	TTI	2068145422	MOL206814-5422

City	State	Country	Sales Engineer Name	Sales Engineer email
Maisach-Gernlinden	09	DE	Darren Fairs	DARREN.FAIRS@MOLEX.COM
Kwun Tong	KLN	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	KLN	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	KLN	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	KLN	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	KLN	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	KLN	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	NT	HK	Micle Dai	MICLE.DAI@MOLEX.COM
Kwun Tong	NT	HK	Micle Dai	MICLE.DAI@MOLEX.COM

Opportunity #	Opportunity Item Lost Indicator
---------------	---------------------------------

PCN No	Part List
517568	0367692416
517568	0367692417
517568	0533071462
517568	0732516200
517568	0936010140
517568	0936010208
517568	0936010216
517568	0936010241
517568	0936010264
517568	0936010274
517568	0936010275
517568	0936010299
517568	0936010309
517568	1201080402
517568	1201080749
517568	1201080768
517568	1201080901
517568	1201080903
517568	1201080904
517568	1300480087
517568	1300480161
517568	1300500080
517568	1300500098
517568	1300500142
517568	1300500193
517568	1300500253
517568	1300500318
517568	1300500326
517568	1300500383
517568	1300500429
517568	1300508036
517568	1300545001
517568	1300545003
517568	1300550015
517568	2047355010
517568	2047355410
517568	2047365010
517568	2057140001
517568	2068145022
517568	2068145422
517568	2072499800
517568	2139120000
517568	2216320001
517568	2247030123
517568	2247040123
517568	5024262640

517568 5024302640

Replacement parts list

Molex Part Number	Replacement part number:	Replacement type	Remarks
2139120000	2139120011/2139	Replacement with differences	
2247040123	2280370123	Drop in replacement	
2247030123	2280360123	Drop in replacement	
2216320001	2024100002	Replacement with differences	
2047355010	5050665022	Drop in replacement	
2047365010	5050705042	Drop in replacement	
1300545003	1300540035	Drop in replacement	
2072499800	2072495006	Replacement with differences	
2057140001	2057141001	Replacement with differences	
5024262640	5024262630	Replacement with differences	
5024302640	5024305030	Replacement with differences	
367692417	367693113	Drop in replacement	
367692416	367693112	Drop in replacement	
1300545001	1300540034	Drop in replacement	
2068145022	5050665022	Drop in replacement	
2068145422	5050665422	Drop in replacement	
2047355410	5050665422	Drop in replacement	
533071462	533071471	Replacement with differences	
1201080901	1201080202	Replacement with differences	
936010309	936010307	Replacement with differences	
936010299	936010297	Replacement with differences	
1201080904	1201080222	Replacement with differences	
1300480087	1200490558	Drop in replacement	
1300500193	1300500514	Replacement with differences	
1201080903	1201088655	Replacement with differences	
936010140	936010139	Replacement with differences	
936010275	936010273	Replacement with differences	
936010216	936010215	Replacement with differences	
1201080749	1201088747	Replacement with differences	
936010208	936010207	Replacement with differences	
1300500429	1300508029	Replacement with differences	
1300500318	1300508073	Replacement with differences	
1300500080	1300508028	Replacement with differences	
1300500326	1300500514	Replacement with differences	
1300550015	1300550001	Replacement with differences	
1300500098	1300505007	Replacement with differences	
1300500142	1300508076	Replacement with differences	
732516200	732512203	Drop in replacement	
936010241	936010238	Replacement with differences	
936010264	936010263	Replacement with differences	
936010274	936010273	Replacement with differences	
1201080402	1201088353	Replacement with differences	

[illegible]

[illegible]

[illegible]

[illegible]