

Part Numbers Affected

TAH20P100RJE	TAH20P7K50JE
TAH20P10K0JE	TAH20P7R50JE
TAH20P10R0JE	TAH20PR050JE
TAH20P150RJE	TAH20PR100JE
TAH20P15R0JE	TAH20PR150JE
TAH20P1K00JE	TAH20PR200JE
TAH20P1K50JE	TAH20PR220JE
TAH20P1R00JE	TAH20PR240JE
TAH20P1R50JE	TAH20PR330JE
TAH20P200RJE	TAH20PR390JE
TAH20P20R0JE	TAH20PR470JE
TAH20P220RJE	TAH20PR510JE
TAH20P22R0JE	TAH20PR750JE
TAH20P240RJE	
TAH20P24R0JE	
TAH20P2K00JE	
TAH20P2K20JE	
TAH20P2K40JE	
TAH20P2K70JE	
TAH20P2R00JE	
TAH20P2R20JE	
TAH20P2R40JE	
TAH20P330RJE	
TAH20P33R0JE	
TAH20P390RJE	
TAH20P39R0JE	
TAH20P3K30JE	
TAH20P3K90JE	
TAH20P3R30JE	
TAH20P3R90JE	
TAH20P470RJE	
TAH20P47R0JE	
TAH20P4K70JE	
TAH20P4R70JE	
TAH20P510RJE	
TAH20P51R0JE	
TAH20P5K10JE	
TAH20P5R10JE	
TAH20P5R60JE	
TAH20P750RJE	
TAH20P75R0JE	