

PRODUCT CHANGE NOTIFICATION

Product Category FIBER ASSEMBLIES 20251103-1

Product Group DC CONNECTIVITY

ISSUE DATE: 03.Nov.25

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

All FDRM% will be discontinued as the purpose of these are research modules for testing. Panduit is aligning its resources to support new market technologies and related research.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2026	2	1
Old product discontinuation date*	2025	11	3

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 CHN-CustomerService@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA		
			EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
FDRM-0100X070C	No Replacement	NO-REPLACEMENT
FDRM-0100Z100F	No Replacement	NO-REPLACEMENT
FDRM-0100W100C	No Replacement	NO-REPLACEMENT
FDRM-0100X070F	No Replacement	NO-REPLACEMENT
FDRM-0100Z050F9	No Replacement	NO-REPLACEMENT
FDRM-0010W100L9	No Replacement	NO-REPLACEMENT
FDRM-0100X030F9	No Replacement	NO-REPLACEMENT
FDRM-0100Z070F	No Replacement	NO-REPLACEMENT
FDRM-0100W150F	No Replacement	NO-REPLACEMENT
FDRM-0100X050F	No Replacement	NO-REPLACEMENT
FDRM-0100W400L	No Replacement	NO-REPLACEMENT
FDRM-0010X070	No Replacement	NO-REPLACEMENT
FDRM-0100X400L	No Replacement	NO-REPLACEMENT
FDRM-0100Z100L	No Replacement	NO-REPLACEMENT
FDRM-0100X070L	No Replacement	NO-REPLACEMENT
FDRM-910KML	No Replacement	NO-REPLACEMENT
FDRM-0010W060	No Replacement	NO-REPLACEMENT
FDRM-0010W070	No Replacement	NO-REPLACEMENT
FDRM-0010W080	No Replacement	NO-REPLACEMENT
FDRM-0010W090	No Replacement	NO-REPLACEMENT
FDRM-0010W100	No Replacement	NO-REPLACEMENT
FDRM-0010W100L	No Replacement	NO-REPLACEMENT
FDRM-0010W110	No Replacement	NO-REPLACEMENT
FDRM-0010W120	No Replacement	NO-REPLACEMENT
FDRM-0010W130	No Replacement	NO-REPLACEMENT
FDRM-0010W140	No Replacement	NO-REPLACEMENT
FDRM-0010W150F	No Replacement	NO-REPLACEMENT
FDRM-0010W150L	No Replacement	NO-REPLACEMENT
FDRM-0010W440F	No Replacement	NO-REPLACEMENT
FDRM-0010X030L	No Replacement	NO-REPLACEMENT
FDRM-0010X040	No Replacement	NO-REPLACEMENT
FDRM-0010X050	No Replacement	NO-REPLACEMENT
FDRM-0010X070-8	No Replacement	NO-REPLACEMENT
FDRM-0010X070L	No Replacement	NO-REPLACEMENT
FDRM-0010X070L9	No Replacement	NO-REPLACEMENT
FDRM-0010X080	No Replacement	NO-REPLACEMENT
FDRM-0010X090	No Replacement	NO-REPLACEMENT
FDRM-0010X100	No Replacement	NO-REPLACEMENT
FDRM-0010X200	No Replacement	NO-REPLACEMENT
FDRM-0010X200F	No Replacement	NO-REPLACEMENT
FDRM-0010X300	No Replacement	NO-REPLACEMENT
FDRM-0010X300F	No Replacement	NO-REPLACEMENT
FDRM-0010X300M	No Replacement	NO-REPLACEMENT
FDRM-0010X330M	No Replacement	NO-REPLACEMENT
FDRM-0010Z060	No Replacement	NO-REPLACEMENT
FDRM-0010Z070	No Replacement	NO-REPLACEMENT
FDRM-0010Z080	No Replacement	NO-REPLACEMENT

Replacement Type Definition

DIRECT
REPLACEMENT

Exact same part in a different part number
has any other update that does not affect the
product itself

COMPATIBLE

The replacement part is different but
allows it to be used for some applications
it is not the same part. The difference could be
in color, size, material, or performance (e.g.,
CAT5 to CAT6), etc.

COMPLEX

The replacement part(s) are too different to
assume it can easily replace the original
part, however Panduit can provide a
replacement which may be used in some
applications. Customer Experience
contacted.

NO REPLACEMENT

NO REPLACEMENT

No replacement product is

package size, or
n't change the

nt in a way that
applications, but
erence can be
ormance (like
s.

o dissimilar to
e discontinued
n offer a
ed in certain
nce should be

available.