

PRODUCT CHANGE NOTIFICATION

Product Category _____ FIBER CONNECTORS _____ **20251112-1**

Product Group _____ ENTERPRISE CONNECTIVITY _____

ISSUE DATE: _____ 12-Nov-25

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

With the increasing market shift to fusion splicing, all OptiCam kits, connectors, and accessories are now end-of-life. One final production run of OptiCam 2 tool kits will be available beginning in late December 2025. Kits, connectors, and accessories are only available while supplies last. Users should convert to the new OmniSplice fusion-spliced connectors offering, already available for order, for their field termination needs.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2025	11	3
Old product discontinuation date*	2025	11	12

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 CHN-CustomerService@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customersevice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Product Groups

- CABLE COPPER, FIBER CABLE AND CONNECTORS
- CONVERGED INFRASTRUCTURE
- COPPER & NETKEY COPPER, FIBER, CABLE
- DATA CENTER SOFTWARE
- DC CONNECTIVITY
- DUCT AND ABRASION
- ID, SAFETY AND ACCESSORIES
- IMS SMARTZONE HARDWARE
- INDUSTRIALNET COPPER
- INDUSTRIALNET FIBER
- INDUSTRIALNET OUTLETS
- IOT SOFTWARE
- IOT SOLUTIONS
- MISC
- OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT
- POWER CONNECTORS, GROUNDING AND STEEL
- PRE-CONFIGURED IA
- TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
FOCTT2-KIT3	No Replacement	NO-REPLACEMENT			10-FEB-2026
FOCTT2-PKIT3	No Replacement	NO-REPLACEMENT			10-FEB-2026
FCCVR2	No Replacement	NO-REPLACEMENT			10-FEB-2026
FLCC2	No Replacement	NO-REPLACEMENT			10-FEB-2026

FSCC2	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSTC2	No Replacement	NO-REPLACEMENT			10-FEB-2026
FOLPC-1.25SM	No Replacement	NO-REPLACEMENT			10-FEB-2026
FOLPC-1.25MM	No Replacement	NO-REPLACEMENT			10-FEB-2026
FOLPC-2.5SM	No Replacement	NO-REPLACEMENT			10-FEB-2026
FOLPC-2.5MM	No Replacement	NO-REPLACEMENT			10-FEB-2026
FOCTT2CORD	No Replacement	NO-REPLACEMENT			10-FEB-2026
OCTTR1.25SS	No Replacement	NO-REPLACEMENT			10-FEB-2026
OCTTR2.5SS	No Replacement	NO-REPLACEMENT			10-FEB-2026
FJQCVR	No Replacement	NO-REPLACEMENT			10-FEB-2026
FJQCVRB	No Replacement	NO-REPLACEMENT			10-FEB-2026
FLCSMCXAQY	Complex	FSOCLCX		No	10-FEB-2026
FLCSMCXAQY-C	Complex	FSOCLCX		No	10-FEB-2026
FLCDMCXAQY	Complex	FSOCLCX		No	10-FEB-2026
FLCSSCBUY	Complex	FSOCLC9		No	10-FEB-2026
FLCSSCBUY-C	Complex	FSOCLC9		No	10-FEB-2026
FLCSMC6BLY	No Replacement	NO-REPLACEMENT			10-FEB-2026
FLCSMC6BLY-C	No Replacement	NO-REPLACEMENT			10-FEB-2026
FLCSMC6EY	No Replacement	NO-REPLACEMENT			10-FEB-2026
FLCSMC6EY-C	No Replacement	NO-REPLACEMENT			10-FEB-2026
FLCSMC5BLY	Complex	FSOCLCX		No	10-FEB-2026
FLCDMC5BLY	Complex	FSOCLCX		No	10-FEB-2026
FLCSSCAG	Complex	FSOCLCA		No	10-FEB-2026
FSC2MCXAQ	Complex	FSOCSCX		No	10-FEB-2026
FSC2MCXAQ-C	Complex	FSOCSCX		No	10-FEB-2026
FSC2DMCXAQ	Complex	FSOCSCX		No	10-FEB-2026
FSC2SCBU	Complex	FSOCSC9		No	10-FEB-2026
FSC2SCBU-C	Complex	FSOCSC9		No	10-FEB-2026
FSC2DSCBU	Complex	FSOCSC9		No	10-FEB-2026
FSC2MC6EI	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSC2MC6EI-C	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSC2DMC6EI	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSC2MC5BL	Complex	FSOCSCX		No	10-FEB-2026
FSC2MC5BL-C	Complex	FSOCSCX		No	10-FEB-2026
FSC2DMC5BL	Complex	FSOCSCX		No	10-FEB-2026
FSC2SCAG	Complex	FSOCSCA		No	10-FEB-2026
FLCC	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSCC	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSTC	No Replacement	NO-REPLACEMENT			10-FEB-2026
OPTICAMCOMP-BAG	No Replacement	NO-REPLACEMENT			10-FEB-2026
FVFLPC-1.25SMY	No Replacement	NO-REPLACEMENT			10-FEB-2026

FVFLPC-2.5SMY	No Replacement	NO-REPLACEMENT			10-FEB-2026
FVFLPCY	No Replacement	NO-REPLACEMENT			10-FEB-2026
FMCBT2AQ-X	No Replacement	NO-REPLACEMENT			10-FEB-2026
FMCBT2BL-X	No Replacement	NO-REPLACEMENT			10-FEB-2026
FMCBT3AQ-X	No Replacement	NO-REPLACEMENT			10-FEB-2026
FMCBT2EI-X	No Replacement	NO-REPLACEMENT			10-FEB-2026
FMCBT3BL-X	No Replacement	NO-REPLACEMENT			10-FEB-2026
FMCBT3EI-X	No Replacement	NO-REPLACEMENT			10-FEB-2026
FSCBT3BU-X	No Replacement	NO-REPLACEMENT			10-FEB-2026

DIRECT REPLACEMENT

Exact same part in a different package size, or has any other update that doesn't change the product itself

COMPATIBLE

The replacement part is different in a way that allows it to be used for some applications, but it is not the same part. The difference can be in color, size, material, or performance (like CAT5 to CAT6), etc.

COMPLEX

The replacement part(s) are too dissimilar to assume it can easily replace the discontinued part, however Panduit can offer a replacement which may be used in certain applications. Customer Experience should be contacted.

NO REPLACEMENT

No replacement product is available.