

Product change notification (PCN)

Title / short description	UL approval NBC Y-coded cables
Affected article category	Cables and lines
Change category	Approval
Change number	CAF260058-00
Reason for PCN/PDN Revision	

Purpose/objective of the change
UL approval

Detailed description of the change

As part of our continuous commitment to quality and regulatory compliance, the affected products have received UL certification. To reflect this approval, the product marking will be updated accordingly. The certification and marking offer the following advantages:
Expanded acceptance in global markets through UL compliance. Simplified product integration for end users and system certifiers due to greater labeling transparency.

Identifying characteristics
Increased V/C

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-10-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☒ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PCN-CAF260058-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1057782	NBC-M12MSY/2,0-94H/M12FSY	0	1		
1146466	NBC-M12MRY/3,0-94H	1	2		
1146469	NBC-M12MRY/5,0-94H	1	2		
1149275	NBC-M12FSY/1,0-94H	1	2		
1149280	NBC-M12FSY/5,0-94H	1	2		
1149285	NBC-M12FSY/10,0-94H	1	2		
1149291	NBC-M12MRY/0,3-94H/M12MRY	1	2		
1149294	NBC-M12MRY/1,0-94H/M12MRY	1	2		
1149296	NBC-M12MRY/2,0-94H/M12MRY	1	2		
1149297	NBC-M12MRY/3,0-94H/M12MRY	1	2		
1149298	NBC-M12MRY/5,0-94H/M12MRY	1	2		
1149299	NBC-M12MRY/7,5-94H/M12MRY	1	2		
1149300	NBC-M12MRY/10,0-94H/M12MRY	1	2		
1149302	NBC-M12MRY/20,0-94H/M12MRY	1	2		
1274101	NBC-M12MSY/2,0-94H/M12MSY	0	1		
1275330	NBC-M12MSY/1,0-94H/M12MSY	0	1		
1276285	NBC-M12MSY/5,0-94H/M12MSY	0	1		
1276287	NBC-M12MSY/10,0-94H	0	1		
1276289	NBC-M12MSY/5,0-94H	0	1		
1276291	NBC-M12MSY/2,0-94H	0	1		
1276293	NBC-M12MSY/1,0-94H	0	1		
1327461	NBC-M12MSY/.../...	1	2		
1327463	NBC-M12MRY/.../...	1	2		
1327464	NBC-M12FSY/.../...	1	2		
1327465	NBC-M12FRY/.../...	1	2		
1327466	NBC-M12MSY-M12MSY/.../...	1	2		
1327467	NBC-M12MSY-M12MRY/.../...	1	2		
1327468	NBC-M12MSY-M12FSY/.../...	1	2		
1327469	NBC-M12MSY-M12FRY/.../...	1	2		
1327471	NBC-M12MRY-M12MRY/.../...	1	2		
1327473	NBC-M12MRY-M12FSY/.../...	1	2		
1327476	NBC-M12MRY-M12FRY/.../...	1	2		
1327477	NBC-M12FSY-M12FSY/.../...	1	2		
1327478	NBC-M12FSY-M12FRY/.../...	1	2		
1328195	NBC-M12MSY/10,0-94H/M12MSY	0	1		
1339210	NBC-M12FRY-M12FRY/.../...	1	2		
1340750	NBC-M12MRY/10,0-94H/M12MSY	0	1		
1340756	NBC-M12MRY/20,0-94H/M12MSY	0	1		

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
1340766	NBC-M12MRY/30,0-94H/M12MSY	0	1		
1343467	NBC-M12MSY/16,0-94H	0	1		
1428124	NBC-M12MSY/50,0-94H/M12MSY	1	2		
1435347	NBC-M12MSY/1,5-94H/M12MSY	0	1		

Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Bemerkung

1057782	;NBC-M12MSY/2	0-94H/M12FSY;HW/FW alt: 0
1146466	;NBC-M12MRY/3	0-94H;HW/FW alt: 1
1146469	;NBC-M12MRY/5	0-94H;HW/FW alt: 1
1149275	;NBC-M12FSY/1	0-94H;HW/FW alt: 1
1149280	;NBC-M12FSY/5	0-94H;HW/FW alt: 1
1149285	;NBC-M12FSY/10	0-94H;HW/FW alt: 1
1149291	;NBC-M12MRY/0	3-94H/M12MRY;HW/FW alt: 1
1149294	;NBC-M12MRY/1	0-94H/M12MRY;HW/FW alt: 1
1149296	;NBC-M12MRY/2	0-94H/M12MRY;HW/FW alt: 1
1149297	;NBC-M12MRY/3	0-94H/M12MRY;HW/FW alt: 1
1149298	;NBC-M12MRY/5	0-94H/M12MRY;HW/FW alt: 1
1149299	;NBC-M12MRY/7	5-94H/M12MRY;HW/FW alt: 1
1149300	;NBC-M12MRY/10	0-94H/M12MRY;HW/FW alt: 1
1149302	;NBC-M12MRY/20	0-94H/M12MRY;HW/FW alt: 1
1274101	;NBC-M12MSY/2	0-94H/M12MSY;HW/FW alt: 0
1275330	;NBC-M12MSY/1	0-94H/M12MSY;HW/FW alt: 0
1276285	;NBC-M12MSY/5	0-94H/M12MSY;HW/FW alt: 0
1276287	;NBC-M12MSY/10	0-94H;HW/FW alt: 0
1276289	;NBC-M12MSY/5	0-94H;HW/FW alt: 0
1276291	;NBC-M12MSY/2	0-94H;HW/FW alt: 0
1276293	;NBC-M12MSY/1	0-94H;HW/FW alt: 0
1327461	;NBC-M12MSY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327463	;NBC-M12MRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327464	;NBC-M12FSY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327465	;NBC-M12FRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327466	;NBC-M12MSY-M12MSY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327467	;NBC-M12MSY-M12MRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327468	;NBC-M12MSY-M12FSY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327469	;NBC-M12MSY-M12FRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327471	;NBC-M12MRY-M12MRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327473	;NBC-M12MRY-M12FSY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327476	;NBC-M12MRY-M12FRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327477	;NBC-M12FSY-M12FSY/.../...;HW/FW alt: 1	HW/FW neu: 2
1327478	;NBC-M12FSY-M12FRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1328195	;NBC-M12MSY/10	0-94H/M12MSY;HW/FW alt: 0
1339210	;NBC-M12FRY-M12FRY/.../...;HW/FW alt: 1	HW/FW neu: 2
1340750	;NBC-M12MRY/10	0-94H/M12MSY;HW/FW alt: 0
1340756	;NBC-M12MRY/20	0-94H/M12MSY;HW/FW alt: 0
1340766	;NBC-M12MRY/30	0-94H/M12MSY;HW/FW alt: 0
1343467	;NBC-M12MSY/16	0-94H;HW/FW alt: 0
1428124	;NBC-M12MSY/50	0-94H/M12MSY;HW/FW alt: 1
1435347	;NBC-M12MSY/1	5-94H/M12MSY;HW/FW alt: 0

HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
eCl@ss 13.0: 27060307	
HW/FW neu: 1	eCl@ss 13.0: 27060307
eCl@ss 13.0: 27060307	
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307
HW/FW neu: 2	eCl@ss 13.0: 27060307
HW/FW neu: 1	eCl@ss 13.0: 27060307

Kunde;Name 1;Name 2;Name 3;Name 4;Straße;PLZ;Stadt;Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Ihre |
49786 ;TTI
49786 ;TTI
49786 ;TTI

Materialnr.;	Menge 2024 ST;	Menge 2025 ST;	Menge 2026 ST;	AE 2026 ST
Inc.;;;Ganghoferstraße 34;82216;Maisach;1146466				;NBC-M12MRY/3
Inc.;;;Ganghoferstraße 34;82216;Maisach;1327463				;NBC-M12MRY/.../...;;;22 ST;22 ST
Inc.;;;Ganghoferstraße 34;82216;Maisach;1327471				;NBC-M12MRY-M12MRY/.../...;;;67 ST;67 ST

0-94H;PHX1146466;;;49 ST;49 ST

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;
1057782;NBC-M12MSY/2
1146466;NBC-M12MRY/3
1146469;NBC-M12MRY/5
1149275;NBC-M12FSY/1
1149280;NBC-M12FSY/5
1149285;NBC-M12FSY/10
1149291;NBC-M12MRY/0
1149294;NBC-M12MRY/1
1149296;NBC-M12MRY/2
1149297;NBC-M12MRY/3
1149298;NBC-M12MRY/5
1149299;NBC-M12MRY/7
1149300;NBC-M12MRY/10
1149302;NBC-M12MRY/20
1274101;NBC-M12MSY/2
1275330;NBC-M12MSY/1
1276285;NBC-M12MSY/5
1276287;NBC-M12MSY/10
1276289;NBC-M12MSY/5
1276291;NBC-M12MSY/2
1276293;NBC-M12MSY/1
1327461;NBC-M12MSY/.../...;1;2;;;27060307;
1327463;NBC-M12MRY/.../...;1;2;;;27060307;
1327464;NBC-M12FSY/.../...;1;2;;;27060307;
1327465;NBC-M12FRY/.../...;1;2;;;27060307;
1327466;NBC-M12MSY-M12MSY/.../...;1;2;;;27060307;
1327467;NBC-M12MSY-M12MRY/.../...;1;2;;;27060307;
1327468;NBC-M12MSY-M12FSY/.../...;1;2;;;27060307;
1327469;NBC-M12MSY-M12FRY/.../...;1;2;;;27060307;
1327471;NBC-M12MRY-M12MRY/.../...;1;2;;;27060307;
1327473;NBC-M12MRY-M12FSY/.../...;1;2;;;27060307;
1327476;NBC-M12MRY-M12FRY/.../...;1;2;;;27060307;
1327477;NBC-M12FSY-M12FSY/.../...;1;2;;;27060307;
1327478;NBC-M12FSY-M12FRY/.../...;1;2;;;27060307;
1328195;NBC-M12MSY/10
1339210;NBC-M12FRY-M12FRY/.../...;1;2;;;27060307;
1340750;NBC-M12MRY/10
1340756;NBC-M12MRY/20
1340766;NBC-M12MRY/30
1343467;NBC-M12MSY/16
1428124;NBC-M12MSY/50
1435347;NBC-M12MSY/1

0-94H/M12FSY;0;1;;;27060307;
0-94H;1;2;;;27060307;
0-94H;1;2;;;27060307;
0-94H;1;2;;;27060307;
0-94H;1;2;;;27060307;
0-94H;1;2;;;27060307;
3-94H/M12MRY;1;2;;;27060307;
0-94H/M12MRY;1;2;;;27060307;
0-94H/M12MRY;1;2;;;27060307;
0-94H/M12MRY;1;2;;;27060307;
0-94H/M12MRY;1;2;;;27060307;
5-94H/M12MRY;1;2;;;27060307;
0-94H/M12MRY;1;2;;;27060307;
0-94H/M12MRY;1;2;;;27060307;
0-94H/M12MSY;0;1;;;27060307;
0-94H/M12MSY;0;1;;;27060307;
0-94H/M12MSY;0;1;;;27060307;
0-94H;0;1;;;27060307;
0-94H;0;1;;;27060307;
0-94H;0;1;;;27060307;
0-94H;0;1;;;27060307;

0-94H/M12MSY;0;1;;;27060307;

0-94H/M12MSY;0;1;;;27060307;
0-94H/M12MSY;0;1;;;27060307;
0-94H/M12MSY;0;1;;;27060307;
0-94H;0;1;;;27060307;
0-94H/M12MSY;1;2;;;27060307;
5-94H/M12MSY;0;1;;;27060307;