

Product discontinuation notification (PDN)

Title / short description	Discontinuation of various products
Affected article category	PCB terminal blocks and PCB connectors
Change category	Discontinuation
Change number	IAA260003-
Reason for PCN/PDN Revision	

Purpose/objective of the change

Discontinuation due to portfolio optimization

Detailed description of the change

As part of our ongoing portfolio optimization, the listed articles will be discontinued from our product range. This decision was made after careful evaluation to ensure we continue providing the most innovative and effective solutions.

For further coordination regarding replacement solutions, remaining stock, and last-time deliveries (LTD), please contact our sales department. Our sales team will be pleased to support you with any questions or requirements.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2027-07-31
Effective date (EOP)	2026-07-31	End of Service (EOSR)	-
End of Sales (EOS)	2027-01-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IAA260003-_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1031401	SMKDS 3/ 8 BK H1L P35				
1034681	MKKDSNH 1,5/ 5-5,08				
1039537	SPTAF 1/ 2-3,5-EL MC YE/BU				
1045575	TDPT 2,5/ 4-SC-5,08 GY				
1045587	TDPT 2,5/ 2-SC-5,08 GY				
1050917	MKKDSG 3/ 2 BD:R1-PX				
1068426	SPT 2,5/ 4-V-5,0 BK 1RZ 5,0				
1081474	SPTAF 1/ 2-5,0-EL MC YE/BK				
1092733	SPTA-THR 1,5/ 6-3,81BDWHSC2R44				
1092739	SPTA-THR 1,5/ 9-3,81BDWHSC2R56				
1095025	SPTAF 1/ 9-3,5-IL BK				
1119432	SPTA 1/20-3,5				
1119438	SPTA 1/17-3,5				
1141358	SPTAF 1/10-3,5-IL BK				
1298532	ZFKKDSA 1,5-5,08-22				
1366248	SPTA-THR 2,5/ 9-5,0 P20 R72				
1713075	PTSA 1,5/ 6-3,5-F MIX NZ08				
1710355	PTSA 1,5/16-3,5-Z GY				
1702615	SPT 1,5/10-V-3,5 GY7035				
1702616	SPT 1,5/10-V-3,5 YE				
1705926	SPT 2,5/ 6-V-5,0 RD				
1706429	SPTA 1,5/13-3,81				
1707580	MKDS 3/ 3 KMGY (VPE 500)				
1710355	PTSA 1,5/16-3,5-Z GY				
1710957	SPTA 1/ 2-5,0 GY				
1711218	MKKDS 3/ 9 BU BDWH:61-44SO				
1711240	PTSA 0,5/14-2,5-ZB GYYEGNRD				
1713075	PTSA 1,5/ 6-3,5-F MIX NZ08				
1714236	FK-MPT 0,5/ 6-3,5-H NZTTB11006				
1716764	MK3DS 3/14-5,08				
1716917	MKDSN 1,5/10-5,08 H1L				
1751037	PTSA 1,5/ 8-3,5-F BD:1-8				
1755907	PTSA 1,5/ 6-3,5-F BD:1-6				
1762479	PTSA 1,5/ 4-3,5-F BD:1-4				
1773808	PTDA 1,5/ 4-3,5 MIX 1RZS 1RZ				
1794434	MKDS 3/18 CRWH BDMC:				
1809607	SMKDS 3/15-5,08				
1873028	MKKDS 3/ 2 BDWH:35-32SO				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1873044	MKKDS 3/ 6 BU BDWH:55-44SO				
1873057	MKDS 3/ 2 BK BDWH:3,4				
1873206	MKDS 3/ 5 BU BDWH:38-34SO				
1889893	MKKDSH 3/ 2 BD:3,4				
1904286	SMKDS 1/ 4-3,5 BD:NZ6510				
1985632	MKDS 3/ 3 BG PIN3,5NZ1636VP500				
1989162	FRONT 2,5-V/SA10/35 BDNZ P+F				
1992573	PT 1,5/ 5-5,0-H BD:1-5				

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1031401;SMKDS 3/ 8 BK H1L P35;;;;;27460101;

1034681;MKKDSNH 1

1039537;SPTAF 1/ 2-3

1045575;TDPT 2

1045587;TDPT 2

1050917;MKKDSG 3/ 2 BD:R1-PX;;;;;27460101;

1068426;SPT 2

1081474;SPTAF 1/ 2-5

1092733;SPTA-THR 1

1092739;SPTA-THR 1

1095025;SPTAF 1/ 9-3

1119432;SPTA 1/20-3

1119438;SPTA 1/17-3

1141358;SPTAF 1/10-3

1298532;ZFKKDSA 1

1366248;SPTA-THR 2

1713075;PTSA 1

1710355;PTSA 1

1702615;SPT 1

1702616;SPT 1

1705926;SPT 2

1706429;SPTA 1

1707580;MKDS 3/ 3 KMGY (VPE 500);;;;;27460101;

1710355;PTSA 1

1710957;SPTA 1/ 2-5

1711218;MKKDS 3/ 9 BU BDWH:61-44SO;;;;;27460101;

1711240;PTSA 0

1713075;PTSA 1

1714236;FK-MPT 0

1716764;MK3DS 3/14-5

1716917;MKDSN 1

1751037;PTSA 1

1755907;PTSA 1

1762479;PTSA 1

1773808;PTDA 1

1794434;MKDS 3/18 CRWH BDMC;;;;;27460101;

1809607;SMKDS 3/15-5

1873028;MKKDS 3/ 2 BDWH:35-32SO;;;;;27460101;

1873044;MKKDS 3/ 6 BU BDWH:55-44SO;;;;;27460101;

1873057;MKDS 3/ 2 BK BDWH:3

1873206;MKDS 3/ 5 BU BDWH:38-34SO;;;;;27460101;

1889893;MKKDSH 3/ 2 BD:3

1904286;SMKDS 1/ 4-3

1985632;MKDS 3/ 3 BG PIN3

1989162;FRONT 2

1992573;PT 1

05.05.2005 08;;;;;27460101;
5-EL MC YE/BU;;;;;27460101;
5/ 4-SC-5 08 GY;;;;;27460101;
5/ 2-SC-5 08 GY;;;;;27460101;

5/ 4-V-5 0 BK 1RZ 5 0;;;;;27460101;
0-EL MC YE/BK;;;;;27460101;
06.05.2003 81BDWHSC2R44;;;;;27460101;
09.05.2003 81BDWHSC2R56;;;;;27460101;
5-IL BK;;;;;27460101;
5;;;;;27460101;
5;;;;;27460101;
5-IL BK;;;;;27460101;

05.Mai 08-22;;;;;27460101;
09.05.2005 0 P20 R72;;;;;27460101;
06.05.2003 5-F MIX NZ08;;;;;27460101;
16.05.2003 5-Z GY;;;;;27460101;
5/10-V-3 5 GY7035;;;;;27460101;
5/10-V-3 5 YE;;;;;27460101;
5/ 6-V-5 0 RD;;;;;27460101;
13.05.2003 81;;;;;27460101;

16.05.2003 5-Z GY;;;;;27460101;
0 GY;;;;;27460101;

14.05.2002 5-ZB GYYEGNRD;;;;;27460101;
06.05.2003 5-F MIX NZ08;;;;;27460101;
06.05.2003 5-H NZTTB11006;;;;;27460101;
08;;;;;27460101;

10.05.2005 08 H1L;;;;;27460101;
08.05.2003 5-F BD:1-8;;;;;27460101;
06.05.2003 5-F BD:1-6;;;;;27460101;
04.05.2003 5-F BD:1-4;;;;;27460101;
04.05.2003 5 MIX 1RZS 1RZ;;;;;27460101;

08;;;;;27460101;

4;;;;;27460101;

4;;;;;27460101;
5 BD:NZ6510;;;;;27460101;
5NZ1636VP500;;;;;27460101;
5-V/SA10/35 BDNZ P+F;;;;;27460101;
05.05.2005 0-H BD:1-5;;;;;27460101;

PCN/PDN Number	Customer Number	Company Name	Street
IAA260003	401641	TTI, INC.	2441 NORTHEAST PKWY

Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)
76106	FORT WORTH	1992573

Phoenix Contact Item Designation (changed/discontinued article)

PT 1,5/ 5-5,0-H BD:1-5

Report Date Substitute Item

28.08.2026

Replacement Product Designation