

TTI INC. TEAM

Please refer below for SWS Change Notification.

- **Parts # Affected:** 6098-9782 (New 6193-0197)adding 6098-8451 (New 6193-0198)
- **Description:** GW12A05FC2BR, GW12A05FDB
- **General Description:** This design change incorporates material and tooling modifications to the matte seal used in the male and female connectors to enhance manufacturability and improve demolding efficiency. The seal color will also change from reddish brown to green. These updates are intended as process improvements and do not affect customer functionality or introduce any customer risk. The existing seals remain suitable for customer use and are not associated with any customer risk.
- **Reason for Change:** This design change incorporates material and tooling modifications to the matte seal used in the male and female connectors to enhance manufacturability and improve demolding efficiency. The seal color will also change from reddish brown to green. These updates are intended as process improvements and do not affect customer functionality or introduce any customer risk. The existing seals remain suitable for customer use and are not associated with any customer risk.
- **Date of change proposed:** June 2027

Veronica De Santiago

Jr. Quality Analyst

SUPPLIER PART NUMBER	SUPPLIER
6188-6504	Sumitomo
6188-6505	Sumitomo
6188-6506	Sumitomo
6188-6507	Sumitomo
6188-6508	Sumitomo
6189-8452	Sumitomo
6189-8451	Sumitomo
6189-8450	Sumitomo
6189-8449	Sumitomo
6189-8448	Sumitomo
6189-9615	Sumitomo
6189-9781	Sumitomo
6189-9782	Sumitomo
6188-7017	Sumitomo
6188-7417	Sumitomo
6188-7018	Sumitomo
6188-7487	Sumitomo
6193-0011	Sumitomo