

TTI INC team:

Please refer below for SWS Change Notification.

- **Parts # Affected:** 8232-4252, 8242-4132
- **Description:** HSG FB TCH M-2MRC L, HSG FBTOUCHF-2RENL
- **General Description:** Regarding the above subject, we have been informed from the supplier named "Nippon Tanshi" that

the plating process after pressing (post-plating) for certain terminals will discontinue and it is scheduled that they will transition to pre-plated material going forward. we would like to hereby inform you of the part numbers that will be affected.

Please note that no current demand at this time from TTI INC used this as information

*Veronica De Santiago*

Jr. Quality Analyst

Sumitomo Wiring Systems (U.S.A.) Inc.