

February 27, 2026

PTN

Discontinuation of transformer B78416* series

To streamline the product range, the following automotive transformers for ultrasonic sensors are being discontinued without replacement. For alternative parts, please contact your regional sales representative.

Affected products

Ordering code Discontinued series	Type
B78416A2029A003	T3340 EP 6 TRANSFORMER
B78416A2151A003	T6487 EP 6 SMD TRANSFORMER
B78416A2199A003	T7978 EP 6 SMD TRANSFORMER
B78416A2232A003	P100143 EP 6 SMD TRANSFORMER
B78416A2327A003	P100612 EP 6 SMDTRANSFORMER
B78416A2360A003	P301048 EP 6 SMD TRANSFORMER
B78416A2386A003	P301143 EP 6 SMD TRANSFORMER
B78416A2430A003	P301598 EP 6 SMD TRANSFORMER
B78416A2433A003	P100953 EP 6 SMD TRANSFORMER
B78416A2447A003	P301802-A1 EP 6 SMD TRANSFORMER
B78416A9874A003	P303954 EP 6 SMD TRANSFORMER
B78416B2000A003	T2906 EP 6 TRANSFORMER
B78416X0001	SAMPLE KIT EP 6 SMD TRANSFORMER

Deadline for last orders: September 1, 2026

Last shipments by: March 27, 2027

Contact René Steinbrecher, MAG TF T PM 2, Munich

Customers are asked to address inquiries directly to their sales contacts.

TDK Electronics AG

Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany
 Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250
 Chairman of the Supervisory Board: Joachim Zichlarz
 Management Board: Dr. Werner Lohwasser, Chairman · Juergen Holzinger
www.tdk-electronics.tdk.com

MAG

Transformers
 Internal / External

260227MAG1e

February 27 2026

EOL - Discontinuation of transformer B78416* series

Affected Parts

B78416A2447A3
B78416A2232A3
B78416A2386A3
B78416A2360A3
B78416A2430A3
B78416A2433A3
B78416X1
B78416A2327A3
B78416A2199A3