

August 21, 2026

PTN

Discontinuation of HVC25 series

To streamline the product range, the following TDK High-Voltage Contactors (HVC) of the HVC25 series will be discontinued. Appropriate replacement types are listed in the table below. Please note that some alternatives are not direct drop-in replacements and may require additional evaluation. For any questions or support, please contact your regional sales representative.

Affected products

Type	Ordering code	Replacement Type	Replacement Ordering Code
HVC200A-12S	B88269X1820C011	HVC43-200A-12MC	B88269X7300C011
		HVC27-300A-12HO	B88269X3920C011
		HVC27-300A-12MOC1	B88269X8560C011
HVC200A-12X1C1	B88269X2020C011	HVC27-300A-12C1	B88269X3280C011
		HVC43-200A-12	B88269X3220C011
HVC300A-12SE	B88269X2050C011	HVC27-300A-12HOE2	B88269X6910C011
HVC300A-12S	B88269X2060C011	HVC27-300A-12HO	B88269X3920C011
		HVC27-300A-12MOC1	B88269X8560C011
HVC500B-12S	B88269X2070C011	HVC27-500B-12HOF	B88269X6340C011
		HVC27-500A-12MOC1	B88269X8600C011
HVC100A-24	B88269X2080C011	HVC43-150A-24	B88269X3330C011
HVC100A-24S	B88269X2090C011	HVC43-150A-24MC	B88269X7320C011
		HVC27-300A-24HO	B88269X3860C011
		HVC27-300A-24MOC1	B88269X8570C011
HVC200A-24	B88269X2110C011	HVC43-200A-24	B88269X3340C011
		HVC27-300A-24	B88269X3890C011
HVC200A-12S	B88269X2120C011	HVC43-200A-12MC	B88269X7300C011
		HVC27-300A-12MOC1	B88269X8560C011
HVC300A-12	B88269X2150C011	HVC27-300A-12	B88269X3870C011
HVC300A-24	B88269X2160C011	HVC27-300A-24	B88269X3890C011
HVC300A-24SE	B88269X2190C011	HVC27-300A-24HOE2	B88269X3780C011
HVC500B-24	B88269X2210C011	HVC27-500B-24F	B88269X6310C011
HVC500B-12	B88269X2220C011	HVC27-500B-12F	B88269X6290C011
HVC200A-12E	B88269X2230C011	HVC27-300A-12E2	B88269X6930C011
HVC200A-24E	B88269X2240C011	HVC27-300A-24E2	B88269X7180C011
HVC200A-12SE	B88269X2250C011	HVC27-300A-12HOE2	B88269X6910C011
HVC200A-24SE	B88269X2260C011	HVC27-300A-24HOE2	B88269X3780C011
HVC300A-12E	B88269X2270C011	HVC27-300A-12E2	B88269X6930C011
HVC300A-24E	B88269X2280C011	HVC27-300A-24E2	B88269X7180C011

TDK Electronics AG

Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany
 Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250
 Chairman of the Supervisory Board: Joachim Zichlarz
 Management Board: Dr. Werner Lohwasser, Chairman · Konrad Beck
www.tdk-electronics.tdk.com

PPD

HVC

Internal / External

260821PPD1e

August 21, 2026

Type	Ordering code	Replacement Type	Replacement Ordering Code
HVC500B-12E	B88269X2290C011	HVC27-500B-12E2F	B88269X6970C011
HVC500B-24E	B88269X2300C011	HVC27-500B-24E2F	B88269X7020C011
HVC500B-12SE	B88269X2310C011	HVC27-500B-12HOE2F	B88269X7400C011
HVC500B-24SE	B88269X2320C011	HVC27-500B-24HOE2F	B88269X6860C011
HVC200A-12	B88269X2340C011	HVC27-300A-12	B88269X3870C011
		HVC43-200A-12	B88269X3220C011
HVC500B-24S	B88269X2350C011	HVC27-500B-24HOF	B88269X3580C011
		HVC27-500A-24MOC1	B88269X8610C011
HVC300B-24S	B88269X2380C011	HVC27-300B-24HOF	ordering code on request
		HVC27-300A-24MOC1	B88269X8570C011
HVC200A-24S	B88269X2390C011	HVC43-200A-24MC	B88269X7330C011
		HVC27-300A-24HO	B88269X3860C011
		HVC27-300A-24MOC1	B88269X8570C011
HVC300A-24S	B88269X2430C011	HVC27-300A-24HO	B88269X3860C011
		HVC27-300A-24MOC1	B88269X8570C011
HVC500B-24SK	B88269X2440C011	please contact TDK	-
HVC500B-24	B88269X2500C011	HVC27-500B-24F	B88269X6310C011
HVC500C-24	B88269X2520C011	please contact TDK	-
HVC500C-12S	B88269X2580C011	please contact TDK	-
HVC350B-24SK	B88269X2600C011	please contact TDK	-
HVC200B-12S	B88269X2640C011	HVC27-300B-12HOF	ordering code on request
		HVC27-300A-12MOC1	B88269X8560C011
HVC300B-12S	B88269X2650C011	HVC27-300B-12HOF	ordering code on request
		HVC27-300A-12MOC1	B88269X8560C011
HVC300A-12S	B88269X2730C011	HVC27-300A-12HO	B88269X3920C011
		HVC27-300A-24MOC1	B88269X8570C011
HVC150A-24SE	B88269X2860C011	please contact TDK	-
HVC150B-24SEF	B88269X3160C011	please contact TDK	-
HVC200A-24SE2	B88269X4010C011	HVC27-300A-24HOE2	B88269X3780C011
HVC300B-12SKF	B88269X4020C011	please contact TDK	-
HVC500B-12SKF	B88269X4030C011	please contact TDK	-
HVC400B-12E2F	B88269X4090C011	HVC27-400B-12E2F	B88269X6960C011
HVC250B-24E2UX3F	B88269X4100C011	please contact TDK	-
HVC500B-12SE2F	B88269X4110C011	HVC27-500B-12HOE2F	B88269X7400C011
HVC300A-12SE	B88269X4130C011	HVC27-300A-12HOE2	B88269X6910C011
HVC135A-24	B88269X4220C011	HVC27-300A-24	B88269X3890C011
		HVC43-150A-24	B88269X3330C011
HVC150A-24S	B88269X4270C011	HVC27-300A-24MOC1	B88269X8570C011

August 21, 2026

Type	Ordering code	Replacement Type	Replacement Ordering Code
		HVC43-150A-24MC	B88269X7320C011
HVC500A-24SE2	B88269X4310C011	HVC27-500A-24HOE2	B88269X3960C011
HVC500B-12SE2F	B88269X4360C011	HVC27-500B-12HOE2F	B88269X7400C011
HVC500B-12SE2F	B88269X4360C011A02	HVC27-500B-12HOE2F	B88269X7400C011
HVC200B-24SEF	B88269X4410C011	HVC27-300B-24HOE2F	ordering code on request
HVC200A-48	B88269X4430C011	please contact TDK	-
HVC200B-12SE2F	B88269X4440C011	HVC27-300B-12HOE2F	ordering code on request
HVC200B-24SE2F	B88269X4470C011	HVC27-300B-24HOE2F	ordering code on request
HVC150A-24	B88269X4500C011	HVC27-300A-24	B88269X3890C011
		HVC43-150A-24	B88269X3330C011
HVC300A-12E2	B88269X4540C011	HVC27-300A-12E2	B88269X6930C011
HVC300A-12EC1	B88269X4550C011	HVC27-300A-12E2C1	B88269X7040C011
HVC300B-24SEF	B88269X4560C011	HVC27-300B-24HOE2F	ordering code on request
HVC300A-12SE2	B88269X4580C011	HVC27-300A-12HOE2	B88269X6910C 11
HVC300A-24E2	B88269X4620C011	HVC27-300A-24E2	B88269X7180C 11
HVC300A-24HC	B88269X4640C011	HVC27-300A-24HC	B88269X3950C 11
HVC300A-48	B88269X4670C011	please contact TDK	-
HVC300A-48E2	B88269X4680C011	please contact TDK	-
HVC300B-12SE2F	B88269X4720C011	HVC27-300B-12HOE2F	ordering code on request
HVC300B-24SE2F	B88269X4760C011	HVC27-300B-24HOE2F	ordering code on request
HVC350A-12	B88269X4780C011	HVC27-400A-12	B88269X6200C011
HVC400B-12F	B88269X4810C011	HVC27-400B-12F	B88269X6210C011
HVC500B-12F	B88269X4900C011	HVC27-500B-12F	B88269X6290C011
HVC500B-12EF	B88269X4910C011	HVC27-500B-12E2F	B88269X6970C011
HVC500B-12SEF	B88269X4940C011	HVC27-500B-12HOE2F	B88269X7400C011
HVC500B-12SF	B88269X4960C011	HVC27-500B-12HOF	B88269X6340C011
		HVC27-500A-12MOC1	B88269X8600C011
HVC500B-24EF	B88269X4970C011	HVC27-500B-24E2F	B88269X7020C011
HVC500B-24F	B88269X4990C011	HVC27-500B-24F	B88269X6310C011
HVC500B-24HCF	B88269X5000C011	HVC27-500B-24HCF	B88269X6570C011
HVC500B-24HOF	B88269X5010C011	HVC27-500B-24HOF	B88269X3580C011
HVC500B-24SEF	B88269X5040C011	HVC27-500B-24HOE2F	B88269X6860C011
HVC500B-24SE2F	B88269X5050C011	HVC27-500B-24HOE2F	B88269X6860C011
HVC500B-24SE2F	B88269X5050C011A02	HVC27-500B-24HOE2F	B88269X6860C011
HVC500B-24SKX3F	B88269X5100C011	please contact TDK	-
HVC500B-24SKX3F	B88269X5100C011X09	please contact TDK	-
HVC500C-12SE	B88269X5130C011	please contact TDK	-
HVC500C-24P5	B88269X5140C011	please contact TDK	-

August 21, 2026

Type	Ordering code	Replacement Type	Replacement Ordering Code
HVC500C-24P5	B88269X5140C011S01	please contact TDK	-
HVC400B-12SE2F	B88269X5170C011	HVC27-400B-12HOE2F	B88269X6190C011
HVC300B-12SEF	B88269X5210C011	HVC27-300B-12HOE2F	TBD, ordering code on request
HVC200B-12SE2F	B88269X5300C011	HVC27-300B-12HOE2F	ordering code on request
HVC300B-12SEF	B88269X5310C011	HVC27-300B-12HOE2F	ordering code on request
HVC300B-12SE2F	B88269X5320C011	HVC27-300B-12HOE2F	ordering code on request
HVC500B-12SEKF	B88269X5350C011	HVC27-500B-12HOE2F	B88269X7400C011
HVC500B-24SEF	B88269X5420C011	HVC27-500B-24HOE2F	B88269X6860C011
HVC400A-24E	B88269X5440C011	HVC27-400A-24E2	B88269X7190C011
HVC150A-24HCE2K	B88269X5470C011	please contact TDK	-
HVC300A-24S	B88269X5490C011	HVC27-300A-24HO	B88269X3860C011
		HVC27-300A-24MOC1	B88269X8570C011
HVC500C-24S	B88269X5500C011	please contact TDK	-
HVC500B-24SE2KF	B88269X5540C011	please contact TDK	-
HVC500B-12E2F	B88269X5550C011	HVC27-500B-12E2F	B88269X6970C011
HVC500B-24HOE2F	B88269X5570C011	HVC27-500B-24HOE2F	B88269X6860C011
HVC500B-12SE2KF	B88269X5590C011	please contact TDK	-
HVC500C-24S	B88269X5620C011	please contact TDK	-
HVC200A-12SE2	B88269X5640C011	HVC27-300A-12HOE2	B88269X6910C011
HVC135A-12SE	B88269X5680C011	HVC27-300A-12HOE2	B88269X6910C011
HVC300A-48SE2	B88269X5710C011	please contact TDK	-
HVC200A-24S	B88269X5770C011	HVC27-300A-24MOC1	B88269X8570C011
		HVC43-200A-24MC	B88269X7330C011
HVC500B-24SF	B88269X5780C011	HVC27-500B-24HOF	B88269X3580C011
		HVC27-500A-24MOC1	B88269X8610C011
HVC500B-24HOEKF	B88269X5810C011	HVC27-500B-24HOE2F	B88269X6860C011
HVC500B-24E2F	B88269X5850C011	HVC27-500B-24E2F	B88269X7020C011
HVC300B-12SE2P6F	B88269X5860C011	please contact TDK	-
HVC400B-12SE2P6F	B88269X5870C011	please contact TDK	-
HVC200B-12E2F	B88269X5890C011	HVC27-300B-12HOE2F	ordering code on request
HVC500B-12SE2P6F	B88269X5900C011	please contact TDK	-
HVC500B-12HOE2KF	B88269X5970C011	please contact TDK	-
HVC500B-24HOE2KF	B88269X6030C011	please contact TDK	-
HVC500C-24S	B88269X6060C011	please contact TDK	-
HVC500B-24SF	B88269X6080C011	HVC27-500B-12HOF	B88269X6340C011
		HVC27-500A-12MOC1	B88269X8600C011
HVC500C-24S	B88269X6090C011	please contact TDK	-
HVC300B-12SE2F	B88269X6120C011	HVC27-300B-12HOE2F	ordering code on request

August 21, 2026

Type	Ordering code	Replacement Type	Replacement Ordering Code
HVC500C-24S	B88269X6530C011	please contact TDK	-
HVC200A-24S	B88269X7690C011	HVC43-200A-24MC	B88269X7330C011
		HVC27-300A-12HO	B88269X3920C011
		HVC27-300A-12MOC1	B88269X8560C011
HVC500B-24HCF	B88269X7700C011	HVC27-500B-24HCF	B88269X6570C011
HVC500B-12SE2KF	B88269X7720C011	please contact TDK	-
HVC500B-12SE2F	B88269X8720C011	HVC27-500B-12HOE2F	B88269X7400C011
HVC500B-12SE2F	B88269X8720C011A02	HVC27-500B-12HOE2F	B88269X7400C011
HVC500B-24SV	B88269X1790C011	HVC27-500B-24HOF	B88269X3580C011
HVC200B-24SE2F	B88269X4420C011	HVC27-300A-24MOC1	B88269X8570C011
HVC500B-12SE2KF	B88269X5720C011	HVC27-500A-12MOC1	B88269X8600C011
HVC500B-24SF	B88269X5060C011	please contact TDK	ordering code on request
HVC500B-24SF	B88269X8040C011	please contact TDK	ordering code on request

Deadline for last orders: December 04, 2026

Last shipments by: March 05, 2027

Contact Saurabh Dilip Kothale, PPD AB PM, Berlin

Customers are asked to address inquiries directly to their sales contacts.

August 21 2026

EOL - Discontinuance of HVC 25 series

Affected Parts

B88269X6150C11
B88269X2070C11
B88269X2110C11
B88269X2120C11
B88269X2150C11
B88269X2190C11
B88269X2210C11
B88269X2220C11
B88269X2240C11
B88269X2250C11
B88269X2260C11
B88269X2270C11
B88269X2280C11
B88269X2290C11
B88269X2300C11
B88269X2310C11
B88269X2320C11
B88269X2340C11
B88269X2350C11
B88269X2390C11
B88269X2430C11