

February 27, 2026

## PTN

### Discontinuation of transformer B78416\* series

To streamline the product range, the following automotive transformers for ultrasonic sensors are being discontinued without replacement. For alternative parts, please contact your regional sales representative.

#### Affected products

Ordering code Discontinued series	Type
B78416A2029A003	T3340 EP 6 TRANSFORMER
B78416A2151A003	T6487 EP 6 SMD TRANSFORMER
B78416A2199A003	T7978 EP 6 SMD TRANSFORMER
B78416A2232A003	P100143 EP 6 SMD TRANSFORMER
B78416A2327A003	P100612 EP 6 SMDTRANSFORMER
B78416A2360A003	P301048 EP 6 SMD TRANSFORMER
B78416A2386A003	P301143 EP 6 SMD TRANSFORMER
B78416A2430A003	P301598 EP 6 SMD TRANSFORMER
B78416A2433A003	P100953 EP 6 SMD TRANSFORMER
B78416A2447A003	P301802-A1 EP 6 SMD TRANSFORMER
B78416A9874A003	P303954 EP 6 SMD TRANSFORMER
B78416B2000A003	T2906 EP 6 TRANSFORMER
B78416X0001	SAMPLE KIT EP 6 SMD TRANSFORMER

Deadline for last orders: September 1, 2026

Last shipments by: March 27, 2027

**Contact** René Steinbrecher, MAG TF T PM 2, Munich

**Customers are asked to address inquiries directly to their sales contacts.**

#### TDK Electronics AG

Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany  
 Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250  
 Chairman of the Supervisory Board: Joachim Zichlarz  
 Management Board: Dr. Werner Lohwasser, Chairman · Juergen Holzinger  
[www.tdk-electronics.tdk.com](http://www.tdk-electronics.tdk.com)

#### MAG

**Transformers**  
 Internal / External

260227MAG1e