

OFFICIAL ANNOUNCEMENT
- Discontinuation Note -

TOSHIBA

Please find the **official announcement** that TOSHIBA, in line with previous verbal information, will stop all promotion and sales activities for products in following attachment:

Related products:

Discontinue Date	BU	P/N	Phase-Out = last order entry	Obsolete = last delivery	Substitution level *	Replacement Company	Replacement P/N	Reason*	Remarks(English)	ACTIVE in TEE
202504	X33	1SS154(TE85L,F)	202607	202610	3	INFINEON	BAT17	5		
202504	X33	1SS268(TE85L,F)	202607	202610	3	ROHM	DAN235FM	5		
202504	X33	1SS269(TE85L,F)	202607	202610	3	ROHM	DAP236U	5		
202504	X33	1SS271(TE85L,F)	202607	202610	2	INFINEON	BAT17-04	5		Y
202504	X33	1SS295(TE85L,F)	202607	202610	3	INFINEON	BAT63-02V	5		Y
202504	X33	1SS312(TE85L,F)	202607	202610	1	ROHM	DAN235FM	5		
202504	X33	1SS313(TE85L,F)	202607	202610	1	ROHM	DAP236U	5		Y
202504	X33	1SS314(TPH3,F)	202607	202610	1	TOSHIBA	1SS314,H3F(T	3		Y
202504	X33	1SS315(TPH3,F)	202607	202610	3	INFINEON	BAT63-02V	5		Y
202504	X33	1SS364(TE85L,F)	202607	202610	1	ROHM	DAN235E	5		
202504	X33	1SS381(TH3PEW,E)	202607	202610	2	ROHM	1SS390SMFH	9		
202504	X33	1SS381(TPH3,F)	202607	202610	1	TOSHIBA	1SS381,L3F(T	3		Y
202504	X33	1SS381(TPL3,F)	202607	202610	1	TOSHIBA	1SS381,L3F(T	3		
202504	X33	2SA1721-O(5LTOJS,E)	202607	202610	2	DIODES	MMBTA92	5		
202504	X33	2SA1721-O,LTOJSF(A	202607	202610	2	DIODES	MMBTA92	5		
202504	X33	DF2S6.8UFS,L3XGM(T	202607	202610	0			1		
202504	X33	JDH3D01FV(TPL3)	202607	202610	3	INFINEON	BAT63-02V	5		Y
202504	X33	JDH3D01S(TE85L,F)	202607	202610	3	INFINEON	BAT63-02V	5		
202504	X33	JS1DK2-A8(ES)	202607	202610	0			5	No future demand	
202504	X33	MT3S111(T5LHARAD,F	202607	202610	3	NXP	BFU550A	4		
202504	X33	MT3S111,LMTMF(A	202607	202610	3	NXP	BFU550A	4		
202504	X33	MT3S111TU(5LALPK,E	202607	202610	3	NXP	BFU550W	4		
202504	X33	MT3S111TU(T5LHARAD	202607	202610	3	NXP	BFU550W	4		
202504	X33	MT3S111TU(T5LMBS,E	202607	202610	3	NXP	BFU550W	4		
202504	X33	MT3S111TU,LCALF(T	202607	202610	3	NXP	BFU550W	4		Y
202504	X33	MT3S111TU,LHARAF(T	202607	202610	3	NXP	BFU550W	4		

202504	X33	MT3S111TU,LXGF(T	202607	202610	3	NXP	BFU550W	4	Y
202504	X33	MT3S111TU,LYKOF(T	202607	202610	3	NXP	BFU550W	4	
202504	X33	MT3S113P(TE12L,ZE)	202607	202610	3	NXP	BFU550W	4	
202504	X33	MT3S113TU(5LYOKO,E	202607	202610	3	NXP	BFU550W	4	
202504	X33	MT3S113TU(T5LHARAD	202607	202610	3	NXP	BFU550W	4	
202504	X33	MT3S113TU,LF(T	202607	202610	3	NXP	BFU550W	4	
202504	X33	MT4S300U(T5LPVT,E)	202607	202610	2	ONSemiconductor	NSVF4009SG4	4	
202504	X33	MT4S300U,LHARADF(A	202607	202610	2	ONSemiconductor	NSVF4009SG4	4	
202504	X33	MT4S300U,LMTMF(A	202607	202610	2	ONSemiconductor	NSVF4009SG4	4	
202504	X33	MT4S300U,LYKOF(A	202607	202610	2	ONSemiconductor	NSVF4009SG4	4	
202504	X33	MT4S301U(T5LFJTN,E	202607	202610	2	ONSemiconductor	NSVF4009SG4	4	Y
202504	X33	MT4S301U,LMTMF(A	202607	202610	2	ONSemiconductor	NSVF4009SG4	4	
202504	X33	SSM3K48FU,LF(T	202607	202610	2	TOSHIBA	SSM3K15AFU,LF(T	3	
202504	X33	SSM3K48FU,LPVAF(A	202607	202610	1	TOSHIBA	SSM3K15AFU,LF(T	3	
202504	X33	SSM3K48FU,LXGF(T	202607	202610	1	TOSHIBA	SSM3K7002KFU,LXH(T	9	
202504	X33	SSM6L09FU(TE85L,F)	202607	202610	3	TOSHIBA	SSM6L40TU,LF(T	3	Y
202504	X33	SSM6L09FU,LKOITF(A	202607	202610	3	TOSHIBA	SSM6L820R,LXHF(T	9	
202504	X33	SSM6L09FU,RSONYF(A	202607	202610	3	TOSHIBA	SSM6L40TU,LF(T	3	
202504	X33	SSM6L16FE(TE85L,F)	202607	202610	1	TOSHIBA	SSM6L35FE,LM(T	3	Y
202504	X33	SSM6L16FE(TLR3SOYF	202607	202610	1	TOSHIBA	SSM6L35FE,LM(T	3	
202504	X33	SSM6N48FU,LF(T	202607	202610	2	TOSHIBA	SSM6N15AFU,LF(T	3	
202504	X33	SSM6N48FU,LXGF(T	202607	202610	2	TOSHIBA	SSM6M7002KFU,LXH(T	3	
202504	X33	SSM6N48FU,RASUSF(T	202607	202610	2	TOSHIBA	SSM6N15AFU,LF(T	3	
202504	X33	T1HZ1F,LF(S	202607	202610	0			4	Termination of SSBU
202504	X33	TA48LS015F,LHTAF(O	202607	202610	0			4	Aging of assembly equipment
202504	X33	TPC6502,LF(O	202607	202610	0			4	Aging of assembly equipment
202504	X33	TPC6504,LDNSOHE(O	202607	202610	0			4	Aging of assembly equipment
202504	X33	TPCA8084,L1JTEKX(O	202607	202610	2	TOSHIBA	XPH3R206NC	1	Shift to Cu connector items
202504	X33	TPCA8084,L1TOKSQ(O	202607	202610	2	TOSHIBA	XPH3R206NC	1	Shift to Cu connector items
202504	X33	TPCA8085,L1ALPSQ(O	202607	202610	2	TOSHIBA	XPH3R304PS	1	Shift to Cu connector items
202504	X33	TPCA8085,L1CHQ(O	202607	202610	2	TOSHIBA	XPH3R304PS	1	Shift to Cu connector items
202504	X33	TPCA8086(L1FJTN,Q)	202607	202610	2	TOSHIBA	XPH3R206NC	1	Shift to Cu connector items
202504	X33	TPCA8086,L1STLQ(O	202607	202610	2	TOSHIBA	XPH3R206NC	1	Shift to Cu connector items
202504	X33	TPCA8121(T2L1FJT,V	202607	202610	2	TOSHIBA	XPH3R114MC	1	Shift to Cu connector items
202504	X33	TPCA8122,L1ALPSQ(O	202607	202610	2	TOSHIBA	XPH4R714MC	1	Shift to Cu connector items
202504	X33	TPCA8122,L1CLEQ(O	202607	202610	2	TOSHIBA	XPH4R714MC	1	Shift to Cu connector items
202504	X33	TPCA8122,L1PAVQ(O	202607	202610	2	TOSHIBA	XPH4R714MC	1	Shift to Cu connector items
202504	X33	TPCA8123,L1PHCQ(O	202607	202610	2	TOSHIBA	XPH13016MC	1	Shift to Cu connector items
202504	X33	TPCA8123,L1TOKSQ(O	202607	202610	2	TOSHIBA	XPH13016MC	1	Shift to Cu connector items
202504	X33	TPCA8124,L1CHQ(O	202607	202610	2	TOSHIBA	XPN9R614MC	1	Shift to Cu connector items
202504	X33	TPCA8124,L1PASQ(O	202607	202610	2	TOSHIBA	XPN9R614MC	1	Shift to Cu connector items
202504	X33	TPCA8125(L1FJTN,Q)	202607	202610	2	TOSHIBA	XPH13016MC	1	Shift to Cu connector items
202504	X33	TPCA8125,L1JTEKX(O	202607	202610	2	TOSHIBA	XPH13016MC	1	Shift to Cu connector items

202504	X33	TPCA8125,L1TOJ1X(O	202607	202610	2	TOSHIBA	XPH13016MC	1	Shift to Cu connector items	
202504	X33	TPCP8R01(T5LHTA,E	202607	202610	3	TOSHIBA	SSM6K809R,LF(T	5		
202504	X33	TPH4R304NC,L1ALQ(O	202607	202610	2	TOSHIBA	XPH3R304PS	1	Shift to Cu connector items	
202504	X33	TPH4R304NC,L1APQ(O	202607	202610	2	TOSHIBA	XPH3R304PS	1	Shift to Cu connector items	
202504	X33	TPH4R304NC,L1NEQ(O	202607	202610	2	TOSHIBA	XPH3R304PS	1	Shift to Cu connector items	
202504	X33	TPH4R304NC,L1Q(O	202607	202610	2	TOSHIBA	XPH3R304PS	1	Shift to Cu connector items	
202504	X35	JS1DP8-AS(TYG1)	202607	202610	0			5	No future demand	
202504	X35	JS1DR0-AS(TYG1)	202607	202610	0			5	No future demand	
202504	X35	JS1HT3-AS(TYG1)	202607	202610	0			5	No future demand	
202504	X35	J55N39-AS(DNSO1)	202607	202610	0			5	No future demand	
202504	X35	J55N39-AS(TYG1)	202607	202610	0			5	No future demand	
202504	X35	J55P15-AS(DNSO1)	202607	202610	0			5	No future demand	
202504	X35	J55P15-AS(TYG1)	202607	202610	0			5	No future demand	
202504	X36	TLP2105(F)	202607	202610	3	TOSHIBA	TLP2355(E(T×2	3		
202504	X36	TLP2105(TP,F)	202607	202610	3	TOSHIBA	TLP2355(TPL,E(T×2	3		Y
202504	X36	TLP2105(V4-TP,F)	202607	202610	3	TOSHIBA	TLP2355(V4-TPL,x2	3		
202504	X36	TLP2108(F)	202607	202610	3	TOSHIBA	TLP2358(E(T×2	3		
202504	X36	TLP2108(TP,F)	202607	202610	3	TOSHIBA	TLP2358(TPL,E(T×2	3		Y
202504	X36	TLP2166A(F)	202607	202610	3	TOSHIBA	TLP2261(LF4,E(O	3		
202504	X36	TLP2166A(TP,F)	202607	202610	3	TOSHIBA	TLP2261(TP4,E(O	3		Y
202504	X36	TLP3100(F)	202607	202610	3	TOSHIBA	TLP3480(TP,E(O	3		Y
202504	X36	TLP3100(OMT,F)	202607	202610	3	TOSHIBA	TLP3480(OMTT05,E(O	3		
202504	X36	TLP3100(OMT-TP,F)	202607	202610	3	TOSHIBA	TLP3480(OMTT05,E(O	3		
202504	X36	TLP3100(TP,F)	202607	202610	3	TOSHIBA	TLP3480(TP,E(O	3		Y
202504	X36	TLP3101(ADV2-TP,F)	202607	202610	3	TOSHIBA	TLP3480(TP,E(O	3		
202504	X36	TLP3101(ADV3-TP,F)	202607	202610	3	TOSHIBA	TLP3480(TP,E(O	3		
202504	X36	TLP3101(ADV-TP,F)	202607	202610	3	TOSHIBA	TLP3480(TP,E(O	3		
202504	X36	TLP3102(CEE-TP,F)	202607	202610	3	TOSHIBA	TLP3107A(TP,F(O	3		
202504	X36	TLP3102(F)	202607	202610	3	TOSHIBA	TLP3107A(F(O	3		
202504	X36	TLP3102(OMT,F)	202607	202610	3	TOSHIBA	TLP3107A(OMT,F(O	3		
202504	X36	TLP3102(OMT-TP,F)	202607	202610	3	TOSHIBA	TLP3107A(OMTT05F(O	3		
202504	X36	TLP3102(TP,F)	202607	202610	3	TOSHIBA	TLP3107A(TP,F(O	3		Y
202504	X36	TLP3102(YIK-TP,F(O	202607	202610	3	TOSHIBA	TLP3107A(TP,F(O	3		
202504	X36	TLP3103(F)	202607	202610	3	TOSHIBA	TLP3107A(F(O	3		
202504	X36	TLP3103(OMT,F)	202607	202610	3	TOSHIBA	TLP3107A(OMT,F(O	3		
202504	X36	TLP3103(OMT-TP,F)	202607	202610	3	TOSHIBA	TLP3107A(OMTT05F(O	3		
202504	X36	TLP3103(TP,F)	202607	202610	3	TOSHIBA	TLP3107A(TP,F(O	3		Y
202504	X36	TLP3105(F)	202607	202610	3	TOSHIBA	TLP3109A(F(O	3		
202504	X36	TLP3105(OMT,F)	202607	202610	3	TOSHIBA	TLP3109A(OMT,F(O	3		
202504	X36	TLP3105(OMT-TP,F)	202607	202610	3	TOSHIBA	TLP3109A(OMTTPF(O	3		
202504	X36	TLP3105(TP,F)	202607	202610	3	TOSHIBA	TLP3109A(TP,F(O	3		
202504	X36	TLP3106(F(O	202607	202610	2	TOSHIBA	TLP3106A(F(O	3		
202504	X36	TLP3106(OMT,F(O	202607	202610	2	TOSHIBA	TLP3106A(OMT,F(O	3		

202504	X36	TLP3106(OMTT05,F(O	202607	202610	2	TOSHIBA	TLP3106A(OMTT05F(O	3	
202504	X36	TLP3106(TP,F(O	202607	202610	2	TOSHIBA	TLP3106A(TP,F(O	3	Y
202504	X36	TLP3107(CMS-TP,F(O	202607	202610	2	TOSHIBA	TLP3107A(TP,F(O	3	
202504	X36	TLP3107(F(O	202607	202610	2	TOSHIBA	TLP3107A(F(O	3	
202504	X36	TLP3107(MBS-TP,F(O	202607	202610	2	TOSHIBA	TLP3107A(TP,F(O	3	
202504	X36	TLP3107(OMT,F(O	202607	202610	2	TOSHIBA	TLP3107A(OMT,F(O	3	
202504	X36	TLP3107(OMTT05,F(O	202607	202610	2	TOSHIBA	TLP3107A(OMTT05F(O	3	
202504	X36	TLP3107(OMT-TP,F(O	202607	202610	2	TOSHIBA	TLP3107A(OMTT05F(O	3	
202504	X36	TLP3107(PP-TP,F(O	202607	202610	2	TOSHIBA	TLP3107A(PP-TP,F(O	3	
202504	X36	TLP3107(TP,F(O	202607	202610	2	TOSHIBA	TLP3107A(TP,F(O	3	Y
202504	X36	TLP3108(F(O	202607	202610	3	TOSHIBA	TLP3107A(TP,F(O	3	
202504	X36	TLP3108(TP,F(O	202607	202610	3	TOSHIBA	TLP3107A(TP,F(O	3	
202504	X36	TLP3109(F(O	202607	202610	2	TOSHIBA	TLP3109A(TP,F(O	3	
202504	X36	TLP3109(OMT,F(O	202607	202610	2	TOSHIBA	TLP3109A(OMT,F(O	3	
202504	X36	TLP3109(OMTT05,F(O	202607	202610	2	TOSHIBA	TLP3109A(OMTT05F(O	3	
202504	X36	TLP3109(TP,F(O	202607	202610	2	TOSHIBA	TLP3109A(TP,F(O	3	Y
202504	X36	TLP3240(FROM-T15,F	202607	202610	3	TOSHIBA	TLP3440(TP,F(O	3	
202504	X36	TLP3240(OMT-T05,F	202607	202610	3	TOSHIBA	TLP3440(OMTT05,F(O	3	
202504	X36	TLP3240(OMT-T15,F	202607	202610	3	TOSHIBA	TLP3440(OMTT05,F(O	3	
202504	X36	TLP3240(TP15,F)	202607	202610	3	TOSHIBA	TLP3440(TP,F(O	3	Y
202504	X36	TLP3241(INO-TP15,F	202607	202610	3	TOSHIBA	TLP3441(TP,F(O	3	
202504	X36	TLP3241(OMT-T05,F	202607	202610	3	TOSHIBA	TLP3441(OMTT05,F(O	3	
202504	X36	TLP3241(OMT-T10,F	202607	202610	3	TOSHIBA	TLP3441(OMTT05,F(O	3	
202504	X36	TLP3241(OMT-T15,F	202607	202610	3	TOSHIBA	TLP3441(OMTT05,F(O	3	
202504	X36	TLP3241(TP15,F)	202607	202610	3	TOSHIBA	TLP3441(TP,F(O	3	Y
202504	X36	TLP3250(OMT-T05,F	202607	202610	3	TOSHIBA	TLP3450(OMTT05,F(O	3	
202504	X36	TLP3250(OMT-T10,F	202607	202610	3	TOSHIBA	TLP3450(OMT-TP,F(O	3	
202504	X36	TLP3250(OMT-T15,F	202607	202610	3	TOSHIBA	TLP3450(OMT-TP,F(O	3	
202504	X36	TLP3250(TP15,F)	202607	202610	3	TOSHIBA	TLP3450(TP,F(O	3	Y
202504	X56	M366F20AFG-7RN9(J	202607	202610	0			5	
202504	X56	M366F20AFG-7RR0(J	202607	202610	0			5	
202504	X56	M366F20AFG-7RV6(J	202607	202610	0			5	
202504	X56	M366F20AFG-7RV7(J	202607	202610	0			5	
202504	X56	M366F20AFG-7U09(J	202607	202610	0			5	
202504	X56	M366F20AFG-7U17(J	202607	202610	0			5	
202504	X56	M380FYFG-7RE1(CJ	202607	202610	0			5	
202504	X56	M380FYFG-7RE2(CJ	202607	202610	0			5	
202504	X56	M380FYFG-7RF1(CJ	202607	202610	0			5	
202504	X56	M380FYFG-7RN5(CJ	202607	202610	0			5	
202504	X56	T5DD9BC-DM	202607	202610	0			5	
202504	X56	TMP86FS28AFG(C,JZ)	202607	202610	0			5	
202504	X56	TMP86PS25FG(C,KJZ)	202607	202610	0			5	
202504	X56	TMP87PH47UG(JZ)	202607	202610	0			5	Y

202504	X56	TMPM374FWUG-DM(JOA	202607	202610	0			5	
202504	X57	TA8940PG(O,ALPSCS)	202607	202610	1	TOSHIBA	TA8940PG(O,ALPSTK)	7	
202504	X57	TB6568KQ(O,8)	202607	202610	3	TOSHIBA	TB67H450AFNG(O,EL)	4	Y
202504	X57	TB6643KQ(O,8)	202607	202610	3	TOSHIBA	TB67H450AFNG(O,EL)	4	Y
202504	X57	TB9044AFNG(HELLAEL	202607	202610	1	TOSHIBA	TB9044FNG(HELLA)	3	Y
202504	X57	TB9081FG(HELLA)	202607	202610	1	TOSHIBA	TB9081FG(HELLA,EL)	3	Y
202504	X57	TB9101FNG(DIHT,EL)	202607	202610	1	TOSHIBA	TB9101FNG(EL)	5	
202504	X57	TB9141FG(OMRON)	202607	202610	0			5	
202504	X57	TB9367FG(AISIN)	202607	202610	1	TOSHIBA	TB9367FGA(AISIN)	3	
202504	X57	TB9397FG(STANL)	202607	202610	1	TOSHIBA	TB9397FG(STANL,EL)	5	
202504	X57	TB9408FG(BC,EL)	202607	202610	1	TOSHIBA	TB9408AFG(BC,3,EL)	7	Y
202504	X57	TC62D517XBG(Z,LNEB	202607	202610	0			4	
202504	X57	TC62D518FTG(Z,LNEB	202607	202610	0			4	
202504	X57	TCK112G,LCF(S	202607	202610	1	TOSHIBA	TCK112G,LF(S	4	

Substitution level:

0 No replacement

1 Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

Reason:

1 Version Up

3 Integration of products

4 Discontinuation of Assembly Machine

5 No Order Forecast

9 Others

Discontinuation schedule:

1) Official announcement to Customer in **April 2025** (Discontinue 202504)

2) Last date of order entry to Toshiba's local Sales Office in **June 2026** (Phase-Out 202607)

3) Last date of delivery to customer in **September 2026** (Obsolete 202610)

Date 29.04.2025

generated by Product Marketing

Toshiba Electronics Europe GmbH

.....
(document transmitted by E-Mail, valid without signature)