



# Product Change Notification

Current Date: 30-Apr-2026

## TE Connectivity

**Product Change Notification:** P-26-030230

**PCN Date:** 29-APR-26

**Customer:** TTI Inc ( 168830 )

**Location:** Fort Worth

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
MicroDot Connectos

**Description of Changes**  
Due to the supplier's discontinuation of the current ink, an alternative ink is being implemented. The new ink uses the same ink base and has similar characteristics to the existing one.

**Reason for Changes:**  
Product improvement. Dear Customer, as part of our commitment to maintain continuity of supply, we are implementing an ink change resulting from the discontinuation of the current ink by the supplier. The replacement ink is equivalent in base material and performance. This change does not negatively impact quality, form, fit, or function of the affected products. The change has been reviewed and approved internally in accordance with TE Connectivity specifications and quality requirements prior to implementation.

Estimated Dates:	
<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	30-APR-2026
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1466292-1</a>	NO			032-0021-0001			
<a href="#">1532187-1</a>	NO		M83513/02-AN	"094-6126-0000", "MCKS-N1-B-9SS"			
<a href="#">1532188-1</a>	NO		M83513/02-BN	"094-6226-0000", "MCKS-N1-B-15SS"			
<a href="#">1532209-1</a>	NO		M83513/01-AN	"094-6125-0000", "MCKS-N1-B-9PS"			
<a href="#">1532210-1</a>	NO		M83513/01-BN	"094-6225-0000", "MCKS-N1-B-15PS"			
<a href="#">2-1532021-4</a>	NO			"095-0605-2067", "MCDG3-P-15P5L4-0.5"			
<a href="#">5-1532137-5</a>	NO		M83513/05-02	"S96-0002-0087"			
<a href="#">5-1532137-9</a>	NO		M83513/05-07	"S96-0002-0009"			
<a href="#">7-1532017-4</a>	NO			"095-0085-5192", "MCDM1-B-51P4C7-18.0"			
<a href="#">8-1532023-9</a>	NO			"095-9002-0023", "MCDA1-B-9S6A7-18.0"			
<a href="#">9-1532005-4</a>	NO			"140-0530-5019"			
<a href="#">9-1532019-3</a>	NO			"095-0573-0952", "MCJB2-10S5L4-0.100"			



# Product Change Notification

Current Date: 30-Apr-2026

## TE Connectivity

**Product Change Notification:** P-26-030230

**PCN Date:** 29-APR-26

**Customer:** TTI Inc. ( 3164508 )

**Location:** Fort Worth

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

MicroDot Connectos

**Description of Changes**

Due to the supplier's discontinuation of the current ink, an alternative ink is being implemented. The new ink uses the same ink base and has similar characteristics to the existing one.

**Reason for Changes:**

Product improvement. Dear Customer, as part of our commitment to maintain continuity of supply, we are implementing an ink change resulting from the discontinuation of the current ink by the supplier. The replacement ink is equivalent in base material and performance. This change does not negatively impact quality, form, fit, or function of the affected products. The change has been reviewed and approved internally in accordance with TE Connectivity specifications and quality requirements prior to implementation.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	30-APR-2026
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1466292-1</a>	NO			032-0021-0001			
<a href="#">1532187-1</a>	NO		M83513/02-AN	"094-6126-0000", "MCKS-N1-B-9SS"			
<a href="#">1532188-1</a>	NO		M83513/02-BN	"094-6226-0000", "MCKS-N1-B-15SS"			
<a href="#">1532209-1</a>	NO		M83513/01-AN	"094-6125-0000", "MCKS-N1-B-9PS"			
<a href="#">2-1532021-4</a>	NO			"095-0605-2067", "MCDG3-P-15P5L4-0.5"			
<a href="#">5-1532137-5</a>	NO		M83513/05-02	"S96-0002-0087"			
<a href="#">5-1532137-9</a>	NO		M83513/05-07	"S96-0002-0009"			
<a href="#">7-1532017-4</a>	NO			"095-0085-5192", "MCDM1-B-51P4C7-18.0"			
<a href="#">8-1532023-9</a>	NO			"095-9002-0023", "MCDA1-B-9S6A7-18.0"			
<a href="#">9-1532005-4</a>	NO			"140-0530-5019"			
<a href="#">9-1532019-3</a>	NO			"095-0573-0952", "MCJB2-10S5L4-0.100"			