



Product Change Notification

Current Date: 27-May-2026

TE Connectivity

Product Change Notification: PCN-26-280486

PCN Date: 27-MAY-26

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
Triaxial Contact Pin MIL-DTL-38999 Size 8

General Description of Changes
Please be aware of an upcoming feature change to the listed part numbers. Before: Dielectric can jam in outer body during sub-assembly process leading to increased scrap. After: Component feature dimensional changes mitigates sub-assembly interference fitment issue.

Reason for Changes:
Change to dielectric component to ensure sub-assembly interference issue is mitigated.

PCN Attributes:	
Product Category: Rf Connector	Kind of Change: Geometry
Change Feature: Subcomponents (Clip, Tape, Cable, etc)	Potential Customer Impact: No Customer Impact
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only): 26-MAY-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
241611N001	NO			9-1191774-8			



Product Change Notification

Current Date: 27-May-2026

TE Connectivity

Product Change Notification: PCN-26-280486

PCN Date: 27-MAY-26

Customer: TTI Inc. (3164508)

Location: Fort Worth

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
Triaxial Contact Pin MIL-DTL-38999 Size 8

General Description of Changes
Please be aware of an upcoming feature change to the listed part numbers. Before: Dielectric can jam in outer body during sub-assembly process leading to increased scrap. After: Component feature dimensional changes mitigates sub-assembly interference fitment issue.

Reason for Changes:
Change to dielectric component to ensure sub-assembly interference issue is mitigated.

PCN Attributes:	
Product Category: Rf Connector	Kind of Change: Geometry
Change Feature: Subcomponents (Clip, Tape, Cable, etc)	Potential Customer Impact: No Customer Impact
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only): 26-MAY-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
241611N001	NO			9-1191774-8			