

Product Name:	HPL-502 CABLE ASSEMBLY	
	USB to LNL cable assy	
Product Manager:	Jimmy Wang	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	End-of-Life	
Change Description:	End-of-Life of Cable Assembly Part Nbr 10140456-Z0400YYLF	
Reason for Change:	Aged tools can't produce for long term, not economic to invest new tools.	
Affected Parts:	10140456-Z0400YYLF	
Effective Date of Change:	May,31 2027	
Last Time Buy Date:	30 November ,2026	
Earliest Disty Return Date:	31 August ,2026	
Last Time Shipment Date	27 February ,2027	
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:		
Available Alternatives?		
Questions?	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Jimmy Wang / Product Manager</i>	
	<i>Jimmy.Wang@amphenol-fci.com</i>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date
PCN26071	10140456-Z0400YYLF	PROCESS CHANGE	MAY 31, 2027
Count:	1		

Last Disty Return date	Last Shipment date	Alternative Parts	Product Family
			502-20VF-LNL ASSEMBLIES STD

Primary MU	Product Manager	Status
4543-45430	BILL.CHEN@AMPHENOL-F	DISCONTINUE