

Product Name:	0.5mm BtB	
	BERGSTAK HS 0.5MM	
Product Manager:	Nina Zhou	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	End-of-Life	
Change Description:	End-of-Life for the listed part numbers	
Reason for Change:	Due to aged tools and low volume business the part numbers are unviable to produce. New replacement part numbers 10163418 & 10163419 available.	
Affected Parts:	10138650-058202SLF;10138651-051202LF;10138650-058202DLF	
Effective Date of Change:	May,30 2026	
Last Time Buy Date:	25 November ,2026	
Earliest Disty Return Date:	25 August ,2026	
Last Time Shipment Date	25 May ,2027	
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:		
Available Alternatives?		
Questions?	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Nina Zhou / Product Manager</i>	
	<i>nina.zhou@amphenol-fci.com</i>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date	Last Disty Return date
PCN26077	10138650-058202DLF	END OF LIFE	MAY 30, 2026	
PCN26077	10138650-058202SLF	END OF LIFE	MAY 30, 2026	
PCN26077	10138651-051202LF	END OF LIFE	MAY 30, 2026	
Count:	3			

Last Shipment date	Alternative Parts	Product Family	Primary MU
		535-57EF-0.5MM BTB-GENERAL	4543-45431
		535-57EF-0.5MM BTB-GENERAL	4543-45431
		535-57EF-0.5MM BTB-GENERAL	4543-45431

Product Manager	Status
YOUNG.YANG@AMPHENOL-FCI.COM	ACTIVE
YOUNG.YANG@AMPHENOL-FCI.COM	ACTIVE
YOUNG.YANG@AMPHENOL-FCI.COM	ACTIVE