

Product Name:	IDC CABLE ASSEMBLY	
	IDC cable assembly	
Product Manager:	Liu, Taylor	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Materials Change	
Change Description:	Qualification of new supplier Keentop as alternative for 3M wire .	
Reason for Change:	Alternate local supplier qualified due to 3M wire long lead time(175 days).	
Affected Parts:	10197766-1030LF	
Effective Date of Change:	August,01 2026	
Last Time Buy Date:	NA	
Earliest Disty Return Date:	NA	
Last Time Shipment Date	NA	
Datasheet Attached?	Yes	
Qual/Test Data Attached?	Yes	
Samples Availability Date:	01 August ,2026	
Available Alternatives?		
Questions?	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Liu, Taylor / Product Manager</i>	
	<i>Taylor.Liu@amphenol-fci.com</i>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date
PCN26115	10197766-1030LF	MATERIALS CHANGE	AUGUST 1, 2026
Count:	1		

Last Disty Return date	Last Shipment date	Alternative Parts	Product Family
			585-5NXF-IDC (CABE TO BOARD) TYPE RECEPTOR

Primary MU	Product Manager	Status
4543-45430	GINO.LIU@AMPHENOL-FC	ACTIVE