



# PRODUCT OBSOLESCENCE MEMO

## MAGNETICS

### **Bourns® Models 049135-001, 068246-000, 068246-001, 068247-001, 046569-001, and 046569-002 Inductors to Be Discontinued**

Riverside, California – May 21, 2026 – In accordance with our ongoing product life cycle management procedures, effective immediately, Bourns will transfer the Models 049135-001, 068246-000, 068246-001, 068247-001, 046569-001, and 046569-002 Inductors to End of Product Life (EOL) status. The obsolescence of supplier materials for these parts necessitates this action. A list of the affected part numbers is provided below.

Obsolete Part Numbers	
049135-001	068247-001
068246-000	046569-001
068246-001	046569-002

Regrettably, no replacement part numbers are available at this time. If there is a need in the future, we are ready to collaborate with you to develop a new design.

#### **Please Plan for the Following Dates:**

Last Time Buy Date: **May 21, 2026**

Last Ship Date: **December 31, 2026**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC26067

049135-001  
068246-000  
068246-001  
068247-001  
046569-001  
046569-002