

## Product Change Notice

PCN#: EE-PCN26031

August 15, 2026

### CLASSIFICATION OF CHANGE:

Datasheet error correction for HVH Series Supercapacitor

### DESCRIPTION OF CHANGE:

The extended voltage at 85 °C is written in error.

#### Existing:

HVH series datasheet: Technical Data ELX1538

#### Ratings

Extended temperature range: -40 °C to +85 °C (with linear voltage derating to **2.5** V @ +85 °C)

#### Performance

Life (1000 hrs @ +85 °C/**2.5** Vdc)  $\geq 70\% \leq 300$

#### To Be:

#### Ratings

Extended temperature range: -40 °C to +85 °C (with linear voltage derating to **2.3** V @ +85 °C)

#### Performance

Life (1000 hrs @ +85 °C/**2.3** Vdc)  $\geq 70\% \leq 300$

### REASON FOR CHANGE:

Datasheet print error

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Not applicable. There will be no effect on quality and reliability or performance.

### PARTS FAMILIES AFFECTED:

See following page for part number list:

### TIME SCHEDULE:

Effective Date: 08/15/2026

### ISSUED BY:

Global Product Manager: Kyle Kim

### CONTACT INFORMATION:

For questions or comments, please [Contact us](#)

**PARTS FAMILIES AFFECTED:**

| Material         | Catalog Number   |
|------------------|------------------|
| HVH0812-2R7205-R | HVH0812-2R7205-R |
| HVH0816-2R7305-R | HVH0816-2R7305-R |
| HVH0820-2R7405-R | HVH0820-2R7405-R |
| HVH1020-2R7705-R | HVH1020-2R7705-R |
| HVH1025-2R7106-R | HVH1025-2R7106-R |
| HVH1030-2R7126-R | HVH1030-2R7126-R |
| HVH1220-2R7156-R | HVH1220-2R7156-R |
| HVH1225-2R7186-R | HVH1225-2R7186-R |
| HVH1230-2R7206-R | HVH1230-2R7206-R |
| HVH1625-2R7306-R | HVH1625-2R7306-R |
| HVH1630-2R7356-R | HVH1630-2R7356-R |
| HVH1840-2R7706-R | HVH1840-2R7706-R |
| HVH1860-2R7127-R | HVH1860-2R7127-R |