



## Product/Process Change Notification [F-44.03]

PCN number	EU427
Issue date	22.01.2026
Submission date	2026.1.22
Change implementation date	2026.2.28
Production Site	JAE Hirosaki Ltd
Type of change	Replacement
Reason of change	Regular replacement in line with the TPM Capacity improvement
Type of improvement	Maintenance
Change description	Our production control team has decided to replace a molding die for MX34R32VF1,32VF1T & 32VF1A. Current molding die : 5 units(current cavity"MN""PQ""RS""VW""TU") → After replacement die : 5 units(current cavity"MN""RS""VW""TU""1C1D")
Current cavities numbers / units number	MN,RS,VW,TU,PQ / 5 units
New cavities numbers / units number	MN,RS,VW,TU,1C1D / 5 units
Affects	Supply Condition



## Product/Process Change Notification [F-44.03]

PCN number	EU427
PPAP availability date	2026.1.20
Samples availability date	2026.1.20
Target Implementation date (first shipment)	2026.3.31
Identification of first shipment	N/A
Disposition of old product	N/A
Other pending PCNs	
JAE production site responsible person	Naoko Shimizu
Additional comments	



<b>Affects:</b>
Function
Material
Process change
Appearance
Drawing/Dimensions
Capacity
Packaging
Manufacturing location
Test/inspection method
Components source
Safety
Supply Condition
Other (please specify)

<b>Reason of change:</b>
Capacity improvement
Leadtime improvement
Cost improvement
Product quality improvement
Product function improvement
Material obsolescence
Sub-supplier obsolescence
Regular replacement in line with the TPM
Other (please specify)

<b>Type of improvements</b>
Cost
Quality
Delivery
Logistics
Maintenance
Equipment upgrade
Other (please specify)

<b>Type of Change</b>
Additional
Replacement
Location change
Design change
Refurbishment
Process change
Other (please specify)

<b>Production side</b>
JAE Hirosaki Ltd
JAE Yamagata Ltd

JAE Akishima Ltd  
JAE Taiwan Ltd  
JAE Wuxi Co. Ltd  
JAE Philippines Inc  
JAE Oregon Inc  
JAE Tijuana S.A. de C.V.



