




June 2024;

Dear KAVX Connector OEM Customer and/or Global Distributors:

Re: EOL Notification - Partial list of Varicon™ Rack/Panel Connectors

The Kyocera AVX Varicon™ Input/Output Rack/panel connector family was developed in the 1970's as a ruggedized connector with tuning fork contacts and has been servicing global customers with applications in military, industrial, and test measurement markets.



As part of product lifecycle management, Kyocera AVX regularly assesses the availability, sustainability, and status of mass production tooling to manufacture these connectors to meet the needs of our global customers.

Due to aging tooling, suppliers obsoleting components, and very limited forecasted demand/sales history, we have decided to end of life (EOL) a large portion of our active Varicon parts.

The attached Varicon parts will be going EOL effective immediately without the possibility for a Last Time Buy (LTB) due to the age/status of production tooling.

Kyocera AVX will continue servicing 1139 part numbers. Please refer to the attachment for details (Kyocera AVX Varicon Parts to KEEP SERVICING 2024-06.xlsx).

We appreciate your Varicon business in the past and apologize for any inconvenience. We look forward to servicing you on any active Varicon P/N. If you have any questions, please contact your local sales representative or distributor.

Best regards,

Kyocera-AVX
Global Connector Marketing team

| Affected Part Number | Affected Part Number | Affected Part Number | Affected Part Number |
|----------------------|----------------------|----------------------|----------------------|
| 020231375200000 | 588219036000008 | 902274002400000 | 008016056000752V |
| 020123725200104 | 588219036000009 | 608026431100331 | 008016056000753HV |
| 020173725200104 | 588219036000010 | 608017036399343 | 008016056000753V |
| 020601143200000 | 588219036000011 | 607001191300343 | 008016056000754HV |
| 020601475200000 | 588219072000017 | 608016417100331 | 008016056000754V |
| 608240021300339 | 588219072000018 | 608016477100331 | 008016056000755HV |
| 608240051300339 | 588219072000019 | 608016473100331 | 008016056000755V |
| 608240031300339 | 588219072000020 | 008219018753111 | 008016056000756HV |
| 607001151300339 | 588219072000021 | 008219018000112 | 008016056000756V |
| 020601136200000 | 588219072000023 | 008223096491101 | 008016056000757HV |
| 020603233100000 | 588219072000025 | 608216031300343 | 008016056000757V |
| 020603325200000 | 588219072000032 | 625204401200062 | 008016056000758HV |
| 607001051300339 | 588219072000033 | 008223096000100 | 008016056000758V |
| 020171143200000 | 588219072000034 | 020443279200100 | 008016056000764V |
| 605001192300339 | 067698010000000 | 608240024300343 | 008016056000774V |
| 625201022300339 | 067858010000000 | 608017031300339 | 008016056217701HV |
| 607001159300339 | 008218026736001 | 007023047000111 | 008016056217701HVL |
| 020123325200104 | 007038023750001 | 608020311700000 | 008016056217701V |
| 020603325125000 | 588223048000009 | 608240031300343 | 008016056217701VL |
| 020603325200104 | 538016056504801 | 608240262300343 | 008016056217702HV |
| 020603279200100 | 067852010000000 | 007023023000110 | 008016056217702HV8 |
| 020241143200000 | 008016038217601 | 608017031300343 | 008016056217702V |
| 020201375200000 | 008016056000355 | 020223725200104 | 008016056217703HV |
| 020200145200000 | 008016120000609 | 020353279200100 | 008016056217703V |
| 605001191300343 | 008016038000910 | 007008023163002 | 008016056217704HV |
| 021203233100000 | 008016038000626 | 020223325200104 | 008016056217704V |
| 020601375200000 | 008016038000905 | 608240021300343 | 008016056217705HV |
| 020181355200000 | 008016020217602 | 020243279200100 | 008016056217705V |
| 020171375200000 | 008016020217605 | 608020331700000 | 008016056217706V |
| 020163325200104 | 008016020217611 | 020183325200104 | 008016056217707HV |
| 021203325100000 | 008016090217607 | 608017032399339 | 008016056217707HV8 |
| 020601133200000 | 008016020000903PG3G1 | 020043725200000 | 008016056217707V |
| 020053325200000 | 008016020000903PG3G3 | 020221143200000 | 008016056217708HV |
| 020140135200000 | 008016020000904PG1G1 | 308016090000413 | 008016056217708HVL |
| 020033325200000 | 008016020000910RS2S1 | 020061136200000 | 008016056217708V |
| 020103725200104 | 008016056000002PG1G1 | 007022023000001 | 008016056217708VL |
| 020211475200000 | 008016090000002PG1G1 | 608016301400000 | 008016056217709HV |
| 020240145200000 | 008016090000002PG2G2 | 007023041000001 | 008016056217709V |
| 020220145200000 | 008016020217603 | 067852700201000 | 008016056217710HV |
| 020603725200000 | 008016038217926 | 608016531600321 | 008016056217710V |
| 020081375200000 | 008020003000001 | 607001041300339 | 008016056217711HV |
| 020091475200000 | 008016038000926 | 008218054000002 | 008016056217711V |

| | | | |
|-----------------|--------------------------|--------------------|-------------------|
| 02050332510000 | 007024017189002 | 061742040000000 | 008016056217712V |
| 02018147520000 | 007024023189002 | 008129015610108 | 008016056217719HV |
| 02016014520000 | 008016020217903 | 008016020000701HV | 008016056217719V |
| 020603373125000 | 008016038000607RS1G1 | 008016020000701HV8 | 008016056217720HV |
| 02041135520000 | 007024017166001 | 008016020000701V | 008016056217720V |
| 02021135520000 | 007022023000002 | 008016020000702HV | 008016056217721HV |
| 02036135520000 | 008016090000505 | 008016020000702HV8 | 008016056217721V |
| 02060014520000 | 008016090000509 | 008016020000702V | 008016056217722V |
| 02014014520000 | 008219036722112 | 008016020000703HV | 008016056217723HV |
| 02033332510000 | 008016038217609 | 008016020000703HV8 | 008016056217723V |
| 02120337310000 | 008016038000924 | 008016020000703V | 008016056217724V |
| 02060332510000 | 008016038000923 | 008016020000704HV | 008016056217725V |
| 02016113320000 | 008016020504502 | 008016020000704HV8 | 008016056217726V |
| 02024147520000 | 008016056217503 | 008016020000704V | 008016056217731HV |
| 02011147520000 | 008016020750008 | 008016020000705HV | 008016056217731V |
| 020263233200100 | 008016020750608 | 008016020000705HV8 | 008016056217732V |
| 020173325200104 | 008016056000503 | 008016020000705V | 008016056217733HV |
| 02013014520000 | 008223048721902 | 008016020000706HV | 008016056217733V |
| 020143725200104 | 008016020000903 | 008016020000706HV8 | 008016056217734V |
| 020113325200104 | 008016120000903 | 008016020000706V | 008016056217737V |
| 020143325200104 | 008016038000925 | 008016020000707HV | 008016056217738V |
| 02036113320000 | 008016120217504 | 008016020000707HV8 | 008016056217739HV |
| 020160135200107 | 008016038000920 | 008016020000707V | 008016056217739V |
| 020503325200100 | 008016038000936 | 008016020000708HV | 008016056217740V |
| 020503273200100 | 008016090217608 | 008016020000708HV8 | 008016056217742V |
| 020503725200100 | 007038029217001 | 008016020000708V | 008016056217745V |
| 02015147520000 | 008016038217620 | 008016020000709HV | 008016056217747V |
| 008016038217507 | 008223048736902 | 008016020000709HV8 | 008016056217748V |
| 008016020217507 | 007024029141111 | 008016020000709V | 008016056217751V |
| 008016120217903 | 008016020000602- MEGG | 008016020000710HV | 008016056217752HV |
| 008016120217008 | 008016020000607- MEGG | 008016020000710HV8 | 008016056217752V |
| 942292703400355 | 008016056000533 | 008016020000710V | 008016056217753HV |
| 007038017000001 | 008016038504507 | 008016020000711HV | 008016056217753V |
| 007038023000001 | 008016020000265 | 008016020000711HV8 | 008016056217754V |
| 007038029000001 | 007024029165001 | 008016020000711V | 008016056217755V |
| 007038035000001 | 007024017165001 | 008016020000712HV | 008016056217756HV |
| 007038041000001 | 008016038000606 | 008016020000712HV8 | 008016056217756V |
| 008020002000001 | 008218030722001 | 008016020000712V | 008016056217757V |
| 902137706720062 | 008016120504002 | 008016020217701HV | 008016056217758HV |
| 007008017163001 | 008016090296602PG1S1 | 008016020217701HV8 | 008016056217758V |
| 007008023141001 | 008016038217904 | 008016020217701V | 008016056217773HV |

| | | | |
|-----------------|--------------------|--------------------|--------------------|
| 007008023163001 | 008016020000909 | 008016020217702HV | 008016056218701HV |
| 007008023163163 | 007008029163133 | 008016020217702V | 008016056218701HVL |
| 007008029163002 | 008016038217637 | 008016020217703HV | 008016056218701V |
| 007008035141001 | 008016090296105 | 008016020217703V | 008016056218701VL |
| 007008035146001 | 008016038217920 | 008016020217704HV | 008016056218702HV |
| 007008035146002 | 008016090504602 | 008016020217704V | 008016056218702HV8 |
| 007008035163002 | 007008029163155 | 008016020217705HV | 008016056218702V |
| 007008035163003 | 008020003504001 | 008016020217705V | 008016056218703HV |
| 007008035163163 | 538016020000122 | 008016020217706HV | 008016056218703V |
| 007008041141001 | 008016038217912 | 008016020217706V | 008016056218704HV |
| 007008041141002 | 008016038000635 | 008016020217707HV | 008016056218704V |
| 007008041163001 | 008016038217623 | 008016020217707V | 008016056218705V |
| 007022017000001 | 008016038217635 | 008016020217708HV | 008016056218706V |
| 007022017000002 | 008016038217636 | 008016020217708V | 008016056218707HV |
| 007022017000108 | 007008023166001 | 008016020217709HV | 008016056218707V |
| 007022017000123 | 007008029166001 | 008016020217709V | 008016056218708HV |
| 007022023000003 | 008016056217607 | 008016020217710HV | 008016056218708HVL |
| 007022023000112 | 008223048519101 | 008016020217710V | 008016056218708V |
| 007022023000123 | 008016120000904 | 008016020217711V | 008016056218708VL |
| 007022029000001 | 588223096000012 | 008016020217712V | 008016056218709V |
| 007022029000112 | 007024035141002 | 008016020218701HV | 008016056218710V |
| 007022029000123 | 008016038217932 | 008016020218701V | 008016056218711V |
| 007022035000001 | 008016038217938 | 008016020218702HV | 008016056218712V |
| 007022035000002 | 007038047217002 | 008016020218702HV8 | 008016056218719V |
| 007022035000003 | 008016038217903 | 008016020218702V | 008016056218720V |
| 007022035000123 | 008016038217909 | 008016020218707V | 008016056218721V |
| 007022041000001 | 008219030753001 | 008016020218708V | 008016056218722V |
| 007022041000002 | 008219030753005 | 008016020296701V | 008016056218723V |
| 007022041000003 | 538016056000237 | 008016020296702HV | 008016056218724V |
| 007022041000123 | 007038047000001 | 008016020296702V | 008016056218725V |
| 007022047000001 | 008016020296607 | 008016020296707V | 008016056218726V |
| 007022047000002 | 007008035166001 | 008016020296708V | 008016056218731HV |
| 007023017000001 | 008016056217601 | 008016020313701HV | 008016056218732HV |
| 007023017000110 | 008016038504604 | 008016020313702HV | 008016056218732V |
| 007023023000001 | 007023023000109 | 008016020313702HV8 | 008016056218733HV |
| 007023023000111 | 008219072000112P18 | 008016020313702V | 008016056218739HV |
| 007023029000001 | 008219072000112P21 | 008016020313703HV | 008016056218739V |
| 007023029000002 | 008219072000112P29 | 008016020313703HV8 | 008016056218741V |
| 007023029000110 | 008219072000112P32 | 008016020313703V | 008016056218742HV |
| 007023029000111 | 008219072000112P34 | 008016020313704HV | 008016056218742V |
| 007023035000001 | 008219072000112P38 | 008016020313704HV8 | 008016056218745V |
| 007023035000002 | 008219072000112P4 | 008016020313704V | 008016056218751V |
| 007023035000110 | 008219072000112P36 | 008016020313705HV | 008016056218773HV |

| | | | |
|-----------------|----------------------|--------------------|--------------------|
| 007023035000111 | 008016056000013 | 008016020313705V | 008016056296701HV |
| 007023041000002 | 008219072000112P26 | 008016020313706V | 008016056296701V |
| 007023041000110 | 008219072000112P1 | 008016020313707HV8 | 008016056296702HV |
| 007023041000111 | 008219072000112P44 | 008016020313707V | 008016056296702V |
| 007023047000001 | 008219072000112P5 | 008016020313708HV | 008016056296703HV |
| 007023047000110 | 008219072000112P6 | 008016020313708V | 008016056296703V |
| 007024017141001 | 008219072000112P61 | 008016020313709HV | 008016056296704V |
| 007024017163001 | 008016020000606 | 008016020313709HV8 | 008016056296705HV |
| 007024017163110 | 008016038000909 | 008016020313709V | 008016056296707HV |
| 007024017163111 | 008016038217607 | 008016020313710HV | 008016056296707V |
| 007024017235110 | 008218020753001 | 008016020313710HV8 | 008016056296708HV |
| 007024023141001 | 007038047217001 | 008016020313710V | 008016056296708HVL |
| 007024023141002 | 008219072000112P46 | 008016020313711HV | 008016056296708V |
| 007024023141102 | 008016120217002 | 008016020313711V | 008016056296709HV |
| 007024023163001 | 008218044736101 | 008016020313712V | 008016056296709V |
| 007024023163110 | 008016020217904 | 008016020750701V | 008016056296710V |
| 007024023163111 | 008223048000105 | 008016020750702HV | 008016056296711HV |
| 007024023235110 | 008016038217606 | 008016020750702V | 008016056296719HV |
| 007024023235111 | 008016020000904 | 008016020750707V | 008016056296719V |
| 007024029141001 | 008016038217605 | 008016020750708V | 008016056296720V |
| 007024029163001 | 008016020000906 | 008016038000701HV | 008016056296721V |
| 007024029163110 | 008016038000922 | 008016038000701HV8 | 008016056296722V |
| 007024029163111 | 008016020296002 | 008016038000701V | 008016056296723V |
| 007024035141001 | 008016056296001 | 008016038000701VL | 008016056296724V |
| 007024035163110 | 008016020217604 | 008016038000702HV | 008016056296725V |
| 007024035163111 | 008016020217610 | 008016038000702HV8 | 008016056296726V |
| 007024041163002 | 008016020504607 | 008016038000702V | 008016056296731V |
| 007024041163111 | 008016020217905 | 008016038000703HV | 008016056296737V |
| 007038017217001 | 008219036000112P34 | 008016038000703HV8 | 008016056296739HV |
| 007038035217001 | 007024023189001 | 008016038000703V | 008016056296745V |
| 007038035750001 | 008218060722100 | 008016038000704HV | 008016056296751V |
| 007038041217001 | 007038047296001 | 008016038000704HV8 | 008016056296755V |
| 007038041296001 | 008016020217910 | 008016038000704V | 008016056296773HV |
| 007038047217111 | 008016038000002PS6S1 | 008016038000705HV | 008016056313701HV |
| 008016020000001 | 008016038000909RG6G1 | 008016038000705HV8 | 008016056313701V |
| 008016020000002 | 007008023141002 | 008016038000705V | 008016056313702HV |
| 008016020000007 | 008016038000931 | 008016038000706HV | 008016056313702V |
| 008016020000008 | 008016038000935 | 008016038000706HV8 | 008016056313703HV |
| 008016020000100 | 008016020217601 | 008016038000706V | 008016056313703V |
| 008016020000121 | 008016090217601 | 008016038000707HV | 008016056313704HV |
| 008016020000338 | 008223024722902 | 008016038000707HV8 | 008016056313704V |
| 008016020000513 | 008016056000903 | 008016038000707V | 008016056313705V |
| 008016020000601 | 008016056000904 | 008016038000708HV | 008016056313706V |

| | | | |
|-----------------|----------------------|--------------------|--------------------|
| 008016020000602 | 008223024000100 | 008016038000708HV8 | 008016056313707HV |
| 008016020000603 | 008016038217002PS1S2 | 008016038000708V | 008016056313707V |
| 008016020000604 | 008016020217608 | 008016038000709HV | 008016056313708HV |
| 008016020000607 | 008219018753002 | 008016038000709HV8 | 008016056313708V |
| 008016020000608 | 008219018753005 | 008016038000709V | 008016056313709HV |
| 008016020000609 | 008016056217608RS5S1 | 008016038000710HV | 008016056313709V |
| 008016020000610 | 008219036721002 | 008016038000710HV8 | 008016056313710HV |
| 008016020000612 | 008016038750602 | 008016038000710V | 008016056313710V |
| 008016020000613 | 008016020750607 | 008016038000711HV | 008016056313711HV |
| 008016020199110 | 008016090000601PS5S1 | 008016038000711HV8 | 008016056313711V |
| 008016020217001 | 008016020504001 | 008016038000711V | 008016056313712HV |
| 008016020217607 | 008016020504007 | 008016038000712HV8 | 008016056313712V |
| 008016020217609 | 008016020000905 | 008016038000712V | 008016056313719HV |
| 008016020504002 | 008016020000605 | 008016038000719HV | 008016056313719V |
| 008016020504602 | 008219072753121 | 008016038000719HV8 | 008016056313720HV |
| 008016020504606 | 008219072753125 | 008016038000719V | 008016056313720V |
| 008016038000001 | 008219072000112P40 | 008016038000720HV | 008016056313721HV |
| 008016038000002 | 008219072753111H36 | 008016038000720HV8 | 008016056313721V |
| 008016038000007 | 008223072000907 | 008016038000720V | 008016056313722HV |
| 008016038000008 | 007022035000104 | 008016038000721HV | 008016056313722V |
| 008016038000234 | 008016020000122 | 008016038000721HV8 | 008016056313723HV |
| 008016038000300 | 007024023156001 | 008016038000721V | 008016056313723V |
| 008016038000501 | 008016038000912 | 008016038000722HV8 | 008016056313724V |
| 008016038000502 | 008016020217002 | 008016038000722V | 008016056313725HV |
| 008016038000507 | 538016020199113 | 008016038000723HV | 008016056313725V |
| 008016038000508 | 308016983500000 | 008016038000723HV8 | 008016056313726HV |
| 008016038000510 | 538016038199103 | 008016038000723V | 008016056313726V |
| 008016038000519 | 007024029166001 | 008016038000724HV | 008016056313731HV |
| 008016038000601 | 007024029156001 | 008016038000724HV8 | 008016056313731V |
| 008016038000602 | 008016020296002PG3G3 | 008016038000724V | 008016056313732HV |
| 008016038000603 | 008223096000003 | 008016038000725HV | 008016056313732V |
| 008016038000604 | 008219018000112H9 | 008016038000725HV8 | 008016056313733HV |
| 008016038000605 | 007008041163163 | 008016038000725V | 008016056313733HV8 |
| 008016038000607 | 008016038000612 | 008016038000726HV8 | 008016056313733V |
| 008016038000608 | 008016056750602 | 008016038000726V | 008016056313734V |
| 008016038000609 | 008016038750912 | 008016038000731HV | 008016056313735V |
| 008016038000611 | 008016056000607RS3S6 | 008016038000731V | 008016056313736HV |
| 008016038000618 | 008016020504008 | 008016038000734V | 008016056313736V |
| 008016038000619 | 008016020504608 | 008016038000737HV | 008016056313737HV |
| 008016038000620 | 008218054722001 | 008016038000737V | 008016056313737V |
| 008016038000623 | 007024017141002 | 008016038000740HV | 008016056313738V |
| 008016038000624 | 008218054000001 | 008016038000740V | 008016056313739HV |
| 008016038000625 | 008016038217601PS1G1 | 008016038000745HV | 008016056313739V |

| | | | |
|-----------------|----------------------|--------------------|-------------------|
| 008016038000631 | 008016038217607RG1S1 | 008016038000751HV | 008016056313740HV |
| 008016038000636 | 308016020000413 | 008016038000751V | 008016056313740V |
| 008016038217001 | 308016020000415 | 008016038000752HV | 008016056313742V |
| 008016038217002 | 308016038000413 | 008016038000752V | 008016056313745HV |
| 008016038217007 | 308016056000413 | 008016038000753HV | 008016056313745V |
| 008016038217008 | 308016090000415 | 008016038000753V | 008016056313747V |
| 008016038217502 | 308016892038113 | 008016038000754HV | 008016056313748V |
| 008016038217524 | 308016892056113 | 008016038000754V | 008016056313751V |
| 008016038217602 | 605007300900000 | 008016038000755V | 008016056313752V |
| 008016038217608 | 605007342900000 | 008016038000756HV | 008016056313753HV |
| 008016038217611 | 605009311500000 | 008016038000756V | 008016056313753V |
| 008016038217624 | 605009317500000 | 008016038000757V | 008016056313754V |
| 008016038217632 | 607001061300000 | 008016038000758HV | 008016056313756HV |
| 008016038296602 | 607001062300000 | 008016038000758V | 008016056313756V |
| 008016038296607 | 607001159300343 | 008016038217701HV | 008016056313757HV |
| 008016038504002 | 607001162300000 | 008016038217701V | 008016056313757V |
| 008016038504007 | 607008301500000 | 008016038217702HV | 008016056313758HV |
| 008016038504008 | 607008302500000 | 008016038217702HV8 | 008016056313758V |
| 008016038504502 | 607008304500000 | 008016038217702V | 008016056313773HV |
| 008016038504602 | 607008305500000 | 008016038217703HV | 008016056313773V |
| 008016038504607 | 607008312500000 | 008016038217703V | 008016056750701HV |
| 008016056000001 | 607008314500000 | 008016038217704HV | 008016056750701V |
| 008016056000002 | 607022302500000 | 008016038217704V | 008016056750702HV |
| 008016056000195 | 607022304500000 | 008016038217705HV | 008016056750702V |
| 008016056000201 | 607022305500000 | 008016038217705V | 008016056750703V |
| 008016056000354 | 607024301500000 | 008016038217706V | 008016056750707HV |
| 008016056000501 | 607024302500000 | 008016038217707HV | 008016056750707V |
| 008016056000502 | 607024303500000 | 008016038217707V | 008016056750708HV |
| 008016056000601 | 607038301500000 | 008016038217708HV | 008016056750708V |
| 008016056000602 | 607038302500000 | 008016038217708HV8 | 008016056750709V |
| 008016056000603 | 607038303500000 | 008016038217708V | 008016056750711V |
| 008016056000607 | 607038305500000 | 008016038217709HV | 008016056750719V |
| 008016056000608 | 607038306500000 | 008016038217709V | 008016056750720V |
| 008016056000609 | 608016301401000 | 008016038217710HV | 008016056750721V |
| 008016056000636 | 608016311401000 | 008016038217710V | 008016056750722V |
| 008016056217001 | 608016321400000 | 008016038217711HV | 008016056750723V |
| 008016056217002 | 608016321401000 | 008016038217711V | 008016056750724V |
| 008016056217602 | 608016331400000 | 008016038217712V | 008016056750725V |
| 008016056217603 | 608016331401000 | 008016038217719HV | 008016056750726V |
| 008016056217608 | 608016341400000 | 008016038217719V | 008016056750731HV |
| 008016056296602 | 608016341401000 | 008016038217720HV | 008016056750745V |
| 008016056296607 | 608016351400000 | 008016038217720V | 008016056750751V |
| 008016056504002 | 608016351401000 | 008016038217721HV | 008016056750773HV |

| | | | |
|-----------------|-----------------|--------------------|--------------------|
| 008016056504502 | 608016361400000 | 008016038217721V | 008016090000701HV |
| 008016056504508 | 608016361401000 | 008016038217722V | 008016090000701HV8 |
| 008016056504601 | 608016371400000 | 008016038217723HV | 008016090000701V |
| 008016056504602 | 608016371401000 | 008016038217723HV8 | 008016090000702HV |
| 008016056504607 | 608016381400000 | 008016038217723V | 008016090000702HV8 |
| 008016056504613 | 608016391400000 | 008016038217724HV | 008016090000702V |
| 008016056750502 | 608016411100331 | 008016038217724HV8 | 008016090000703HV |
| 008016056750607 | 608016412100331 | 008016038217724V | 008016090000703HV8 |
| 008016087101000 | 608016413100000 | 008016038217725V | 008016090000703V |
| 008016090000001 | 608016414100000 | 008016038217726V | 008016090000704HV |
| 008016090000002 | 608016421600321 | 008016038217731HV | 008016090000704HV8 |
| 008016090000007 | 608016451600321 | 008016038217731V | 008016090000704V |
| 008016090000008 | 608016471100331 | 008016038217737HV | 008016090000705HV |
| 008016090000272 | 608016471100355 | 008016038217740V | 008016090000705V |
| 008016090000501 | 608016472100331 | 008016038217751HV | 008016090000706V |
| 008016090000502 | 608016472100355 | 008016038217751V | 008016090000707HV |
| 008016090000507 | 608016474100000 | 008016038217753V | 008016090000707HV8 |
| 008016090000508 | 608016521500000 | 008016038217755V | 008016090000707V |
| 008016090000536 | 608016531100355 | 008016038217756V | 008016090000708HV |
| 008016090000601 | 608016571600321 | 008016038217757V | 008016090000708HV8 |
| 008016090000602 | 608016582600000 | 008016038217758HV | 008016090000708V |
| 008016090000607 | 608016651500113 | 008016038217758V | 008016090000709HV |
| 008016090000608 | 608016691100331 | 008016038218701HV | 008016090000709HV8 |
| 008016090217001 | 608016692100000 | 008016038218701V | 008016090000709V |
| 008016090217007 | 608016692100331 | 008016038218702HV | 008016090000710HV |
| 008016090217602 | 608016701100000 | 008016038218702HV8 | 008016090000710HV8 |
| 008016090296001 | 608016701100355 | 008016038218702V | 008016090000710V |
| 008016090296002 | 608016702100355 | 008016038218703HV | 008016090000711HV |
| 008016090296007 | 608016711100000 | 008016038218703V | 008016090000711HV8 |
| 008016090296607 | 608016711100331 | 008016038218704V | 008016090000711V |
| 008016090504002 | 608016711100355 | 008016038218705V | 008016090000712HV |
| 008016090504007 | 608016731600321 | 008016038218706V | 008016090000712V |
| 008016090504601 | 608016892056113 | 008016038218707HV | 008016090000731HV |
| 008016090504607 | 608017032300339 | 008016038218707V | 008016090000731HV8 |
| 008016120000001 | 608017063300339 | 008016038218708HV | 008016090000731V |
| 008016120000002 | 608017131300339 | 008016038218708V | 008016090000734HV |
| 008016120000007 | 608017791300474 | 008016038218709HV | 008016090000734V |
| 008016120000008 | 608020321000000 | 008016038218709V | 008016090000737HV |
| 008016120000166 | 608026121600321 | 008016038218710HV | 008016090000737HV8 |
| 008016120000387 | 608026411600321 | 008016038218710V | 008016090000737V |
| 008016120000388 | 608026431100355 | 008016038218711V | 008016090000740HV |
| 008016120000389 | 608026461000000 | 008016038218712V | 008016090000740V |
| 008016120000390 | 608106032300000 | 008016038218719HV | 008016090000788HV8 |

| | | | |
|-----------------|-----------------|-------------------|--------------------|
| 008016120000501 | 608129301500000 | 008016038218719V | 008016090000789HV8 |
| 008016120000502 | 608129302500000 | 008016038218720V | 008016090000790HV8 |
| 008016120000507 | 608129303500000 | 008016038218721V | 008016090000791HV8 |
| 008016120000508 | 608129401100231 | 008016038218722V | 008016090217701HV |
| 008016120217001 | 608129411100062 | 008016038218723V | 008016090217701HV8 |
| 008016120217007 | 608129431500148 | 008016038218724V | 008016090217701V |
| 008016120217501 | 608129451200000 | 008016038218725V | 008016090217702HV |
| 008016120504007 | 608129451200062 | 008016038218726V | 008016090217702HV8 |
| 008020002217001 | 608218301500000 | 008016038218731V | 008016090217702V |
| 008020003217001 | 608218311500000 | 008016038218737V | 008016090217703HV |
| 008129006603002 | 608218421800000 | 008016038218751V | 008016090217703V |
| 008129006603003 | 608218432800130 | 008016038296701HV | 008016090217704HV |
| 008129006603006 | 608218441800000 | 008016038296701V | 008016090217704V |
| 008129006603007 | 608218442800130 | 008016038296702HV | 008016090217705V |
| 008129006610001 | 608219301500000 | 008016038296702V | 008016090217706V |
| 008129006612002 | 608219302500000 | 008016038296703HV | 008016090217707HV |
| 008129009603002 | 608219304500000 | 008016038296703V | 008016090217707HV8 |
| 008129009603003 | 608219305500000 | 008016038296704V | 008016090217707V |
| 008129009610001 | 608219306500000 | 008016038296707HV | 008016090217708HV |
| 008129009612003 | 608219311500000 | 008016038296707V | 008016090217708HV8 |
| 008129012603002 | 608219312500000 | 008016038296708HV | 008016090217708V |
| 008129012603003 | 608219315500000 | 008016038296708V | 008016090217709HV |
| 008129012610001 | 608219316500000 | 008016038296709HV | 008016090217709HV8 |
| 008129012610002 | 608219401300382 | 008016038296709V | 008016090217709V |
| 008129012612003 | 608219431200000 | 008016038296710V | 008016090217710HV |
| 008129015610003 | 608219431200148 | 008016038296712V | 008016090217710V |
| 008129015612003 | 608219461200148 | 008016038296719HV | 008016090217711HV |
| 008218002722001 | 608219461200382 | 008016038296719V | 008016090217711V |
| 008218004000002 | 608219471200225 | 008016038296720V | 008016090217712V |
| 008218006000002 | 608223361500000 | 008016038296721V | 008016090217731HV |
| 008218010753001 | 608223362500000 | 008016038296722V | 008016090217731HV8 |
| 008218010753102 | 608223364500000 | 008016038296723V | 008016090217731V |
| 008218014000100 | 608223371500000 | 008016038296724V | 008016090217737V |
| 008218014753101 | 608223372500000 | 008016038296725V | 008016090217740HV |
| 008218016000002 | 608223373500000 | 008016038296726V | 008016090217740V |
| 008218018722101 | 608223381500000 | 008016038296731V | 008016090218701HV |
| 008218020000101 | 608223382500000 | 008016038296751V | 008016090218701V |
| 008218020753102 | 608223383500000 | 008016038296753V | 008016090218702HV |
| 008218022000109 | 608223391500000 | 008016038313701HV | 008016090218702HV8 |
| 008218022000114 | 608223393500000 | 008016038313701V | 008016090218702V |
| 008218022753001 | 608223452200062 | 008016038313702HV | 008016090218703HV |
| 008218022753108 | 608223466200062 | 008016038313702V | 008016090218703V |
| 008218022753109 | 608240030300000 | 008016038313703HV | 008016090218704HV |

| | | | |
|-----------------|-----------------|--------------------|--------------------|
| 008218032000002 | 608240030300339 | 008016038313703V | 008016090218704V |
| 008218032722001 | 625101061300000 | 008016038313704HV | 008016090218705V |
| 008218032722002 | 625101341400000 | 008016038313704HV8 | 008016090218706V |
| 008218032722102 | 625201023300343 | 008016038313704V | 008016090218707HV |
| 008218040722001 | 625204411200000 | 008016038313705HV | 008016090218707HV8 |
| 008218040736100 | 628202400200062 | 008016038313705V | 008016090218707V |
| 008218040736101 | 628202402200062 | 008016038313706V | 008016090218708HV |
| 008218040736102 | 628202403200062 | 008016038313707HV | 008016090218708V |
| 008218040736103 | 667699000201001 | 008016038313707HV8 | 008016090218709V |
| 008218040736104 | 900104007310355 | 008016038313707V | 008016090218710HV |
| 008218050722100 | 900407003710747 | 008016038313708HV | 008016090218710V |
| 008218054000106 | 900502003111053 | 008016038313708V | 008016090218711V |
| 008218054519100 | 900602012111053 | 008016038313709HV | 008016090218712V |
| 008218054736001 | 900604019610000 | 008016038313709V | 008016090218731HV |
| 008218054736102 | 900604019610331 | 008016038313710HV | 008016090218731V |
| 008218054771001 | 900604019610355 | 008016038313710V | 008016090218737V |
| 008218060722001 | 900902021510355 | 008016038313711V | 008016090296701V |
| 008218060722014 | 902033701600000 | 008016038313712HV | 008016090296702HV |
| 008218070000002 | 902072700300000 | 008016038313712V | 008016090296702V |
| 008218070736001 | 902075000902000 | 008016038313719HV | 008016090296703V |
| 008218070736101 | 902113000503000 | 008016038313719V | 008016090296704V |
| 008218072000002 | 902120001100000 | 008016038313720HV | 008016090296705V |
| 008218076000002 | 902120001500000 | 008016038313720V | 008016090296706V |
| 008218076722001 | 902120700000000 | 008016038313721V | 008016090296707HV |
| 008219018000002 | 902121733901000 | 008016038313723HV | 008016090296707HV8 |
| 008219018000012 | 902137011511053 | 008016038313723V | 008016090296707V |
| 008219018000117 | 902137017800474 | 008016038313724HV | 008016090296708V |
| 008219018721005 | 902137018511053 | 008016038313724V | 008016090296709V |
| 008219018721011 | 902167000900355 | 008016038313725HV | 008016090296710V |
| 008219018721100 | 902218002800000 | 008016038313725V | 008016090296711V |
| 008219018721115 | 902218010400000 | 008016038313726HV | 008016090296712V |
| 008219018721116 | 902300716910355 | 008016038313726V | 008016090296731V |
| 008219018721117 | 902300717010355 | 008016038313731HV | 008016090313701HV |
| 008219018721118 | 902300717310355 | 008016038313731V | 008016090313701V |
| 008219018722002 | 902300717410355 | 008016038313734V | 008016090313702HV |
| 008219018736115 | 942218703610355 | 008016038313737HV | 008016090313702HV8 |
| 008219018753106 | 942300705610355 | 008016038313737V | 008016090313702V |
| 008219018753107 | 942300711610355 | 008016038313740V | 008016090313703HV |
| 008219018753115 | 952182000213000 | 008016038313751HV | 008016090313703V |
| 008219018753117 | 952182002302000 | 008016038313751V | 008016090313704HV |
| 008219030000002 | 982346719600000 | 008016038313752HV | 008016090313704HV8 |
| 008219030721001 | 902072709642000 | 008016038313752V | 008016090313704V |
| 008219030721005 | 061877100000000 | 008016038313753HV | 008016090313705V |

| | | | |
|-----------------|-----------------|--------------------|--------------------|
| 008219030737111 | 067519030000000 | 008016038313753V | 008016090313706V |
| 008219030753106 | 308016882000000 | 008016038313754V | 008016090313707HV |
| 008219030753107 | 308016891056113 | 008016038313755V | 008016090313707HV8 |
| 008219030753108 | 308016892100113 | 008016038313756V | 008016090313707V |
| 008219030753109 | 308016892200113 | 008016038313757V | 008016090313708HV |
| 008219030753111 | 308016892500113 | 008016038313758HV | 008016090313708V |
| 008219030771001 | 308016892600113 | 008016038313758V | 008016090313709HV |
| 008219030771115 | 308016892900113 | 008016038750701HV | 008016090313709V |
| 008219036000002 | 308016893100113 | 008016038750701V | 008016090313710HV |
| 008219036000112 | 308016893400113 | 008016038750702HV | 008016090313710HV8 |
| 008219036721001 | 308016893500113 | 008016038750702V | 008016090313710V |
| 008219036721005 | 308016893800113 | 008016038750703HV | 008016090313711HV |
| 008219036722005 | 308016894300113 | 008016038750703V | 008016090313711V |
| 008219036737001 | 308016894400113 | 008016038750707HV | 008016090313712V |
| 008219036737005 | 308016922300000 | 008016038750707V | 008016090313731HV |
| 008219036753106 | 308016972000000 | 008016038750708HV | 008016090313731V |
| 008219036753107 | 308016982500000 | 008016038750708V | 008016090313737HV |
| 008219036771001 | 308016982900000 | 008016038750709V | 008016090313737V |
| 008219036771005 | 308016983100000 | 008016038750710HV | 008016090313740HV |
| 008219042000002 | 308016983800000 | 008016038750719V | 008016090313740V |
| 008219042000112 | 308016984600000 | 008016038750720V | 008016090313789HV8 |
| 008219042753001 | 308017981000000 | 008016038750721V | 008016090313791HV8 |
| 008219042753111 | 308026940100000 | 008016038750722V | 008016090750701HV |
| 008219054000002 | 378223082301000 | 008016038750723V | 008016090750701V |
| 008219054000112 | 608017031300042 | 008016038750724V | 008016090750702HV8 |
| 008219054721115 | 608218301518000 | 008016038750725V | 008016090750702V |
| 008219054722001 | 608218311530000 | 008016038750726V | 008016090750703HV |
| 008219054737111 | 608218311532000 | 008016038750751V | 008016090750703V |
| 008219054753001 | 608218311540000 | 008016056000701HV | 008016090750704V |
| 008219054753005 | 608218311552000 | 008016056000701HV8 | 008016090750705V |
| 008219054753111 | 608218311554000 | 008016056000701HVL | 008016090750706V |
| 008219072000002 | 902140700400000 | 008016056000701V | 008016090750707V |
| 008219072000012 | 608017066300000 | 008016056000701VL | 008016090750708V |
| 008219072000112 | 608314021399000 | 008016056000702HV | 008016120000701HV |
| 008219072000120 | 625101062300000 | 008016056000702HV8 | 008016120000701HV8 |
| 008219072000132 | 625203401000000 | 008016056000702V | 008016120000701V |
| 008219072721111 | 367699000101000 | 008016056000703HV | 008016120000702HV |
| 008219072753111 | 607001052300339 | 008016056000703HV8 | 008016120000702V |
| 008219072753118 | 607001061300339 | 008016056000703V | 008016120000703HV |
| 008219072753119 | 607001062300339 | 008016056000704HV | 008016120000703HV8 |
| 008219072753120 | 607001063300339 | 008016056000704HV8 | 008016120000703V |
| 008219072753122 | 607001191300339 | 008016056000704V | 008016120000704HV |
| 008219072753124 | 607001201300339 | 008016056000705HV | 008016120000704HV8 |

| | | | |
|-----------------|-----------------|--------------------|--------------------|
| 008219072753126 | 607001202300339 | 008016056000705HV8 | 008016120000704V |
| 008219072753128 | 607004021300339 | 008016056000705V | 008016120000705HV |
| 008219072753129 | 608011531600321 | 008016056000706HV | 008016120000705V |
| 008219072753130 | 608016412100355 | 008016056000706HV8 | 008016120000706V |
| 008219072753131 | 608016413100331 | 008016056000706V | 008016120000707HV |
| 008219072753132 | 608016414100331 | 008016056000707HV | 008016120000707HV8 |
| 008219072753133 | 608016432600321 | 008016056000707HV8 | 008016120000707V |
| 008223024000001 | 608016572600321 | 008016056000707V | 008016120000708HV |
| 008223024000003 | 608016581600321 | 008016056000708HV | 008016120000708HV8 |
| 008223024000901 | 608016582600321 | 008016056000708HV8 | 008016120000708V |
| 008223024580103 | 608016591600321 | 008016056000708HVL | 008016120000709HV |
| 008223024721902 | 608016671300474 | 008016056000708V | 008016120000709HV8 |
| 008223024753002 | 608016701100331 | 008016056000708VL | 008016120000709V |
| 008223048000001 | 608016702100331 | 008016056000709HV | 008016120000710HV |
| 008223048000100 | 608016722600321 | 008016056000709HV8 | 008016120000710V |
| 008223048000101 | 608016741600321 | 008016056000709V | 008016120000711HV |
| 008223048000901 | 608017032300042 | 008016056000710HV | 008016120000711V |
| 008223048580102 | 608017032300343 | 008016056000710HV8 | 008016120000712V |
| 008223048722902 | 608017032399042 | 008016056000710V | 008016120000731HV |
| 008223048753902 | 608017041300339 | 008016056000711HV | 008016120000731V |
| 008223048771101 | 608017051300339 | 008016056000711HV8 | 008016120000734V |
| 008223072000903 | 608017051300343 | 008016056000711V | 008016120000737HV |
| 008223072580102 | 608017062300339 | 008016056000712HV | 008016120000737V |
| 008223072771101 | 608017063300343 | 008016056000712HV8 | 008016120000740V |
| 008223096000001 | 608017066300339 | 008016056000712V | 008016120217701HV |
| 008223096000101 | 608017072300339 | 008016056000719HV | 008016120217701V |
| 008223096000115 | 608017371900019 | 008016056000719HV8 | 008016120217702V |
| 008223096000117 | 608026401600321 | 008016056000719V | 008016120217703HV |
| 008223096000901 | 608026551600321 | 008016056000720HV | 008016120217703V |
| 008223096000903 | 608036641600321 | 008016056000720HV8 | 008016120217704V |
| 008223096580102 | 608106024300339 | 008016056000720V | 008016120217705V |
| 008223096753100 | 608106032300339 | 008016056000721HV | 008016120217707HV |
| 008223096753902 | 608114022300339 | 008016056000721V | 008016120217707V |
| 067699010000000 | 608200162300339 | 008016056000722V | 008016120217708HV |
| 308016982200000 | 608200164300339 | 008016056000723HV | 008016120217708V |
| 308016982600000 | 608200165300343 | 008016056000723HV8 | 008016120217709HV |
| 538016020000158 | 608200166300339 | 008016056000723V | 008016120217709V |
| 538016020000193 | 608216031300339 | 008016056000724HV | 008016120217710V |
| 538016020000229 | 608219401200382 | 008016056000724HV8 | 008016120217711V |
| 538016020000265 | 608219411200225 | 008016056000724V | 008016120217731HV |
| 538016020199109 | 608219431200382 | 008016056000725HV | 008016120217731V |
| 538016020199110 | 608219441200225 | 008016056000725V | 008016120217734V |
| 538016020199112 | 608223025300339 | 008016056000726V | 008016120217737V |

| | | | |
|--------------------|------------------|--------------------|--------------------|
| 538016020199114 | 608223456200062 | 008016056000731HV | 008016120218701HV |
| 538016020217113 | 608223462200062 | 008016056000731HV8 | 008016120218701V |
| 538016038000221 | 608314031399752 | 008016056000731V | 008016120218702HV |
| 538016038000257 | 625101061300339 | 008016056000732HV | 008016120218702V |
| 538016038000293 | 625101062300339 | 008016056000732V | 008016120218703HV |
| 538016038000329 | 625101441200454 | 008016056000733HV | 008016120218703V |
| 538016038199104 | 625204411200062 | 008016056000733V | 008016120218704V |
| 538016038199105 | 625204411200489 | 008016056000734V | 008016120218705V |
| 538016056000309 | 625306031300339 | 008016056000735V | 008016120218706V |
| 538016056296106 | 628202401200062 | 008016056000736HV | 008016120218707HV |
| 538016090199100 | 667699000201403 | 008016056000736V | 008016120218707HV8 |
| 538016090199102 | 667699000401403 | 008016056000737HV | 008016120218707V |
| 538016090199103 | 900104033310331 | 008016056000737V | 008016120218708HV |
| 538016120000266 | 900106007310331 | 008016056000738HV | 008016120218708V |
| 538016120199102 | 900604019610231 | 008016056000738V | 008016120218709V |
| 588016056000087 | 902083000704331 | 008016056000739HV | 008016120218710HV |
| 588016120000084 | 902083000704355 | 008016056000739V | 008016120218710V |
| 588016120000088 | 942300015101053 | 008016056000740V | 008016120218711V |
| 588026075000002 | 942300015201053 | 008016056000741V | 008016120218712V |
| 588218040000002 | 942300015204053 | 008016056000742HV | 008016120218731HV |
| 588219018000001 | 608223022300339 | 008016056000742V | 008016120218737V |
| 588219018000002 | 608223021300339 | 008016056000745HV | 008016120296701V |
| 588219018000003 | 608016474100331 | 008016056000745V | 008016120296702HV |
| 588219018000004 | 608200163300339 | 008016056000747HV | 008016120296702V |
| 588219018000005 | 902167004200321 | 008016056000747HV8 | 008016120296703V |
| 588219018000007 | 625201021300343 | 008016056000747V | 008016120296704V |
| 588219018000028 | SPEC FOR TOOLING | 008016056000748HV8 | 008016120296707HV |
| 588219018000029 | 608200165300339 | 008016056000748V | 008016120296707V |
| 588219018000030 | 900902013611053 | 008016056000751V | 008016120296708V |
| 588219018000031 | 625201021300339 | 008016056000752HV | 008016120296709V |
| 008016120296710V | 008016120750707V | 008017130217008J | 208014350000128S |
| 008016120296712V | 008016120750708V | 008017130218001J | 208014350200128S |
| 008016120296731V | 008016120750712V | 008017130218002J | 208014350999028 |
| 008016120296737V | 008017075000001J | 008017130296001J | 308016020S |
| 008016120313701V | 008017075000007J | 008017130296007J | 308016020T |
| 008016120313702HV | 008017075000008J | 008017130313001J | 308016038A |
| 008016120313702V | 008017075217001J | 008017130313002J | 308016038AAA |
| 008016120313703HV | 008017075217007J | 008027030000004 | 308016038BBB |
| 008016120313703V | 008017075217008J | 008027030000013 | 308016038S |
| 008016120313704HV | 008017075218001J | 008027030000023 | 308016038SS |
| 008016120313704HV8 | 008017075218002J | 008027030000024 | 308016038T |
| 008016120313704V | 008017075296007J | 008027030213004 | 308016038TT |
| 008016120313705V | 008017075313001J | 008027030213013 | 308016056A |

| | | | |
|--------------------|------------------|-----------------|-------------------|
| 008016120313706V | 008017075313002J | 008027030213023 | 308016056AAA |
| 008016120313707HV | 008017075750001J | 008027030213024 | 308016056BBB |
| 008016120313707HV8 | 008017075750002J | 008027030217004 | 308016056CCC |
| 008016120313707V | 008017100000001J | 008027030217013 | 308016056S |
| 008016120313708HV | 008017100000007J | 008027030217023 | 308016056SS |
| 008016120313708V | 008017100000008J | 008027030217024 | 308016056T |
| 008016120313709HV | 008017100217001J | 008027030218004 | 308016056TAS |
| 008016120313709V | 008017100217007J | 008027030218023 | 308016056TT |
| 008016120313710HV | 008017100217008J | 008027030296004 | 308016056TTT |
| 008016120313710V | 008017100218001J | 008027030313004 | 308016090BBB |
| 008016120313711V | 008017100218002J | 008027030313013 | 308016090S |
| 008016120313712V | 008017100296007J | 008027030313023 | 308016090T |
| 008016120313731HV | 008017100296008J | 008027030313024 | 308016120BBB |
| 008016120313731V | 008017100313001J | 008027030750004 | 308016120S |
| 008016120313737HV | 008017100313002J | 008027030750013 | 308016120T |
| 008016120313737V | 008017100750001J | 008027030750023 | 308016896038113 |
| 008016120313740HV | 008017100750002J | 108014350000028 | 608017032311339 |
| 008016120313740V | 008017130000001J | 108014350000038 | 608017061300339 |
| 008016120750701V | 008017130000007J | 108014350000128 | 708014000000858 |
| 008016120750702V | 008017130000008J | 108014350100028 | 708014000004892 |
| 008016120750703V | 008017130217001J | 108014350100038 | 708014999000000 |
| 008016120750704V | 008017130217007J | 108014350100128 | 708014999000858 |
| | | | 008016056296755HV |