

Issue Date: May 11th, 2026

Dear Valued Customer,

This notice C0636 is to inform you of a change in some items that you have purchased from Littelfuse

Description of the Change:

- Littelfuse we will be updating the firmware and the outside label for the following part numbers:
 - LFHCD002Z-01
 - LFHCD002Z-02
 - LFHCD002Z-03
 - LFHCD002Z-04
 - LFHCD002Z-05
 - LFHCD002Z-06
 - LFHCD002Z-11
- This modification ensures the sensor powers off as expected once the engine is shut down.

Reason for The Change:

- Provide a solution to allow the sensor's power to be turned off.

Effective Date of the Change:

- May 11, 2026

What You Need to Do:

- There is no change in product's fit or function.
- Please validate the update firmware and approve outside label.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Associate Product Manager
Littelfuse Commercial Vehicle Products