

Document Receipt Acknowledgement

Date:
Section:
Name:



Document Number: D10122-A-A3560

Date: August 27, 2026

Attention:

TTI/FT WORTH/TX/HQ

Notice of Change to Individual Bag for Connectivity Module

Connrctivity Module Family

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.
This is the official notification of change to individual bag for connectivity module family.
Your understanding and support are highly appreciated.

1. Product Type and Changes

Product Type: Connrctivity Module Family

Before Change	After Change
Sticking a Caution Label	Printing a Caution Label
Right angle corner	Curved corner

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

As part of SDGs activities, we will eliminate the ESD labels that were previously attached to aluminum moisture-proof bags and print information equivalent to the contents of the ESD label on aluminum moisture-proof bags.

3. Products Before and After the Change:

This change does not alter the material of the aluminum moisture-proof bag or alter its environmental impact.

4. Change Schedule:

Production Start with new alminum bag: January 01, 2027 or later
(Running change)

5. Contact Window:

Should you have any questions or concerns,
please contact Murata Sales, Representative, or Distributor in your area.

6. Request regarding information handling

We kindly request that the information provided by us not be disclosed or shared with third parties, including data base providers or by posting on websites.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.
Connectivity Module Products Dept. / General Manager
Hirokazu Nakae

Customer Part Number	Murata Part Number
315-2095-000	LBEE5KL1YN-814
CMWX1ZZABZ-078	CMWX1ZZABZ-078
CMWX1ZZABZ-091	CMWX1ZZABZ-091
CMWX1ZZABZ-093	CMWX1ZZABZ-093
CMWX1ZZABZ-102	CMWX1ZZABZ-102
LBAA0QB1SJ-295	LBAA0QB1SJ-295
LBAA0QB1SJ-296	LBAA0QB1SJ-296
LBAA0XV2DT-158	LBAA0XV2DT-158
LBAA0XV2GT-001	LBAA0XV2GT-001
LBAD0XX1SC-005	LBAD0XX1SC-005
LBAD0XX1SC-151	LBAD0XX1SC-151
LBEE0ZZ2FP-546	LBEE0ZZ2FP-546
LBEE0ZZ2KL-001	LBEE0ZZ2KL-001
LBEE59B1LV-278	LBEE59B1LV-278
LBEE5CJ1XK-687	LBEE5CJ1XK-687
LBEE5HY1MW-230	LBEE5HY1MW-230
LBEE5HY2FY-922	LBEE5HY2FY-922
LBEE5KL1DX-883	LBEE5KL1DX-883
LBEE5KL1YN-814	LBEE5KL1YN-814
LBEE5PA1LD-005	LBEE5PA1LD-005
LBEE5PK2AE-564	LBEE5PK2AE-564
LBEE5PK2BC-771	LBEE5PK2BC-771
LBEE5QD1ZM-572	LBEE5QD1ZM-572
LBEE5WV2GF-001	LBEE5WV2GF-001
LBEE5XV2BZ-883	LBEE5XV2BZ-883
LBEE5XV2EA-802	LBEE5XV2EA-802
LBEE5ZZ1XL-774	LBEE5ZZ1XL-774
LBEE5ZZ2XS-846	LBEE5ZZ2XS-846
LBES0ZZ2FR-580	LBES0ZZ2FR-580
LBES0ZZ2LL-001	LBES0ZZ2LL-001
LBUA0VG2BP-741	LBUA0VG2BP-741
LBUA2ZZ2DK-882	LBUA2ZZ2DK-882
LBUA5QJ2AB-828	LBUA5QJ2AB-828
LBWA0ZZ2DS-688	LBWA0ZZ2DS-688
LBWA1KL1FX-875	LBWA1KL1FX-875
LBWA1UZ1GC-958	LBWA1UZ1GC-958
LBWA1UZ1PS-241	LBWA1UZ1PS-241
MQ100	CMWX1ZZABZ-101
MQ200	CMWX1ZZABZ-102
WSM-BL241-ADA-008	WSM-BL241-ADA-008

[illegible]