

Infonote AO-IN-2026-040-I TO56 Shipping Cover Packaging Supplier Change

Customer information package

Dr. Christian Jung, Customer Quality Visualization & Sensing (OS OSQ Q CQM ICI VS)
2026-07-01

Agenda

	Page
1. Reason for change	3
2. Description of change	4
3. List of affected products	5
4. Time schedule	6

AO-IN-2026-040-I

TO56 Shipping Cover Packaging Supplier Change

Reason for change

Description

Switching the packaging supplier for the TO56 shipping cover, since the original supplier is no longer available due to the factory shutdown.


Assessment

- No change in form, fit and function.

AO-IN-2026-040-I

TO56 Shipping Cover Packaging Supplier Change

Description of change

Current status	New status
TO56 shipping cover sourced from original supplier, now unavailable due to factory shutdown.	TO56 shipping cover sourced from new qualified supplier with identical design and performance.
 The image shows a side-by-side comparison of two black plastic shipping covers, labeled 'Old' and 'New'. The covers are rectangular with a grid of circular indentations. The top row shows the 'Top View' of both covers, and the bottom row shows the 'Bottom View'. The 'Old' cover is on the left and the 'New' cover is on the right. The covers appear identical in design and performance.	

AO-IN-2026-040-I

TO56 Shipping Cover Packaging Supplier Change

List of affected products

Product Name
PLT5 450GB
PLT5 518FB_P
PLT5 520B
PLT5 520DB_P
PLT5 520EB_P
PLT5 520EB_Q
PLT5 520FB_P
PLT5 520HB_P
SPL TL90AT03
SPL TL90AT08
SPL UL90AT03
SPL UL90AT08


AO-IN-2026-040-I

TO56 Shipping Cover Packaging Supplier Change

Time schedule

Time schedule	
Start of Introduction	22.06.2026

am



OSRAM

Infonote

AO-IN-2026-040-I

TO56 Shipping Cover Packaging Supplier Change

01.07.2026

Dear Customer,

please take note of this **Infonote**.

This customer notification is for information only and does not require customer approval.

Objective:	TO56 Shipping Cover Packaging Supplier Change
Affected products:	Refer to document 2_cip_AO-IN-2026-040-I
Reason for change:	Switching the packaging supplier for the TO56 shipping cover, since the original supplier is no longer available due to the factory shutdown.
Description of change:	Refer to document 2_cip_AO-IN-2026-040-I
Time schedule:	Start of introduction: 22.06.2026
Assessment:	No change in form, fit and function.
Documentation:	Customer information package 2_cip_AO-IN-2026-040-I

Dear customers,

Please find attached the ams OSRAM Infonote

---> CN Number: AO-IN-2026-040-I

---> CN Title: TO56 Shipping Cover Packaging Supplier Change

---> Customer Specific: NO

affected products:

Material (Q#)	Q# Description
Q65113A5272	PLT5 450GB
Q65112A0737	PLT5 520B
Q65113A4956	PLT5 520DB_P
Q65113A9218	PLT5 520B B2B3
Q65113A9217	PLT5 520EB_P B2B3
Q65115A0266	PLT5 520HB_P B2B3
Q65113A4968	PLT5 520FB_P
Q65113A8771	PLT5 520HB_P
Q65113A4964	PLT5 518FB_P
Q65112A2622	SPL TL90AT08
Q65113A4965	PLT5 520EB_Q
Q65112A2623	SPL TL90AT03
Q65113A4961	PLT5 520EB_P
Q65113A1660	SPL UL90AT03
Q65113A6694	PLT5 520DB_P C1034
Q65113A9301	PLT5 520FB_P B3

Q65112A2621	SPL UL90AT08
Q65115A2746	PLT5 518FB_P-MCT
Q65113A4967	PLT5 518FB_P C1009
Q65113A4973	PLT5 520FB_P C1009
Q65113A8770	PLT5 520B C1009
Q65113A4955	PLT5 520DB_P C1009
Q65113A4969	PLT5 520FB_P-B2B3

Kindly check and forward to your affected end-customers.

Thank You

Please note: Our company mail addresses have been changed, please update your address book and any SPAM filter rules accordingly!