

Infonote

AO-IN-2026-042-I

Process Optimization for DIL SMT Product Family

15.08.2026

Dear Customer,

please take note of this **Infonote**.

This customer notification is for information only and does not require customer approval.

Objective:	Process Optimization: Integration of 1st Visual Inspection (Manual) into Automatic Visual Inspection (AOI) for DIL SMT Product Family	
Affected products:	BP 104 FAS; BP 104 FASR; BP 104 FS; BPW 34 FAS; BPW 34 FASR; BPW 34 FS; BPW 34 FSR	
Reason for change:	Integrate the 1st Visual Inspection (VI) into the AOI process to streamline manufacturing and improve efficiency.	
Description of change:	<u>Current status</u>	<u>New status</u>
	1st Visual Inspection (Manual)	Automatic Visual Inspection (AOI)
	+ Automatic Visual Inspection (AOI)	
Time schedule:	Phase in data code: 3926 (WWYY)	
Assessment:	No Change in fit, function and reliability	
Documentation:	NA	

affected products:

Material (Q#)	Q# Description
Q65110A3121	BPW 34 FAS-Z
Q65110A2700	BPW 34 FS-Z
Q65110A2740	BPW 34 FSR-Z
Q65110A3124	BP 104 FS R33-Z
Q65110A4263	BP 104 FASR-Z
Q65110A2699	BPW 34 FASR-Z
Q65110A2627	BP 104 FS-Z
Q65110A4002	BPW 34 FAS R33-Z
Q65110A2672	BP 104 FAS-Z
Q65111A6637	BPW 34 FAS-A R33 Opt
Q65113A6629	BPW 34 FS C1038