

# PRODUCT CHANGE NOTIFICATION

Product Category LOOSE PIECE CABLE TIES **20230330-2**

Product Group PLASTIC CABLE TIES

ISSUE DATE: 30.Mär.26

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Please be advised that these items are being obsolete. We greatly value and thank you for your ongoing support.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2026	3	30
Old product discontinuation date*	2023	6	28

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	CHINA: 400-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA 1800 801435 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
NORTH AMERICA	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	EMEA	EMEA: +44 208 6017219 <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)





**Product Groups**

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

<b>IMPACTED PART NUMBER(s)</b>	<b>Compatibility Type</b>	<b>Replacement Part 1</b>
CBR1.5I-M30	Complex	PLT1.5I-M30
CBR2M-M10	Compatible	CBR2M-M
CBR2M-M3	Compatible	PLT2M-M3
CBR2M-M6	Compatible	PLT2M-M6
CBR3I-M10	Compatible	CBR3I-M
CBR3I-M3	Compatible	PLT3I-M3
CBR3S-M	Compatible	CBR4S-M
CBR3S-M30	Compatible	CBR4S-M30
CBR4I-M	Compatible	PLT4I-M
CBR4LH-TL30	Compatible	CBR6LH-C30
DHC1.12X1.75-D0	Compatible	PLB4H-TL0
HV9250-CP0	Compatible	HV9250-C0
ILT2S-C	Compatible	CBR2S-M
ILT2S-M	Compatible	CBR2S-M
ILT2S-M0	Compatible	ILT3S-M0
ILT4LH-TL	Compatible	CBR4LH-TL
ILT4LH-TL0	Complex	IT9100-C0
ILT4S-C0	No Replacement	NO-REPLACEMENT
ILT4S-M	Complex	CBR4S-M
ILT6LH-C0	Complex	CBR6LH-C0
K-205	No Replacement	NO-REPLACEMENT
KB-550	No Replacement	NO-REPLACEMENT
KB-551	No Replacement	NO-REPLACEMENT
KP-506A	No Replacement	NO-REPLACEMENT
KP-506A-0	No Replacement	NO-REPLACEMENT
PLB2S-M30	Compatible	PLB3S-M30
PLB4S-C	Compatible	PLB4S-M
PLC2H-S25-TL	Direct	PLC2H-S25-L
PLDC1.5EH-L350	Direct	PLDC1.5EH-C350
PLF1MA-M3	Direct	PLF1MA-C3
PLF1M-C0	Direct	PLF1M-M0
PLF1M-M6	Compatible	PLM1M-M6
PLM2M-M6	No Replacement	NO-REPLACEMENT
PLM4S-D2	No Replacement	NO-REPLACEMENT
PLT1.5I-M20	Compatible	PLT1.5I-M0
PLT1.5I-MP	Direct	PLT1.5I-M
PLT1.5M-M20	Compatible	PLT1.5M-M0
PLT1M-M20	Compatible	PLT1M-M0
PLT1M-MP0	Direct	PLT1M-M0
PLT200B-D	Direct	PLT200B
PLT2H-TL2	Compatible	PLT4H-TL2
PLT2H-TL6	Compatible	PLT4H-TL6
PLT2M-M20	Compatible	PLT2M-M0
PLT2M-M300	Complex	PLT2I-M300
PLT2S-M20	Compatible	PLT2S-M0
PLT3S-C100	Direct	PLT3S-M100
PLT3S-C20	Compatible	PLT3S-C0

































# Replacement Type Definition

---

DIRECT  
REPLACEMENT

Exact same part in a different part number  
has any other update that does not affect the  
product itself

COMPATIBLE

The replacement part is different but  
allows it to be used for some applications  
it is not the same part. The difference could be  
in color, size, material, or performance (e.g.,  
*CAT5 to CAT6*), etc.

COMPLEX

The replacement part(s) are too different to  
assume it can easily replace the original  
part, however Panduit can provide a  
replacement which may be used in some  
applications. Customer Experience  
contacted.

NO REPLACEMENT

NO REPLACEMENT

No replacement product is

---

---

package size, or  
n't change the

nt in a way that  
applications, but  
erence can be  
ormance (like  
s.

o dissimilar to  
e discontinued  
n offer a  
ed in certain  
nce should be

available.