

PRODUCT CHANGE NOTIFICATION

Product Category COPPER - CABLE - 10G 20260319-1

Product Group BULK COPPER CABLE

ISSUE DATE: 19.Mär.26

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Please be advised that these items are being obsolete. We greatly value and thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2026	3	19
Old product discontinuation date*	2026	6	17

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 IPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 CHN-CustomerService@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
PUP6004BL-WLPZ	Complex	PUP6004BL-WZ	PUP6C04BL-WLPZ
PUP6004BU-WLPZ	Complex	PUP6004BU-WZ	PUP6C04BU-WLPZ
PUP6004IG-WLPZ	Complex	PUP6004IG-WZ	PUP6C04IG-WLPZ
PUP6004GR-WLPZ	Complex	PUP6004GR-WZ	PUP6C04GR-WLPZ
PUP6004RD-WLPZ	Complex	PUP6004RD-WZ	PUP6C04RD-WLPZ
PUP6004OR-WLPZ	Complex	PUP6004OR-WZ	PUP6C04OR-WLPZ
PUP6004VL-WLPZ	Complex	PUP6004VL-WZ	PUP6C04VL-WLPZ
PUP6004WH-WLPZ	Complex	PUP6004WH-WZ	PUP6C04WH-WLPZ
PUP6004YL-WLPZ	Complex	PUP6004YL-WZ	PUP6C04YL-WLPZ
PUP6004BL-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004BU-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004IG-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004GR-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004RD-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004OR-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004VL-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004WH-ULPZ	No Replacement	NO-REPLACEMENT	
PUP6004YL-ULPZ	No Replacement	NO-REPLACEMENT	
PUR6C04BL-F	Direct	PUR6C04BL-WZ	
PUR6C04BU-F	Direct	PUR6C04BU-WZ	
PUR6C04IG-F	Direct	PUR6C04IG-WZ	
PUR6C04GR-F	Direct	PUR6C04GR-WZ	
PUR6C04RD-F	Direct	PUR6C04RD-WZ	
PUR6C04OR-F	Direct	PUR6C04OR-WZ	
PUR6C04VL-F	Direct	PUR6C04VL-WZ	
PUR6C04WH-F	Direct	PUR6C04WH-WZ	
PUR6C04YL-F	Direct	PUR6C04YL-WZ	
PUR5525WH-VD/N	No Replacement	NO-REPLACEMENT	
PUD6C2804YL-CEN	No Replacement	NO-REPLACEMENT	
PUD6C2804RD-CEN	No Replacement	NO-REPLACEMENT	
PUL6004IG-FEGLP	Direct	PUL6004IG-FE	
PUL6004WH-FEGLP	Direct	PUL6004WH-FE	
PUL6004BU-FEGLP	Direct	PUL6004BU-FE	
PSL6X04WH-HED/N	Direct	PSL6X04WH-HED	
PSL6X04BU-HED/N	Direct	PSL6X04WH-HED	
PUW6AV04WH-EG	Direct	PUK6AHD04WH-EG	
PUL6004WH-KE	Direct	PUL6004WH-FE	
PUL6004WH-EDY	Direct	PUL6004WH-FE	
PFFL6X04GR-CEDN	Direct	PFFL6X04WH-CED	
PUR6004BUY	Direct	PUR6004BU-FE	
PUR6004BUY	Direct	PUR6004BU-FE	
PUR6004WHY	Direct	PUR6004WH-FE	
PUR6004IGY	Direct	PUR6004IG-FE	
PUY6AV04WH-ED	Direct	PUY6AHD04WH-EG	
PUY6AV04BU-ED	Direct	PUY6AHD04BU-EG	
PUY6AV04IG-ED	Direct	PUY6AHD04IG-EG	

Replacement Type Definition

DIRECT
REPLACEMENT

Exact same part in a different part number
has any other update that does not affect the
product itself

COMPATIBLE

The replacement part is different but
allows it to be used for some applications
it is not the same part. The difference could be
in color, size, material, or performance (e.g.,
CAT5 to CAT6), etc.

COMPLEX

The replacement part(s) are too different to
assume it can easily replace the original
part, however Panduit can provide a
replacement which may be used in some
applications. Customer Experience
contacted.

NO REPLACEMENT

NO REPLACEMENT

No replacement product is

package size, or
n't change the

nt in a way that
applications, but
erence can be
ormance (like
s.

o dissimilar to
e discontinued
n offer a
ed in certain
nce should be

available.