

# PRODUCT CHANGE NOTIFICATION

Product Category COPPER PATCHCORDS 20260427-5

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 27.Apr.26

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Obsolescence of non-standard STP Zone Cord, moved to standard part number. We greatly value and thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2026	4	27
Old product discontinuation date*	2026	10	20

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b> <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	<b>TAIWAN: 0080 165 1487</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b> <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customer-service@panduit.com">MEX-customer-service@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
<b>NORTH AMERICA</b>	<b>USA &amp; CANADA: 1-800-777-3300</b> <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b> <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)





**Product Groups**

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS



































# Replacement Type Definition

---

DIRECT  
REPLACEMENT

Exact same part in a different part number  
has any other update that does not affect the  
product itself

COMPATIBLE

The replacement part is different but  
allows it to be used for some applications  
it is not the same part. The difference is  
in color, size, material, or performance (e.g.,  
*CAT5 to CAT6*), etc.

COMPLEX

The replacement part(s) are too different to  
assume it can easily replace the original  
part, however Panduit can provide a  
replacement which may be used in some  
applications. Customer Experience  
contacted.

NO REPLACEMENT

NO REPLACEMENT

No replacement product is

---

package size, or  
n't change the

nt in a way that  
applications, but  
erence can be  
ormance (like  
s.

o dissimilar to  
e discontinued  
n offer a  
ed in certain  
nce should be

available.