

PRODUCT CHANGE NOTIFICATION

Product Category COMPUTER PRINTABLES 20251205-1

Product Group ID AND SAFETY

ISSUE DATE: 05.Dez.25

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Please be advised that this item is being obsolete. Part number C170X090AST-J will be discontinued. The replacement part number is C170X090APT. We greatly value and thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2025	12	5
Old product discontinuation date*	2026	3	5

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 CHN-CustomerService@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customer-service@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

Replacement Type Definition

DIRECT
REPLACEMENT

Exact same part in a different part number
has any other update that does not affect the
product itself

COMPATIBLE

The replacement part is different but functionally
allows it to be used for some applications
it is not the same part. The difference could be
in color, size, material, or performance (e.g.,
CAT5 to CAT6), etc.

COMPLEX

The replacement part(s) are too different to
assume it can easily replace the original
part, however Panduit can provide a
replacement which may be used in some
applications. Customer Experience
contacted.

NO REPLACEMENT

NO REPLACEMENT

No replacement product is

package size, or
n't change the

nt in a way that
applications, but
erence can be
ormance (like
.

o dissimilar to
e discontinued
n offer a
ed in certain
nce should be

available.