

## Product discontinuation notification (PDN)

<b>Title / short description</b>	Discontinuation of article within the Interface Relay & Contactor product line
<b>Affected article category</b>	Relay modules
<b>Change category</b>	Discontinuation
<b>Change number</b>	IDK260005E01-00
<b>Reason for PCN/PDN Revision</b>	

---

### Purpose/objective of the change

Discontinuation due to streamlining the product portfolio

### Detailed description of the change

This notification informs that selected items within the Interface Relay & Contactor product line will be discontinued. For further questions, please contact Sales department.

### Identifying characteristics

See attached item list

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	2027-04-30
<b>Effective date (EOP)</b>	2026-04-30	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	2026-10-31		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

---

### Attachments

- Material\_list.csv
- PDN-IDK260005E01-00\_EN

### Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
2282088	FLKM-2I/O				
5601974	RMOB-JR-1-120AC-MKDS5				
5520569	UMK 22 REL 24 VAC/21-21				
5601975	RMOB-JR-1-24DC-MKDS5				
2282075	FLKM-I/O				
7001438	RMOB 1-24 JR				
2909744	REL-IR4/120AC/4X21/EX				
2908823	REL-MR-110DC/21HC/EX				
2908824	REL-MR-110DC/21-21/EX				
2906988	REL-MR-12DC/21-21/C1D2				
2903707	REL-PR3- 24AC/3X1				
2908821	REL-MR-12DC/21HC/EX				
1081616	REL-MR- 12DC/1ICT				
2903709	REL-PR3-230AC/3X1				
2909742	REL-IR4/230AC/4X21/EX				
2982168	OPT- 5DC/230AC/ 2				
2908043	RIF-RHS-2				
1188200	RIF-2-RPT-LV-230AC/4X21AU				
2900955	RIF-RH-3				
1577412	RIF-2-RPT-PHS-LDP-24DC/2X21				
2903277	RIF-4-RPT-LV-120AC/3X21				
2903276	RIF-4-RPT-LV-230AC/3X21				
1125943	PLC-RSC-230UC/21HC/SO46				
2909671	PLC-RPT- 12DC/21AU/MS				
2909518	PLC-RSC-12DC/21HC/EX				
1091790	ST - A -SCE INPUT KIT				
1091821	ST - A -SCE OUTPUT PLC KIT				
2311438	PLC-RSC-SWS-U/18-30/21/SO215				
1079402	PLC-RSC-230AC/21HC/SO46/HI				
2910513	PLC-RSC-230UC/21-21AU/MS				
5603263	PLC-OSC-120UC/ 48DC/100/C1D2				
2966443	PLC-RSC-230UC/ 2AU/SEN				
2967455	PLC-OSC- 60DC/ 48DC/100				
2904590	PLC-BPT-125DC/21				
2967303	PLC-RSC- 60DC/21-21AU				
2982799	PLC-BSC- 24UC/ 1/ACT				
2910506	PLC-RSC-230UC/21-21/MS				
5789177	INNGANGSRELÉPAKKE 24VDC 8CH				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
5789151	SAMMENSATT PR1 24VDC				
5789452	INNGANGSRELÉPAKKE 48VDC 8CH				
1196111	BDL ST OT D-FUJ003-110VDCRELAY				
1227711	RELAY - 4PDT 125VDC ECOR SET				
1227710	RELAY - 4PDT 115VAC ECOR SET				
1227713	RELAY - 4PDT 230VAC ECOR SET				
5789216	INNGANGSRELÉPAKKE 230VUC 8CH				
1227708	RELAY - 4PDT 24VDC ECOR SET				
5789193	INNGANGSRELÉPAKKE 120VUC 8CH				
1227709	RELAY - 4PDT 110VDC ECOR SET				

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

2282088;FLKM-2I/O;;;;;27371603;  
5601974;RMOB-JR-1-120AC-MKDS5;;;;;27371603;  
5520569;UMK 22 REL 24 VAC/21-21;;;;;27371601;  
5601975;RMOB-JR-1-24DC-MKDS5;;;;;27371603;  
2282075;FLKM-I/O;;;;;27371601;  
7001438;RMOB 1-24 JR;;;;;27371603;  
2909744;REL-IR4/120AC/4X21/EX;;;;;27371601;  
2908823;REL-MR-110DC/21HC/EX;;;;;27371601;  
2908824;REL-MR-110DC/21-21/EX;;;;;27371601;  
2906988;REL-MR-12DC/21-21/C1D2;;;;;27371601;  
2903707;REL-PR3- 24AC/3X1;;;;;27371601;  
2908821;REL-MR-12DC/21HC/EX;;;;;27371601;  
1081616;REL-MR- 12DC/1ICT;;;;;27371601;  
2903709;REL-PR3-230AC/3X1;;;;;27371601;  
2909742;REL-IR4/230AC/4X21/EX;;;;;27371601;  
2982168;OPT- 5DC/230AC/ 2;;;;;27371604;  
2908043;RIF-RHS-2;;;;;27371692;  
1188200;RIF-2-RPT-LV-230AC/4X21AU;;;;;27371601;  
2900955;RIF-RH-3;;;;;27371692;  
1577412;RIF-2-RPT-PHS-LDP-24DC/2X21;;;;;27371601;  
2903277;RIF-4-RPT-LV-120AC/3X21;;;;;27371601;  
2903276;RIF-4-RPT-LV-230AC/3X21;;;;;27371601;  
1125943;PLC-RSC-230UC/21HC/SO46;;;;;27371601;  
2909671;PLC-RPT- 12DC/21AU/MS;;;;;27371601;  
2909518;PLC-RSC-12DC/21HC/EX;;;;;27371601;  
1091790;ST - A -SCE INPUT KIT;;;;;  
1091821;ST - A -SCE OUTPUT PLC KIT;;;;;  
2311438;PLC-RSC-SWS-U/18-30/21/SO215;;;;;27210120;  
1079402;PLC-RSC-230AC/21HC/SO46/HI;;;;;27371601;  
2910513;PLC-RSC-230UC/21-21AU/MS;;;;;27371601;  
5603263;PLC-OSC-120UC/ 48DC/100/C1D2;;;;;27371604;  
2966443;PLC-RSC-230UC/ 2AU/SEN;;;;;27371601;  
2967455;PLC-OSC- 60DC/ 48DC/100;;;;;27371604;  
2904590;PLC-BPT-125DC/21;;;;;27371603;  
2967303;PLC-RSC- 60DC/21-21AU;;;;;27371601;  
2982799;PLC-BSC- 24UC/ 1/ACT;;;;;27371603;  
2910506;PLC-RSC-230UC/21-21/MS;;;;;27371601;  
5789177;INNGANGSRELÅ%oPAKKE 24VDC 8CH;;;;;  
5789151;SAMMENSATT PR1 24VDC;;;;;  
5789452;INNGANGSRELÅ%oPAKKE 48VDC 8CH;;;;;  
1196111;BDL ST OT D-FUJ003-110VDCRELAY;;;;;  
1227711;RELAY - 4PDT 125VDC ECOR SET;;;;;  
1227710;RELAY - 4PDT 115VAC ECOR SET;;;;;

1227713;RELAY - 4PDT 230VAC ECOR SET;;;;;  
5789216;INNGANGSRELÃ%00PAKKE 230VUC 8CH;;;;;  
1227708;RELAY - 4PDT 24VDC ECOR SET;;;;;  
5789193;INNGANGSRELÃ%00PAKKE 120VUC 8CH;;;;;  
1227709;RELAY - 4PDT 110VDC ECOR SET;;;;;

<b>PCN/PDN Number</b>	<b>Customer Number</b>	<b>Company Name</b>	<b>Street</b>	<b>Postcode/Zip Code</b>
IDK260005E01	401641	TTI, INC.	2441 NORTHEAST PKWY	76106
IDK260005E01	401641	TTI, INC.	2441 NORTHEAST PKWY	76106

<b>City</b>	<b>Phoenix Contact Item-Nr. (changed/discontinued article)</b>
FORT WORTH	2903277
FORT WORTH	2909518

<b>Phoenix Contact Item Designation (changed/discontinued article)</b>	<b>Report Date</b>	<b>Substitute Item</b>
RIF-4-RPT-LV-120AC/3X21	08.06.2026	
PLC-RSC-12DC/21HC/EX	08.06.2026	

## Replacement Product Designation