

PRODUCT CHANGE NOTICE

PCN Number: 2025-CIR-04 Issue Date: August 28, 2025
PCN Type: Product/Process Change
 Discontinued Product

Part Number(s) Affected: 116431-3226 REV J

Description of the Change: ECO-088144 Pin location "z" using grounding clip instead of reflow

Reason for the Change:

Dear Valued Customer,

Due to high rework and scrap rate of the TLA 116431-3226 we are eliminating the solder reflow and using a spring clip to make contact to the ground plane at the "z" pin location. Smiths Interconnect has performed testing to verify that contact resistance meets the 2.5 mOhm MAX Ground Resistance limits of the product's specification.

If you have any questions or concerns, please reach out to Smiths Interconnect Sales.

Thank you,

Effective Date: August 28, 2025

Availability of New Samples: Not Applicable

For more information contact:

Kyle Gobble
Product Line Manager
Defense/Space/Aerospace Connectors

smiths interconnect

kyle.gobble@smithsinterconnect.com

Hello

Please contact all customer regarding PCN.

TTI PART# Affected

SAB 71137-2 REV C

SAB 116431-3226