

JUST A CORRECTION to SCR# it should be 25-08-01

TTI INC Group

Please refer below for SWS Change Notification.

- **Parts # Affected:** SEE BELOW
- **Description:** SEE BELOW
- **General Description:** SEWS is transferring assembly conducted at our subcontractor Genasco to an internal SEWS manufacturing site
- **Reason for Change:** SEWS is transferring the assembly location from an external subcontractor (Genasco) to an internal manufacturing site
- **Date of change proposed:** Dec. 2025

<b>Part number</b>	<b>Part description</b>	<b>Customer</b>
60988684	FO-064A10MA-B	TTI
60988688	FO-064A10FA-B	TTI
60988727	FO-064A6MA-B	TTI
60988731	FO-064A6MB-GR	TTI

*Veronica De Santiago*

Jr. Quality Analyst

Sumitomo Wiring Systems (U.S.A.) Inc.

7500 Viscount Blvd., Ste. 192

El Paso TX 79925

P: (915) 843-3000 ext. 6714

F: (915) 843-3001

[s.veronica@us.sws.co.jp](mailto:s.veronica@us.sws.co.jp)

TTI INC Group:

Please refer below for SWS Change Notification.

- **Parts # Affected:** SEE BELOW
- **Description:** SEE BELOW
- **General Description:** SEWS is transferring assembly conducted at our subcontractor Genasco to an internal SEWS manufacturing site
- **Reason for Change:** SEWS is transferring the assembly location from an external subcontractor (Genasco) to an internal manufacturing site
- **Date of change proposed:** Dec. 2025

Part number	Part description	Customer
60988684	FO-064A10MA-B	TTI
60988688	FO-064A10FA-B	TTI
60988727	FO-064A6MA-B	TTI
60988731	FO-064A6MB-GR	TTI

*Veronica De Santiago*

Jr. Quality Analyst

Sumitomo Wiring Systems (U.S.A.) Inc.

7500 Viscount Blvd., Ste. 192

El Paso TX 79925

P: (915) 843-3000 ext. 6714

F: (915) 843-3001