

SWS China :

Please refer below for SWS Change Notification.

- **Parts # Affected:** 6098-7138
- **Description:** FOSPDJB1F-H-B-1
- **General Description :** The injection molding location and mold will transfer from SEWS SV/FR Manufacturing Locations to Juárez AVE.PARQUE INDUSTRIAL AZTECA 620COLONIA: PARQUE INDUSTRIAL AZTECA SCP 32679. The parts will be molded using previously approved injection mold. The new location currently does not hold an IATF 16949 certificate. However, SEWS is actively working with the auditing agency to organize accreditation once the required 1 year of production has been met.
- **Reason for Change:** The injection molding location and mold will transfer from SEWS SV/FR Manufacturing Locations to Juárez AVE.PARQUE INDUSTRIAL AZTECA 620COLONIA: PARQUE INDUSTRIAL AZTECA SCP 32679. The parts will be molded using previously approved injection mold. The new location currently does not hold an IATF 16949 certificate. However, SEWS is actively working with the auditing agency to organize accreditation once the required 1 year of production has been met.
- **Date of change proposed:** Nov. 2026

Veronica De Santiago

Jr. Quality Analyst

Sumitomo Wiring Systems (U.S.A.) Inc.