

TTI INC team:

Please refer below for SWS Change Notification. Only part number highlighted related to your company

- **Parts # Affected:** see below list for all components affected
- **Description:** see below list for all component affected

**General Description:** Transfer Tool 5504-2 ring seal

**Reason for Change:** Transfer Tool 5504-2 (3-6 - 3-1038 ) for 1.2 2-way ring seal to Jasper from Mexico.

- **Date of change proposed:** August 2026

This is the completed list of components just in the event that you have any future demand

<b>Part Description</b>	<b>Part Number</b>
FOW120A02FA-B	61897456
FOW120A02FB-B	61897457
FOW120A02FA-BWC	61897673
FOW120A02FB-BWC	61897674
FOW120A02FE-B	61897909
FOW120A02FE-BWC	61897910
FOW120A02FA-SL-B	61898460
PROTOTYPE FOW120A02FB-SL-B	61898461

FOW120A02FA-SLC-B	61898465
PROTOTYPE FOW120A02FB-SLC-B	61898466
FOW120A02FA1-B	61898475

<b>Part Description</b>	<b>Part Number</b>
FOW120A03FA-B	61897458
FOW120A03FA-B	61897458N
FOW120A03FB-B	61897459
FOW120A03FB-B	61897459N
FOW120A03FD-2	61897615
FOW120A03FC-B	61897660
FOW120A03FC-B	61897660N
FOW120A03FD-B	61897661

FOW120A03FD-B	61897661N
FOW120A03FA-BWC	61897675
FOW120A03FA-BWC	61897675N
FOW120A03FB-BWC	61897676
FOW120A03FB-BWC	61897676N
FOW120A03FC-BWC	61897677
FOW120A03FD-BWC	61897678
FOW120A03FC-2	61897814
FOW120A03FD-2	61897815
FOW120A03FD-3	61898022
FOW120A03FA-2	61898023
FOW120A03FD-4	61898099
FOW120A03FA-BWC3	61898338
FOW120A03FA-3	61898399

*Veronica De Santiago*