

August 2026

To: Distribution

Please be informed Toshiba has announced discontinuation on the following product(s) in August 2026. Our sales records indicate you have purchased the following product(s) from Toshiba America Electronic Components in the past.

Products

Generic Item No	Last Time Buy Date	Substitution Level	Replacement Supplier Name	Replacement Part #	Reason*	Remarks
TK034Z60Z5,S1F	October 1, 2026	4	Toshiba	TK62N60W5,S1VF	3	Integration of products
TK040Z60Z5,S1F	October 1, 2026	3	Toshiba	TK62N60W5,S1VF	3	Integration of products
TK055Z60Z5,S1F	October 1, 2026	3	Toshiba	TK62N60W5,S1VF	3	Integration of products
TK073A60Z5,S4X	October 1, 2026	2	Toshiba	TK35A65W5,S5X	3	Integration of products
TK073E60Z5,S1X	October 1, 2026	2	Toshiba	TK25E60X5,S1X	3	Integration of products
TK073Z60Z5,S1F	October 1, 2026	3	Toshiba	TK39N60W5,S1VF	3	Integration of products
TK090A60Z5,S4X	October 1, 2026	2	Toshiba	TK25A60X5,S5X	3	Integration of products
TK090E60Z5,S1X	October 1, 2026	2	Toshiba	TK25E60X5,S1X	3	Integration of products
TK090N60Z5,S1F	October 1, 2026	1	Toshiba	TK31N60W5,S1VF	3	Integration of products
TK090U60Z5,RQ	October 1, 2026	4	Toshiba	TK31V60W5,LVQ	3	Integration of products
TK090Z60Z5,S1F	October 1, 2026	3	Toshiba	TK31N60W5,S1VF	3	Integration of products
TK095E65Z5,S1X	October 1, 2026	2	Toshiba	TK25E60X5,S1X	3	Integration of products
TK095V60Z5,LQ	October 1, 2026	1	Toshiba	TK31V60W5,LVQ	3	Integration of products
TK095Z65Z5,S1F	October 1, 2026	3	Toshiba	TK35N65W5,S1F	3	Integration of products
TK115A65Z5,S4X	October 1, 2026	1	Toshiba	TK35A65W5,S5X	3	Integration of products
TK115E65Z5,S1X	October 1, 2026	2	Toshiba	TK25E60X5,S1X	3	Integration of products
TK115N65Z5,S1F	October 1, 2026	2	Toshiba	TK35N65W5,S1F	3	Integration of products
TK115U65Z5,RQ	October 1, 2026	4	Toshiba	TK28V65W5,LQ	3	Integration of products
TK115Z65Z5,S1F	October 1, 2026	4	Toshiba	TK31N60W5,S1VF	3	Integration of products

TK125A60Z5,S4X	October 1, 2026	2	Toshiba	TK25A60X5,S5X	3	Integration of products
TK125E60Z5,S1X	October 1, 2026	2	Toshiba	TK25E60X5,S1X	3	Integration of products
TK125U60Z5,RQ	October 1, 2026	3	Toshiba	TK31V60W5,LVQ	3	Integration of products
TK130V60Z5,LQ	October 1, 2026	2	Toshiba	TK25V60X5,LQ	3	Integration of products
TK155A60Z5,S4X	October 1, 2026	1	Toshiba	TK25A60X5,S5X	3	Integration of products
TK155E60Z5,S1X	October 1, 2026	1	Toshiba	TK25E60X5,S1X	3	Integration of products
TK155U60Z5,RQ	October 1, 2026	3	Toshiba	TK25V60X5,LQ	3	Integration of products
TK165A65Z5,S4X	October 1, 2026	1	Toshiba	TK22A65X5,S5X	3	Integration of products
TK165E65Z5,S1X	October 1, 2026	2	Toshiba	TK20E60W5,S1VX	3	Integration of products
TK165U65Z5,RQ	October 1, 2026	3	Toshiba	TK22V65X5,LQ	3	Integration of products
TK165V60Z5,LQ	October 1, 2026	1	Toshiba	TK25V60X5,LQ	3	Integration of products
TK165V65Z5,LQ	October 1, 2026	1	Toshiba	TK22V65X5,LQ	3	Integration of products
TK200A65Z5,S4X	October 1, 2026	2	Toshiba	TK17A65W5,S5X	3	Integration of products
TK200E65Z5,S1X	October 1, 2026	2	Toshiba	TK20E60W5,S1VX	3	Integration of products
TK200U65Z5,RQ	October 1, 2026	4	Toshiba	TK16G60W5,RVQ	3	Integration of products
TK200V65Z5,LQ	October 1, 2026	1	Toshiba	TK22V65X5,LQ	3	Integration of products

Last Time Buy (LTB) Option

Toshiba will support last time buy (LTB) orders received on or before the dates listed above (LTB Date). Last time buy orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unforeseen circumstances might prevent Toshiba to support partially or fully on LTB orders. If such event occurs, we will notify you of our best support plan as soon as possible. Thank you for your understanding. Should you have any questions, please contact your sales representative.

Best Regards,

Semiconductor Business Unit
Toshiba America Electronics Components, Inc.

=====

Substitution Level**

- 0 = No Replacement P/N
- 1 =Package and characteristics are mostly same or better, not necessary to change other circuit to replace.
- 2 = Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.
- 3 = Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.
- 4 = Other reason