

Standardrized Information For Process/Product Change Notification (PCN)

1.PCN basic data			
1.1 Company		Pulse (Suzhou) Wireless Products Co.,Ltd.	
1.2 PCN No.	NO.20260602		
1.3 Tittle of PCN	Production site change		
1.4 Product Category	Filter series		
1.5 Issue date	2026.6.11		
1.6 Others	NA		
2.PCN Team			
2.1 Contact supplier			
2.1.1 Name	Libby.Hsu		
2.1.2 Phone	841-3589		
2.1.3 Mail	Libby.Hsu@yageo.com		
2.2 Team Supplier (Optional)			
2.2.1 Name (Optional)	2.2.2 Phone	2.2.3 Mail	
Lemon He		Lemon.He@yageo.com	
Tomas Wu	+86 13584849320	Tomas.Wu@yageo.com	
3.Description			
		Old	New
Description #1	Production site	Suzhou (LTCC_SZ2 factory) LTCC苏州工厂	TaiWan (LTCC_PZ1 factory) LTCC台湾平镇工厂
Description #2	Man	Suzhou Local Employee	Taiwan Local Employee
Description #3	Machine	YAGEO Equipments	Chilisin Equipments
Description #4	Material	No change	No change
Description #5	Method	No change	No change
4.Reason/Motivation			
4.1 Motivation	Resource integration and optimization of the product manufacturing and efficiency. All the Filter series in SZ2 will be transferred to PZ1 for production.		
5.Making of parts /Traceability			
5.1 Description	Reel label of batch number for traceability.		

6. Timing /Schedule			
6.1 Intended start of delivery	2026.10.1		
Remark	Due to affect many part numbers and Pulse will move forward based on customers' approval and suggestions.		
7.Qualification/Verification			
7.1 Description	Each part shall pass reliability test before transferring. Reference standard:IEC 60384-21/22/NASI-EIA-469-D		
8. Affected parts			
Pulse Part number	Pulse Part number	Pulse Part number	Pulse Part number
BPF1005LM03R2400A	DPX1608LL80R2455A	LPF1608LL57RWHEXA	TPX2520LKTBR0914A
BPF1608LM06R5000A	DPX1608LL85R2455A	LPF1608LL53R2400A	TPX2520LKTCR0913L
BPF1608LM06R5000C	DPX1608LL83R2455A	LPF1608LL52R2500A	TPX2520LKTDRWH34L
BPF1608LM09R5000A	DPX1608LL76R1925A	LPF1608LL55R0709A	DPX2012LKHHR1931L
BPF1608LM10R5000A	DPX1608LL87R1524A	BLN1608LL01R5000A	
BPF1608LM02R2400A	DPX1608LL88R1524A	BLN1608LL01R2400A	
BPF1608LM03R2400A	DPX2012LL75R2455A	BLN0605LM09R0780A	
BPF1608LM02R2400C	DPX2012LL75R2455C	CPL0605AT13R2455A	
BPF1608LM02R1880A	DPX2012LL76R2455A	CPL0605LL15R2460A	
BPF2012LL01R5000A	DPX2012LL74R0917A	CPL1608LL12RWHEXA	
DPX1608LL60R2455A	DPX2012LL75R0917A	TPX2012LL94R1525A	
DPX1608LL66R2455A	LPF1005LL50R2400A	TPX2012LL95R1525A	
DPX1608LL67R2455A	LPF1005LM63R2400A	TPX2520L09AR0924L	
DPX1608LL65R2455A	LPF1005LM55R2400A	BLF2012LL98R2400A	
DPX1608LL60R2460A	LPF1005LM53R1880A	BPF2012LKBMR6580A	
9.Customer feedback/Comment			
9.1 Customer feedback			

Form revision reference ZVEI 5.0