







Product Change Notification

PCN Date:	Jul 13, 2026	
Supplier Name:	Pulse Electronics	
Pulse PCN No.	PCN-100000868	
Description of Change	For the header 043-2508.001, 4 pins are too close stand to wrap, it affect operation of wrapping wire lead to terminal and solder quality, this change is to cut some side wall(refer to the summary of changes).	
Reason for Change	header structure optimization (the stand-off structure upgrade) to improve processability.	
Summary of Changes	Old	New
	  	  
Traceability guidelines	By date code, traceability record can be provided upon request	

Qualification Data	Pulse arranged the AEC-Q200 full qualification on the similar to part HM2103NL, please refer to attached qualification report.  HM2103NL Qualification Test		
Customer	Customer Part Number	Pulse art Number	PCN Effectivity Date
	 Part number list_PCN-B.xlsx		Oct 12, 2026

Customer: Generic

Phone: (86)-0816-7077888-2901

Originator: XL Guo

E-mail: xl.guo@yageo.com

Statement: Dear customer, please response this PCN requirement. If you have any special requirements, please let us know. Lack of response after 30 days will be considered acceptable of change.

Affected Part Numbers for PCN-100000868
23Z105SMNL
23Z106SMNL-T
23Z356SMQNLT
23Z467SMNL
23Z467SMNLT
23Z91SMNL-T
HX1324NL
HX6523NLT
ST7010QNL
ST7010QNLT
ST7033QNL
TX1520NLT