



Product Change Notification

Current Date: 08-Apr-2026

TE Connectivity

Product Change Notification: P-26-030036

PCN Date: 30-MAR-26

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Multiple Part Numbers

Description of Changes
Changing alloy from C511 to C425 for Generation - Y T2 tin plated female terminals. New PN's have been generated and will be released for traceability. North American supply will be transitioned to the New PN's. There will be no change to the Form, Fit, or Function of the finished product.

Reason for Changes:
Product improvement. There will be a change to the base metal used in the production of these parts as an effort toward Tariff Mitigation. C425 is available from North American Sources and is not subject to the same Tariff impacts as C511.

| | |
|---|---|
| Estimated Dates: | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 23-JUN-2026 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-1456574-1 | NO | | | | | |
| 1-1456574-2 | NO | | | | | |
| 1-1456574-3 | NO | | | | | |
| 1-1456574-4 | NO | | | | | |
| 1-1456574-5 | NO | | | | | |
| 1-1456574-6 | NO | | | | | |
| 1-1456574-7 | NO | | | | | |
| 1-1456574-8 | NO | | | | | |
| 1-1456841-1 | NO | | | | | |
| 1-1456841-2 | NO | | | | | |
| 1-1456841-3 | NO | | | | | |
| 1-1456841-4 | NO | | | | | |
| 1-1456841-5 | NO | | | | | |
| 1-1456841-6 | NO | | | | | |
| 1-1456841-7 | NO | | | | | |
| 1-1456841-8 | NO | | | | | |
| 1-1924955-1 | NO | | | | | |
| 1-1924955-2 | NO | | | | | |
| 1-1924955-3 | NO | | | | | |
| 1-1924955-4 | NO | | | | | |
| 1-1924955-6 | NO | | | | | |
| 1-1924955-7 | NO | | | | | |
| 1-1924955-8 | NO | | | | | |
| 1-2035334-3 | NO | | | | | |
| 1-2035334-4 | NO | | | | | |
| 1-2035334-6 | NO | | | | | |
| 1-2035334-8 | NO | | | | | |
| 1924955-1 | NO | | | | | |
| 1924955-2 | NO | | | | | |
| 1924955-3 | NO | | | | | |
| 1924955-4 | NO | | | | | |
| 1924955-5 | NO | | | | | |
| 1924955-6 | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1924955-7 | NO | | | | | |
| 1924955-8 | NO | | | | | |
| 2035334-1 | NO | | | | | |
| 2035334-2 | NO | | | | | |
| 2035334-3 | NO | | | | | |
| 2035334-4 | NO | | | | | |
| 2035334-5 | NO | | | | | |
| 2035334-6 | NO | | | | | |
| 2035334-7 | NO | | | | | |
| 2035334-8 | NO | | | | | |