



Product Change Notification

Current Date: 11-Jun-2026

TE Connectivity

Product Change Notification: PCN-26-281852

PCN Date: 09-JUN-26

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
 DEUTSCH Stamped and Formed Size 16,20 Pins and Sockets Manufacturing Location Change

General Description of Changes
 The Industrial and Commercial Transportation business unit of TE Connectivity is transferring the following part number(s) from a TE warehouse located in NC, USA to TE approved supplier located in PA, USA. The transfer project will be phased in gradually over the next 6-18 months. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days (or per contract with TE) of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. This PCN is a continuance of PCN-24-219068.

Reason for Changes:
 Dear Customer, we hereby inform you of the manufacturing location change because when the supplier in RI, USA closed, all tools were stored in TE warehouse since a new supplier had not been defined. We apologize any inconvenience this has caused. This transfer project will be phased in gradually over the next 6-18 months. **IMPORTANT:** Product from the new supplier are the same as the previous supplier and does not impact product performance. Shipments from previous and new supplier may be mixed.

PCN Attributes:	
Product Category:	Kind of Change:
Terminals	Location Change
Change Feature:	Potential Customer Impact:
No Feature Change	Additional Location
Remarks:	
Future supplier is located in PA, USA	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	17-OCT-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	17-APR-2028
Effectivity Date:	Date of First Samples:
17-OCT-2026	31-JUL-2026

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1060-14-0122	NO			"ZPF000000000131897", "1060-14-0122-LS", "1060-14-0122-L"			
1060-16-0122	NO			"ZPF000000000131901", "1060-16-0122-AS", "1060-16-0122-LD", "1060-16-0122-LS", "1060-16-0122-SC", "1060-16-0122-E", "1060-16-0122-L", "1060-16-0122-S"			
1060-16-0144	NO			"ZPF000000000131903", "1060-16-0144-LS", "1060-16-0144-L"			
1060-16-0177	NO						
1060-16-0622	NO			"ZPF000000000131905", "1060-16-0622-LD", "1060-16-0622-LS", "1060-16-0622-SC", "1060-16-0622SAMPLE", "ZPF000000000141127", "1060-16-0622-L", "1060-16-0622-S", "61.310.00", "5000636"			
1060-16-0644	NO			"ZPF000000000131907", "1060-16-0644SAMPLE"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1060-16-0677	NO						
1060-16-0988	NO			"ZPF000000000131910", "1060-16-0988-LD", "1060-16-0988-LS", "1060-16-0988-MS", "1060-16-0988-L", "1060-16-0988-M"			
1060-16-1222	NO			"ZPF000000000131912", "2113497-1", "61.309.00"			
1060-20-0122	NO			"ZPF000000000131914", "1060-20-0122-AS", "1060-20-0122-LS", "1060-20-0122-SC", "1060-20-0122-E", "1060-20-0122-S", "1060-20-0122-L", "1572032-1"			
1060-20-0144	NO			"ZPF000000000131916", "1060-20-0144-LD", "1060-20-0144-LS", "1060-20-0144-MS", "1060-20-0144-M", "1060-20-0144-L", "8-1899794-0"			
1060-20-0222	NO			"ZPF000000000131918"			
1060-20-0244	NO			"ZPF000000000131920"			
1060-20-0277	NO						
1060-20-0622	NO			"1060-20-0622SAMPLE", "2113498-1"			
1062-14-0122	NO			"ZPF000000000131928", "1062-14-0122-LD", "1062-14-0122-LS", "1062-14-0122-E", "1062-14-0122-L"			
1062-14-0144	NO			"ZPF000000000131930"			
1062-16-0122	NO			"ZPF000000000131932", "1062-16-0122-AS", "1062-16-0122-LD", "1062-16-0122-LS", "1062-16-0122-SC", "1062-16-0122-E", "1062-16-0122-L", "1062-16-0122-S"			
1062-16-0144	NO			"ZPF000000000131934", "1062-16-0144-LS", "1062-16-0144-SC", "1062-16-0144-S", "1062-16-0144-L"			
1062-16-0177	NO						
1062-16-0622	NO			"ZPF000000000131936", "1062-16-0622SAMPLE", "ZPF000000000141109", "1062-16-0622-MS", "1062-16-0622-M", "820P-36949"			
1062-16-0644	NO			"ZPF000000000131938", "1062-16-0644SAMPLE"			
1062-16-0677	NO						
1062-16-0722	NO			"ZPF000000000131940", "1062-16-0722SAMPLE"			
1062-16-0988	NO			"ZPF000000000131942", "1062-16-0988-LD", "1062-16-0988-LS", "1062-16-0988-MS", "1062-16-0988-L", "1062-16-0988-M"			
1062-16-1222	NO			"ZPF000000000131944", "1062-16-1222SAMPLE", "1949119-3"			
1062-20-0122	NO			"ZPF000000000131949", "1062-20-0122-AS", "1062-20-0122-LS", "1062-20-0122-MS", "1062-20-0122SAMPLE", "1062-20-0122-SC", "1062-20-0122-E", "1062-20-0122-S", "1062-20-0122-L", "1062-20-0122-M"			
1062-20-0144	NO			"ZPF000000000131951", "1062-20-0144-AS", "1062-20-0144-LD", "1062-20-0144-LS", "1062-20-0144-MS", "\$1062-20-0144", "1062-20-0144-L", "1062-20-0144-M", "7-1899794-7"			
1062-20-0177	NO						
1062-20-0222	NO			"ZPF000000000131953", "1062-20-0222SAMPLE", "1062-20-0222-SC", "1062-20-0222-S"			
1062-20-0244	NO			"ZPF000000000131955"			
1062-20-0277	NO						
1062-20-0622	NO						

